

AD-A155 743

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
CLAM LAKE DAM (MA 010...101) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV FEB 80


1/2

UNCLASSIFIED

F/G 13/13

NI





"MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A155 743

CONNECTICUT RIVER BASIN  
SANDSFIELD, MASSACHUSETTS

CLAM LAKE DAM  
MA 01052

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



DTIC  
S<sup>E</sup> JUN 27 1985  
G

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

FEBRUARY 1980

**DISTRIBUTION STATEMENT A**  
Approved for public release  
Distribution Unlimited

85 06 6 145

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

**UNCLASSIFIED**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER <b>MA 01052</b>	2. GOVT ACCESSION NO. <b>AD-A155743</b>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) <b>Clam Lake Dam</b>  <b>NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS</b>		5. TYPE OF REPORT & PERIOD COVERED <b>INSPECTION REPORT</b>
7. AUTHOR(s) <b>U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION</b>		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS <b>DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254</b>		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE <b>February 1980</b>
		13. NUMBER OF PAGES <b>95</b>
		15. SECURITY CLASS. (of this report) <b>UNCLASSIFIED</b>
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  <b>APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED</b>		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES <b>Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.</b>		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) <b>DAMS, INSPECTION, DAM SAFETY,  Connecticut River Basin Sandisfield, Massachusetts Clam River</b>		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  <b>The dam is an earthfill embankment about 950 ft. long and 94 ft. high. The dam was found to be in poor condition. It is intermediate in size with a hazard potential of high A great deal of maintenance and major remedial work as listed in section 7 must be undertaken by the owner.</b>		



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02254

REPLY TO  
ATTENTION OF:

NEDED

JAN 06 1981

Honorable Edward J. King  
Governor of the Commonwealth of  
Massachusetts  
State House  
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Clam Lake (MA-01052) Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam.

The brief assessment included at the beginning of the report contains a discussion of two serious deficiencies relating to the condition of the principal spillway and to the emergency spillway side slopes. Because of this the dam has been rated in poor condition. Both the Commonwealth of Massachusetts and the U.S. Department of Agriculture, Soil Conservation Service are aware of these problems and design of corrective modifications is currently underway.

I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

WILLIAM E. HODGSON, JR.  
Colonel, Corps of Engineers  
Acting Division Engineer

Incl  
As stated



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02254

REPLY TO  
ATTENTION OF:

NEDED

JAN 06 1981

Honorable Edward J. King  
Governor of the Commonwealth of  
Massachusetts  
State House  
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Clam Lake (MA-01052) Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam.

The brief assessment included at the beginning of the report contains a discussion of two serious deficiencies relating to the condition of the principal spillway and to the emergency spillway side slopes. Because of this the dam has been rated in poor condition. Both the Commonwealth of Massachusetts and the U.S. Department of Agriculture, Soil Conservation Service are aware of these problems and design of corrective modifications is currently underway.

I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

WILLIAM E. HODGSON, JR.  
Colonel, Corps of Engineers  
Acting Division Engineer

Incl  
As stated

CLAM LAKE DAM

MA 01052

CONNECTICUT RIVER BASIN  
SANDISFIELD, MASSACHUSETTS

Accession For		
NTIS GRA&I <input checked="" type="checkbox"/>		
DTIC TAB <input checked="" type="checkbox"/>		
Unannounced <input type="checkbox"/>		
Justification		
By		
Distribution/		
Availability Codes		
Dist	Avail and/or Special	
A/		23

*mmw*

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT

Identification No.: MA 01052  
Mass. D.P.W. No: 1-2-260-11  
Name of Dam: Clam Lake  
Town: Sandisfield  
County and State: Berkshire County, Massachusetts  
Stream: Clam River  
Date of Inspection: November 1, 1979 and November 7, 1979

BRIEF ASSESSMENT

The Clam Lake Dam, No. MA 01052, is located on the Clam River, a tributary of the West Branch of the Farmington River, in the Town of Sandisfield, Massachusetts. The dam site is approximately three miles upstream of the Village of West New Boston and is located off of Montville-Beech Plain Road. The dam is a multiple purpose recreation and flood protection facility which is owned by the Massachusetts Division of Water Resources. It was designed by the U.S. Department of Agriculture, Soil Conservation Service and construction was completed in 1977.

The dam is an earthfill embankment about 950 feet in length, and 94 feet in height, has a reinforced concrete principal spillway which is designed to maintain the recreation pool level and control the release of stored floodwater, and a 385 foot wide earth fill and earth excavated emergency spillway channel around the left abutment. No water is presently impounded by the dam because of serious deficiencies related to the soundness of the principal spillway structure and emergency spillway side slopes. Both of these deficiencies were noted by SCS prior to the completion of construction.


The dam and appurtenances were found to be in POOR condition. The visual inspection indicated that the emergency spillway side slopes are unstable, the downstream emergency spillway slopes have eroded, the principal spillway structure is failing at the transition, the pond drain intake structure is defective and the upstream and downstream slopes of the dam show erosion. The defective pond drain structure, erosion of the dam embankment and the erosion of the emergency spillway channel warrant additional investigations. The side slope instability and failure of the principal spillway has been investigated thoroughly by the Soil Conservation Service. The summary, conclusions, and recommendations of the SCS investigation reports are reproduced herein in Appendix B.

The test flood for this dam has been determined to be the Probable Maximum Flood (PMF), based on a classification of INTERMEDIATE size and HIGH hazard. The drainage area is 10.8 square miles and the test flood is 21,060 CFS. Routing the test flood through the reservoir, with the initial pool level at the normal recreation stage, resulted in test flood outflow of 14,960 CFS which does not exceed the capacity of the spillways. Total discharge capacity with water at top of dam is 16,150 CFS.

Failure of the dam will pose a serious threat to approximately 25 houses and buildings, one major road bridge, one secondary road bridge, 9000 feet of major road, and a cemetery in addition to damage caused by the PMF flow through the spillway and tributary drainage areas.

A great deal of maintenance and major remedial work as listed in Section 7 must be undertaken by the Owner. Listed items include: repair of riser structure, develop access to top of dam, determine cause of and correct slope failures and causes of erosion of slopes.

The recommendations for additional investigations and recommended remedial measures as listed in Section 7 should be implemented within one year of receipt of this report by the Owner.



*John W. Powers*  
*Sanitary*

John W. Powers  
Massachusetts Registration 23106

This Phase I Inspection Report on Clam Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, MEMBER  
Water Control Branch  
Engineering Division

Aramast Mantesian

ARAMAST MANTESIAN, CHAIRMAN  
Geotechnical Engineering Branch  
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD SIGNATURE SHEET	
PREFACE	i
TABLE OF CONTENTS	ii-iv
OVERVIEW PHOTO	v
LOCUS PLAN 1	vi
LOCUS PLAN 2	vii

### REPORT

1. PROJECT INFORMATION	
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
c. Scope	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-5
d. Hazard Classification	1-5
e. Ownership	1-5
f. Operator	1-5
g. Purpose of Dam	1-6
h. Design and Construction History	1-6
i. Normal Operational Procedure	1-6
1.3 Pertinent Data	1-6
2. ENGINEERING DATA	2-1
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operation Data	2-1
2.4 Evaluation of Data	2-1

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-3
d. Reservoir Area	3-4
e. Downstream Channel	3-4
3.2 Evaluation	3-4
4. OPERATIONAL AND MAINTENANCE PROCEDURES	4-1
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	5-1
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-2
5.5 Dam Failure Analysis	5-2
6. EVALUATION OF STRUCTURAL STABILITY	6-1
6.1 Visual Observation	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1

<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
7.4 Alternatives	7-2

#### APPENDICES

APPENDIX A - INSPECTION CHECKLIST

APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS


APPENDIX D - HYDROLOGIC AND HYDRAULIC  
COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE  
NATIONAL INVENTORY OF DAMS

REPRODUCED AT GOVERNMENT EXPENSE







0 5 10  
SCALE IN MILES



TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS


## LOCUS PLAN I

CLAM LAKE DAM (MA 01052)  
BERKSHIRE COUNTY

SANDISFIELD  
MASSACHUSETTS

SCALE: AS NOTED

DATE: FEBRUARY 1980



- SCALE -  
1000' 0 1000' 2000' 3000'

FROM: U.S.G.S. MONTEREY, OTIS,  
SOUTH SANDISFIELD, AND  
TOLLAND CENTER, MASS.  
QUADRANGLE MAPS



TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

## LOCUS PLAN 2

CLAM LAKE DAM (MA 01052)  
BERKSHIRE COUNTY

SANDISFIELD  
MASSACHUSETTS

SCALE: AS NOTED

DATE: FEBRUARY 1980

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT

CLAM LAKE DAM

SECTION 1

PROJECT INFORMATION

1.1 General

(a) Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Tighe & Bond/SCI has been retained by the New England Division to inspect and report on selected dams in Massachusetts. Authorization and notice to proceed were issued to Tighe & Bond/SCI under a letter of October 24, 1979 from Colonel William E. Hodgson, Jr., Corps of Engineers. Contract No. DACW-33-80-C-0005 has been assigned by the Corps of Engineers for this work.

(b) Purpose

- 1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.
- 2) Encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams.
- 3) Update, verify, and complete the National Inventory of Dams.

(c) Scope

The program provides for the inspection of non-federal dams in the high hazard potential category based upon location of the dams, and those dams in the significant hazard potential category believed to represent an immediate danger based on condition of the dams.

1.2 Description of Project

(a) Location

The Clam Lake Dam is located within the Town of Sandisfield, Massachusetts, on the Clam River about three miles upstream from West New Boston. The Clam River is a tributary of the West

Branch of the Farmington River. The dam is accessible by way of Montville-Beech Plain Road from West New Boston.

The dam is located on the U.S.G.S. Otis, Mass., quadrangle at longitude N 42°-08'-18" and latitude W 73°-06'-24". Refer to the location plan, and Appendix B for additional information.

(b) Description of Dam & Appurtenances

The dam consists of an earthfill embankment, a principal spillway consisting of a reinforced concrete drop inlet structure having a two stage riser section, a 60-inch diameter reinforced concrete outlet conduit, and a plunge pool excavated in ledge at the conduit outlet. An emergency spillway is located on the left abutment and consists of a grass covered, partly earth excavated through natural ground and partly earth filled channel. The crest of the spillway is provided with a 12" wide concrete weir.

1) Embankment (See pages B-5, B-6, B-7, B-9 and B-10)

The following information has been taken from the Construction Drawings dated 1972.

The dam embankment is approximately 950 feet long and has a maximum structural height of 94 feet. The upstream slope is 3 horizontal on 1 vertical and has a 20 foot terrace (horizontal section) at elev. 1145.0, which is the approximate level of the normal recreation pool. The downstream slope is 2.5 horizontal on 1 vertical, and the width of the top of dam is 26 feet. The upper portion of the upstream slope surface is covered with dumped riprap from 5 feet below the normal pool elevation to the top of the dam.

The embankment material is sand, silty with gravel. A 10' wide section of drain fill beginning 41' from the dam centerline, extends from about elevation 1156.0 on a slope of 1.5 horizontal to 1 vertical to the foundation, which is bedrock and glacial till. The drain fill extends the full length of the dam and is provided with a foundation drain conduit which outlets at each side of the 60" conduit at the endwall. A cutoff trench consisting of the sand, silty with gravel is located beneath the embankment along the centerline of the dam.

The downstream embankment, and upper portion of the upstream embankment are covered with riprap.

2) Principal Spillway (See pages B-9, B-10, and B-12)

The principal spillway consists of a reinforced concrete drop inlet structure with a sluice gate controlled inlet pipe at invert elevation 1100.00 for the pond drain, a sluice gate controlled orifice inlet at invert elevation 1141.3 for the low level bottom release, an uncontrolled orifice at elevation

1143.3 for the high level bottom release, uncontrol weirs at elevation 1144.3 for the normal pool level and uncontrolled weirs at elevation 1153.0 for the high stage outlet.

The riser structure is 59½ feet high from the base of the foundation to the top of the structure. The inside dimensions are 5 feet x 15 feet.

The structure is provided with a gate well having dimensions of 2.5 feet x 5.5 feet which extends from elevation 1097.0 to 1143.3. Provision for stop logs exist from 1143.3 to 1144.3. The purpose of the gate well is to provide facilities for gating the pond drain and to provide a bottom release of water when the impoundment level is below the normal pool elevation of 1144.3.

The walls of the riser normal to the centerline of the dam vary in thickness from 36" beginning at the base to a height of 9 feet and decrease in thickness by 3" every 5 feet to a height of 44 feet above the base. From 44 feet above the base to the crest of the high stage weir the walls are 12" thick. The walls of the riser parallel to the centerline of the dam, including the gate well walls are 12" thick from top to bottom. (See Sheet B-12)

The top of the riser is provided with flared out walls, 45° to the horizontal, parallel to the centerline of the dam, from 45.5 feet above the base to 55.5 feet. At 55.5 feet above the base to 59.5 feet the walls are vertical.

Trash racks of galvanized steel angles are provided between the flared walls to prevent the clogging of the high stage weir. Also, a galvanized steel angle trash rack is formed over the top of the gate well to prevent debris from clogging that opening.

The bottom of the riser is formed to make a transition from the rectangular vertical section to a 60" diameter outlet pipe.

The inside bottom elevation of the riser structure is 1097.0. The low level and high level bottom release orifices are located on the upstream side of the riser inside the gate well. The low level orifice is 17" x 12" and the high level orifice is 4 feet x 12 inches. These orifices are at elevations 1141.3 and 1143.3 respectively. The normal pool level orifice is located on the side faces of the riser and measures 53 inches wide x 12 inches high with an invert elevation of 1144.3. The high level overflow weirs are formed by the tops of the riser section walls and have a total length of 30 feet with a crest elevation of 1153.0. The two flared walls of the riser act as anti-vortex walls perpendicular to and across the top of the weir walls with a solid concrete platform bridging the two walls and acting as the support for the sluice gate operator stands.

The sluice gate which controls the 48 inch diameter pond drain is a 48 inch square gate mounted on a 12 inch deep wall thimble. The gate is operated by a rising stem, crank operated, gear assisted floor stand located on the top of the riser structure.

The sluice gate which controls the low stage bottom release is a 12" x 17" gate which opens downward. The gate is operated by a rising stem, hand wheel operated, floor stand located on top of the riser.

The pond drain pipe consists of about 120 feet of 48 inch diameter reinforced concrete water pipe conduit with a concrete bedding and reinforced concrete inlet structure. This conduit enters the riser structure through the upstream side of the gate well on the riser.

The principal spillway structure has a 60 inch diameter outlet conduit which discharges to a plunge pool located at the downstream toe of the dam. The 60 inch diameter conduit consists of reinforced concrete water pipe with a continuous concrete bedding and nine reinforced concrete anti-seep collars. The pipe has an inlet invert elevation of 1097.0 and an outlet invert elevation of 1088.0 with an overall length of 312 feet.

The plunge pool is constructed from excavated ledge and is approximately 50 feet long x 12 feet wide with a toe wall spanning across the downstream end of the flow path to dissipate the energy from the high velocity outlet flow from the 60 inch diameter conduit during flood flows.

### 3) Emergency Spillway (See pages B-6 and B-11)

The emergency spillway consists of a grass covered earth fill and earth excavated channel on the left abutment of the dam. The spillway channel has a control section approximately at elevation 1172.0 which is 385 feet wide and 50 feet long. A 12 inch wide buried concrete curb weir is located at the downstream end of the flat crest of the spillway. The spillway approach channel, along the centerline, slopes upward at 4% from the impoundment area. The discharge channel slopes downward at 3% to the edge of a steeper discharge slope. The spillway discharges down a 2 horizontal to 1 vertical slope at the toe of which is original ground downstream of the dam. The side slopes of the spillway channel are at 2 horizontal to 1 vertical. The maximum depth of excavation is just upstream of the control section and is about 32 feet. The control section is approximately 6 feet below the top of the dam.

The maximum depth of fill in the discharge channel of the emergency spillway is about 48 feet.

The toe of the emergency spillway left side slope is provided with a drain composed of sand and gravel with a 6" drainpipe discharging at both ends of the spillway. The drain is not continuous through the crest of the spillway being interrupted by the emergency spillway weir control section.

4) Foundation and Embankment Drainage (See page B- )

A trench drain of clean sand and gravel extends into the foundation at the toe of the drainfill. The trench drain extends from the principal spillway conduit left about 490 ft. and right about 240 ft., with a 4 inch diameter A.C. perforated drain pipe extending 425 ft. left and 175 feet right of the principal spillway. Both 4 inch diameter trench drain outlet pipes discharge into the plunge pool basin through the end wall at the outlet of the principal spillway. Also, a blanket drain is provided at the valley floor section about 140' wide and extending horizontally from the toe of the drain fill to the toe of the dam.

(c) Size Classification

The dam's maximum impoundment (computed to the top of the dam) of about 3800 acre-feet and structural height of 94 feet place it in the INTERMEDIATE size classification.

(d) Hazard Classification

The hazard potential classification for this dam is HIGH because of the significant potential for loss of human life and property which may occur in the event of a failure. There is a high potential for damaging about 25 houses with attendant probable loss of more than a few lives, as well as one major bridge, one secondary bridge, 9000 feet of major road and a cemetery.

(e) Ownership

The Clam Lake dam is owned by the Commonwealth of Massachusetts, Division of Water Resources. The address is as follows:

Commonwealth of Massachusetts  
Department of Environmental Management  
Division of Water Resources  
100 Cambridge Street  
Boston, Massachusetts 02202  
Telephone No.: 617-727-3170

(f) Operator

The operation of the Clam Lake Dam is the responsibility of the Commonwealth of Massachusetts, Department of Environmental Management, Division of Forests and Parks. The regional office responsible for the dam is as follows:

Commonwealth of Massachusetts  
Department of Environmental Management  
Division of Forests and Parks  
Pittsfield State Forest  
Cascade Street  
Pittsfield, Massachusetts 01201

Mr. Douglas G. Poland is the Regional Supervisor. The telephone number is 413-442-8992.

(g) Purpose of Dam

The Clam Lake Dam is a multiple-purpose dam which is designed to maintain a low level recreation pool and provide flood water storage to reduce downstream flooding from the dam's drainage area. Stored flood water would be gradually released through low and high level inlets of the principal spillway.

(h) Design and Construction History

The Clam Lake Dam was designed by the U.S. Department of Agriculture, Soil Conservation Service. It was completed in the fall of 1977 and has not been in operation since that time because of deficiencies in the emergency spillway slope stability and the principal spillway riser. The Owner, Commonwealth of Massachusetts, and the SCS are presently planning corrective measures deemed necessary by them as reported in investigations conducted in early 1978. (See Page B-1)

(i) Normal Operation Procedure

The Clam Lake Dam would normally be self regulating with the only controlled outlets being the pond drain and the low level bottom release. These outlets are operated only as part of infrequent maintenance checks.

1.3 Pertinent Data

(a) Drainage Area

The drainage area for the Clam Lake Dam covers approximately 10.8 square miles. The upper portion of the drainage area has some swamps and existing natural and manmade impoundments from which the Clam River originates, and the surrounding perimeter areas are primarily mountainous woodland with some open areas. There is some development of farms and homes within the watershed area.

(b) Discharge at Dam Site

Normal discharge at the site is via the low level and high level inlets to the principal spillway and through the 60 inch diameter outlet conduit to the downstream channel. If flood flows occur of sufficient magnitude and duration to fill the flood water



storage available, then excess flow will be discharged around the dam via the emergency spillway channel.

- 1) Outlet works (conduit) size 60 inch, Invert Elev. 1097.0 and Discharge Capacity 950 cfs at Elevation 1178.
- 2) Maximum known flood at dam site - Unknown
- 3) Ungated spillway capacity, principal and emergency, at top of dam - 16,150 cfs at 1178 elev.
- 4) Ungated spillway capacity at test flood elevation - 14,960 cfs at 1177.7 elev.
- 5) Gated spillway capacity at normal pool elevation: None
- 6) Gated spillway at test flood elevation: None
- 7) Total spillway capacity at test flood elevation - 14,960 cfs at 1177.7 elev. (Same as #4)
- 8) Total project discharge (principal and emergency spillways) at top of dam - 16,150 cfs at 1178.0 elev. (Same as #3)
- 9) Total project discharge at test flood elevation - 14,960 cfs at 1177.7 elev. (Same as #4)

(c) Elevation (ft. above MSL)

- 1) Streambed at toe of dam - 1084±
- 2) Bottom of cutoff - 1079±
- 3) Maximum tailwater - Unknown
- 4) Normal Recreation pool - 1144.3
- 5) Full flood control pool - 1172
- 6) Emergency spillway crest - crest elev. = 1172 ungated
- 7) Design surcharge - 1173.68
- 8) Top of dam - 1178.0
- 9) Test flood surcharge - 1177.7

(d) Reservoir (Length in feet)

- 1) Normal pool - 3500 ft±
- 2) Flood Control pool - 6600 ft±
- 3) Emergency spillway crest pool - (Same as 2)

- 4) Top of dam - 7000 ft±
- 5) Test flood pool - (Same as 4)

(e) Storage (acre-feet)

- 1) Normal pool - 750
- 2) Flood control pool - 3060
- 3) Spillway crest pool
  - a) Low stage crest - 750
  - b) High stage crest - 1310
  - c) Emergency spillway - 3060
- 4) Top of dam - 3840
- 5) Test flood pool - 3800

(f) Reservoir Surface (acres)

- 1) Normal pool - 47
- 2) Flood-control pool - 120.5
- 3) Spillway crest
  - a) Low stage crest - 47
  - b) High stage crest - 67
  - c) Emerg. spillway crest - 120.5
- 4) Test flood pool - 139
- 5) Top of dam - 140

(g) Dam

- 1) Type - Earth embankment
- 2) Length - 950 ft±
- 3) Height - 94 ft±
- 4) Top Width - 26 ft
- 5) Side Slopes - 3 hor. on 1 vert. on upstream face, with 20 ft. terrace at elev. 1143.0 of upstream embankment. 2.5 hor. on 1 vert. on downstream face.

- 6) Zoning - Homogeneous, semi-pervious sand, silty with gravel
- 7) Impervious Core - None
- 8) Cutoff - Variable width and depth, sand, silty with gravel earthfill
- 9) Grout curtain - None

(h) Diversion and Regulating Tunnel

Not applicable

(i) Spillways

1) Type:

- a) Principal spillway: Reinforced concrete drop inlet
- b) Emergency spillway: Grass covered, earth fill and excavated channel with level control section. Buried concrete curb weir at downstream end of level section at same elevation

2) Length of weir:

- a) Pond drain inlet: 48 inch diameter pipe
- b) Low stage bottom release (gated): Rectangular orifice 17 inches wide x 12 inches high
- c) High stage bottom release (ungated): Rectangular orifice 4 feet wide x 1 foot high
- d) Low stage inlet: Two rectangular orifices 4.4 feet wide x 1 foot high
- e) High stage inlet: Two weirs 15 ft. long = 30 ft.
- f) Emergency spillway: 385 ft.

(3) Crest Elevation

- a) Pond drain inlet: 1100.0 inv.
- b) Low stage bottom release: 1141.3

- c) High stage bottom release 1143.3
- d) Low stage inlet: 1144.3
- e) High stage inlet: 1153.0
- f) Emergency spillway: 1172.0
- (4) Gates: 48 inch square sluice gate on pond drain inlet and 17 inch x 12 inch open down, low stage bottom release
- (5) Upstream channel:
  - a) Principal Spillway: Stream bed (no impoundment)
  - b) Emergency Spillway: Grass covered earth fill and excavated channel.
- (6) Downstream Channel:
  - a) Principal Spillway: Ledge excavated plunge pool to natural stream channel through narrow valley
  - b) Emergency Spillway: Grass covered, earth fill and excavated channel

(j) Regulating Outlets

The regulated outlets from the dam include the pond drain and the low stage bottom release. The pond drain is controlled by a manually operated 48 inch square sluice gate. This gate is located on the outside face of the principal spillway riser inside the gate well with its invert at elevation 1098. The floor stand operator is located on the top of the principal spillway riser. The gate is a Rodney Hunt, seating type, with a rising stem gear assisted operator having the following identification:

43939-2  
S-5020A

The gate would normally be in the closed position, if the reservoir was functional and would only be operated for maintenance checks and normal (permanent) pool dewatering purposes.

The low stage bottom release is controlled by a manually operated rectangular 17 inch x 12 inch sluice gate. This gate is located on the inside of the face of the principal spillway riser with its invert at elevation 1141.3. The floor stand operator is located on the top of the principal spillway riser. The gate is a

Rodney Hunt, non-seating type, open down and the operator has the following identification:

43939-2  
S-2600A

The gate is normally in the closed position and would only be operated for maintenance checks and when the normal pool is below the high stage bottom release elevation.

## SECTION 2 - ENGINEERING DATA

### 2.1 Design Data

The design data for the Clam Lake Dam provided by the Soil Conservation Service includes hydrologic and hydraulic computations and summaries, structural calculations, a geological report, soil laboratory test data, a summary of embankment slope stability analysis, and other design information all contained within a "Design Report" dated January 1971. The design of the dam and appurtenances is based primarily on a number of Soil Conservation Service Publications which are listed in the General Section of the Design Report.

### 2.2 Construction Data

Design drawings were available for the Clam Lake Dam. These drawings have been reviewed and found to show good agreement with the visual inspection. Since deficiencies have been noted by the Owner and the Soil Conservation Service, "As Built" record drawings have not been issued pending the completion of remedial measures. Completed record drawings may be reviewed at the USDA Soil Conservation Service Office, Cottage Street, Amherst, Massachusetts 01002.

Appendix B contains copies of the more important design drawings. These copies have been made from originals provided by the Soil Conservation Service.

### 2.3 Operational Data

The dam has not been put into service due to a number of recognized deficiencies. Therefore, no operational data is available. Under normal operating conditions, the hydraulics of the principal spillway would maintain a low level recreation pool.

### 2.4 Evaluation of Data

#### (a) Availability

Sufficient data is available to permit an evaluation of the dam when combined with findings of the visual inspection.

#### (b) Adequacy

There is sufficient design and construction data to permit an assessment of dam safety when combined with the visual inspection, past performance, and sound engineering judgment.

#### (c) Validity

Since the observations of the inspection team generally confirm the available data, a satisfactory evaluation for validity is indicated.

## SECTION 3 - VISUAL INSPECTION

### 3.1 Findings

#### (a) General

The Clam Lake Dam, No MA 01052 was in POOR condition at the time of the inspection.

#### (b) Dam

##### 1) Earth Embankment

There are many areas on the downstream slope of the dam where the riprap bedding has washed out. Many areas around the outlet conduit headwall and the swale formed by the intersection of the dam embankment and the emergency spillway embankment showed signs of similar erosion of the bedding material.

The upstream slope near the top of the dam is not uniform due either to improper grading during construction or subsequent settlement.

Some trespassing was noted on the upstream slope between the base of the dam and the beginning of the riprap protective cover. The trespassing appeared to be of the 4 wheel drive vehicle and motorcycle type. Unprotected earth slope areas of the upstream face of the embankment (below elevation 1145.0) are exposed to surface water erosion. There were signs that the reservoir pool has been as high as elevation 1134; whether due to flood flows exceeding the capacity of the 48 inch drain or to unauthorized closing of the pond drain sluice gate is unknown.

Flowing water was noted in the drainage channel at the right toe of the downstream face of the embankment. Since there was no water impounded at the time of the inspection, it can be concluded that the source of this water is ground water from the right abutment area.

There was no discharge in either foundation drain outlet. The ends of the drain pipes have been damaged by vandals; the right drain pipe was broken off inside the sleeve through the headwall.

A serious condition exists relative to the accessibility of the top of the dam. Access is by way of Montville Beech Plain Road to the toe of the dam or across the emergency spillway from Beech Plain Road; access by vehicle by either of these routes is difficult to impossible; neither route would be available during flood conditions since these routes would be blocked by impounded water in the reservoir.

## 2) Emergency Spillway

The emergency spillway is in poor condition.

The left slope of the spillway channel is unstable due to the existence of a stream diverted along the top of the slope. The slope is saturated and slippage has occurred in many areas. It is reported that this stream has overflowed the diversion channel eroding the side slope of the spillway channel.

Trespassing by four wheel drive vehicles and motorcycles has aggravated the condition of the slope. During construction of the dam and spillway, the unstable condition of the slope was recognized and crushed stone was placed on the slope as a remedial measure. This has proven to be less than effective.

Erosion of the downstream face of the emergency spillway training wall embankment was noted between the crest and the beginning of the riprap. Small channels have been eroded by runoff because of the lack of vegetation cover.

The spillway at the transition from the discharge channel to the riprap protected discharge slope is severely eroded and the riprap is being undercut by runoff. Failure of the slope at the transition due to local runoff indicates that serious erosion problems will result when the emergency spillway is in operation.

The right training dike embankment of the emergency spillway, downstream of the spillway crest, is eroding under the riprap cover.

The right downstream training dike does not have sufficient vegetative cover to prevent erosion when the spillway is operating. Also, the right side of spillway floor downstream of the spillway crest slopes about 6 inches in 100 feet toward the training dike. This will result in an imbalanced flow against the training wall and erosion could cause the dike to fail.

The vegetative growth on the spillway floor and slopes is inadequate to prevent surface water erosion or erosion due to spillway flood flows.

The crest and weir wall are in good condition and the grade along the centerline of the emergency spillway appears to conform to the construction plans.



c) Appurtenant Structure

1) Drop Inlet Principal Spillway

The principal spillway riser to the top of the transition section is in poor condition. Cracks, up to 1/16 inch wide were found running continuous from the floor up the walls and running across the transition section ceiling, indicating probable structural weakening of the integrity of the transition section at the base of the riser. Some form ties have either not been cut off, have been poorly patched after being cut off, or have not been patched at all.

The riser structure above the transition section appeared to be in good condition.

The stems and guides for the pond drain sluice gate have been damaged. Guides are broken and the stem is distorted. This damage appears to be the work of vandals.

The gate operators appear to be in good condition, but require some lubrication. Most of the nuts used to fasten the bottom release operator and the pond drain operator are loose.

Vandals have removed the manhole cover at the top of the riser and dropped it into the riser structure.

2) Pond Drain Inlet Structure and Conduit

The pond drain inlet structure is in poor condition. The headwall and wing walls are cracked. Evidence of vertical and horizontal movement of the wing walls suggest foundation failure and shear or moment failure at the interface joint between the head and wing walls. The trash rack bars on the pond drain inlet opening are damaged and cannot function as intended.

The 48 inch diameter pond drain pipe appeared to be in good condition with no visible misalignment or defective joints.

3) Outlet Conduit

The 60 inch diameter conduit was found to be in good condition. The first joint downstream of the riser structure appears to have been grouted. All other joints were found to be evenly spaced and no evidence of prior leakage was observed in the conduit.

4) Plunge Pool and End Wall

The plunge pool which as cut in ledge appears to be in good condition and functioning as intended.

The end wall at the outlet of the 60 inch diameter conduit is in fair condition. There is vertical crack from the top of the outlet conduit to the top of the wall. Also, the right top corner of the endwall has been fractured by vandals.

(d) Reservoir Area

The shore of the reservoir is generally medium sloping woodland. It appears stable and in good condition.

(e) Downstream Channel

The downstream channel is in good condition with no vegetation encroachment. The channel immediately downstream of the dam is unobstructed. Riprap protection of the channel is in good condition and appears to be adequate.

3.2 Evaluation

The dam is in poor condition with areas for additional investigation and/or remedial work being as follows:

- a) Bedding material is eroding from beneath the riprap slope protection on the downstream face of the embankment.
- b) Unprotected earth surfaces on the upstream face of the embankment (submerged by normal pool under operating conditions) are subject to surface water erosion as well as erosion due to fill and draw cycles during high runoff periods.
- c) The upstream slope surface is not uniform.
- d) There appears to be frequent trespassing on the embankment and the emergency spillway channel side slopes.
- e) The outlet ends of the foundation drain pipe are damaged.
- f) There is no reasonable access to the top of the dam at any time and no access at all in full flood time.
- g) The left slope of the emergency spillway channel is unstable.
- h) The transition from emergency spillway discharge channel to the riprap protected discharge is severely eroded.
- i) The right training wall of the emergency spillway discharge channel is not protected against erosion.

- j) The downstream end of the emergency spillway channel floor slopes toward the right training wall.
- k) The inlet structure at the entrance to the pond drain conduit is structurally unsound.
- l) The principal spillway transition section is structurally unsound.
- m) The stem guides for the pond drain sluice gate have been damaged.
- n) Most of the nuts on the sluice gate operating stands are loose.
- o) The first joint in the 60-inch outlet conduit downstream of the riser structure appears to have been grouted.
- p) The end wall at the outlet of the 60 inch diameter conduit is cracked.
- q) The emergency spillway pitches back towards the face of dam. In the event of overtopping or erosion of emergency spillway training dike erosion of the unprotected dam face could occur.
- r) The reservoir was not storing water and therefore other possible problems, such as leakage, could not be viewed.

## SECTION 4 - OPERATIONAL AND MAINTENANCE PROCEDURES

### 4.1 Operational Procedures

#### (a) General

No written operational procedures are available for this dam. The dam would be self regulating when in operation. The sluice gate on the pond drain and the low stage bottom release would normally be closed and would not routinely be operated.

#### (b) Description of Warning System In Effect

There is no written warning system in effect.

### 4.2 Maintenance Procedures

#### (a) General

An annual inspection is made by the Soil Conservation Service and recommendations resulting from this inspection would normally be implemented by the Massachusetts Division of Forests and Parks if the dam was in service.

Typical maintenance items assigned to the Division of Forests and Parks includes liming and fertilizing, mowing, clearing of accumulated debris, etc. At the time of this Phase I inspection some items of maintenance such as liming and fertilizing are not being carried out because of the proposed major modification work which is anticipated.

#### (b) Operational Facilities

Discussions with Division of Forests and Parks personnel indicated that the sluice gate for the pond drain is not operated but remains in the open position because they are aware of the poor condition of the dam's emergency and principal spillways. Also, the low stage bottom release is not operated because there is no requirement to do so at this time. A visual inspection of the gate operators indicated that lubrication is required.

There are no other facilities which require operation.

### 4.3 Evaluation

Since the dam is not in service and will not be placed in service until such time as the spillway problems are resolved, a valid evaluation of the operation and maintenance procedures cannot be made. It must be pointed out, however, that if a major storm event occurs before remedial repairs are completed, in which the capacity of the low level outlet weir was exceeded, the dam would impound water up to the elevation of the high level outlet weir or possibly the emergency spillway crest level. If such an event should occur, it could, in turn, result in

a significant increase in the loading on the spillway riser, thus aggravating the previously discussed evidence of structural instability of the riser transition section.

A formal, written downstream emergency flood warning system should be developed for this dam before it is placed in service.

## SECTION 5 - EVALUATION OF HYDRAULIC/ HYDROLOGIC FEATURES

### 5.1 General

Clam Lake Dam, No. 01052, is a multiple-purpose recreation and floodwater storage facility which was designed by the Soil Conservation Service (SCS), as part of the overall Clam River flood protection project.

The dam is located on the Clam River about 3 miles upstream of the Village of West New Boston in the Town of Sandisfield, Massachusetts and is about 4.5 miles upstream from the confluence of the Clam River with the West Branch of the Farmington River.

The drainage area upstream of the dam is 10.8 square miles with generally mountainous topography.

Development within the watershed is very limited and consists of only a few structures which appear on the USGS quadrangle sheet. The area is mostly wooded with only a minor amount of open fields and ponds.

The dam itself is about 950 feet long and 94 feet high, and is an earthfill embankment. The facility has a principal spillway which maintains a low stage recreation pool and discharges all normal stream flows via a 60-inch diameter conduit through the dam. An emergency spillway, consisting of a 385 ft. wide earth fill and excavated channel with a grass cover, is designed to carry flood flows which exceed the storage capacity, at elevation 1172, of the impoundment around the dam to the downstream channel.

### 5.2 Design Data

The hydraulic features of the Clam Lake Dam have been designed by the S.C.S. to retard a 100 year frequency storm without discharge occurring in the emergency spillway. The calculations included in the SCS Design Report include storage vs. elevation, stage discharge curves for the combined spillways, and routing of the 100 year frequency storm through the reservoir. These calculations are dated 1971.

The SCS has established the elevation of the low stage outlet as 1144.3 which provides 750 acre-feet of storage including 2 acre-feet of sediment storage. The high stage storage was set at elevation 1153.0 providing an additional 560 acre-feet of storage, and the emergency spillway crest set at elevation 1172 providing an additional 1750 acre-feet of storage above the 1153 level pool, resulting in a total flood storage pool of 2310 acre-feet.

### 5.3 Experience Data

No records of flow or stage are known to be available for the Clam Lake Dam since it has just recently been completed and has not been placed in service.

#### 5.4 Test Flood Analysis

The selection of the test flood is based on the Corps of Engineers, "Recommended Guidelines for Safety Inspection of Dams," dated November 1976. These guidelines state that dams classified as "Intermediate" in size, and "High" in hazard potential be tested against the "Probable Maximum Flood" for the region within which the dam is located.

The determination of the PMF for the Clam Lake Dam is based on the Corps of Engineers "Preliminary Guidance for Estimating Maximum Probable Discharges in Phase I Dam Safety Investigations" dated March 1978. The test flood was determined by reference to the mountainous curve in this "Guidance" for a drainage area of 10.2 square miles.

The unit flow of 1,950 cfs per square mile which results in an PMF of 21,060 cfs for the Clam Lake Dam.

The purpose of this Phase I investigation is to assess the dam's overtopping potential and its ability to store and/or discharge the test flood. This requires determining the storage characteristics of the impoundment area and the stage vs. discharge characteristics of the spillway. The SCS design report tabulates all of this data, and our review has determined the information to be in accordance with standard design practices, therefore, as noted in the computations included in Appendix D, this information has been utilized in performing the test flood analysis.

The test flood has been routed through the reservoir using the iteration process as outlined in the Corps of Engineers, "Preliminary Guidance for Estimating Probable Maximum Discharges in Phase I Dam Safety Inspections." The results of routing the PMF through the reservoir indicate that the storage capacity of the impoundment area will reduce the PMF inflow of 21,060 cfs to a reservoir outflow of approximately 14,960 cfs. This assumes that the level of the recreation pond is at elevation 1143.3 at the start of the storm, and the entire flood storage volume is available. Elevation 1,153.0 is the crest elevation of the high stage overflow weirs.

The combined spillways have a discharge capacity with the water level at the top of the dam of 16,150 cfs which is sufficient to pass the calculated PMF outflow of 14,960.

#### 5.5 Dam Failure Analysis

A dam failure analysis using the procedures in the Corps of Engineers, "Rule of Thumb Guidance for Estimating Downstream Failure Hydrographs" dated April, 1978, was performed for the Clam Lake Dam. The assumed conditions are as follows:

1. Water level prior to breach is at top of dam elevation.
2. Stream flow at time of breach is PMF test flood for the reach in question.

3. Stream flow at confluence, is PMF for tributary watershed.

Prior to dam failure the PMF outflow from the dam and the PMF from tributary drainage areas will cause significant damage downstream and possibly the loss of a few lives. The damage that will result includes 11 houses, four bridges and 13,000 feet of roadway.

For an assumed breach equal to 40 percent of the dam width computed at half height, the breached width is 236 ft. The resulting dam failure flow using a water height of 94 ft. is 361,975 cfs.

The first area impacted by the dam failure is at a crossing of Montville-Beech Plain Road. There is a steel beam-wood deck bridge at the crossing. The roadway will be severely overtopped and the structure inundated by about 34 feet of water. The structure can be expected to fail and the roadway washed out.

The second and major area impacted by the dam failure is the Village of West New Boston at the confluence of the Clam River and the Buck River. The failure of the dam would result in potential loss of lives, homes, out buildings, private property, major roadways and a bridge. The area will be inundated with as much as 19 feet of water.

The third area to be impacted would be an area west of New Boston near the intersection of Beech Plain Road and New Boston-New Hartford Road. The failure of the dam in this area will result in potential loss of lives, homes, outbuildings, private property, major roadways, a cemetery and a major road bridge. The area would be inundated by as much as 11 feet of water.

The fourth area to be impacted by the dam failure would be the Village of Roosterville, which is on the West Branch of the Farmington River. The failure of the dam in this area will result in potential loss of life, homes, outbuildings, private property, a major roadway and a bridge. The area would be inundated by as much as 26 feet of water.



The fifth area to be impacted by the failure of the dam would be downstream of Roosterville on the West Branch of the Farmington River where Rt. 8 and a secondary road crosses the River. This area would experience damage to the secondary road and the secondary road bridge. Since Rt. 8 has recently been constructed, it would be expected that the bridge would adequately pass the flood due to failure of the dam. The area would be inundated with about 26 feet of water.

The sixth area to be impacted by the dam failure flood in the Colebrook Reservoir. It is estimated that sufficient storage would be available to retard any additional flooding downstream. The surface elevation is estimated to rise about 8 feet due to the volume of flood water from the dam failure.



PROBABLE DOWNSTREAM IMPACT OF DAM FAILURE  
CLAM LAKE DAM  
MA 01052

Area Location	Impact Area	Flood Flow Prior to Dam Failure (cfs)	Stage Prior to Dam Failure (Ft.)	Flood Flow After Dam Failure	Stage After Dam Failure (Ft.)	Downstream			Comments
						Damage After Dam Failure	No. of Houses	Other	
1 Dam	--	15,000	5.7'	362,000	Dam Failure		0	Dam	No downstream damage prior to dam failure.
2 2000'DS	1	15,000	8	242,000	34		0	1 Bridge	Montville Beech Plain Rd. is a secondary road. Before dam failure 1 bridge inundated. Roadway and bridge are major. Before dam failure no damage.
3 14,000'DS	2	20,500	9	151,500	19		19±	1 Bridge 5000' of road	Roadway and bridge are major. Before dam failure no damage.
4 18,000'DS	3	53,000	8	184,000	11		6±	1 Bridge 4000' of road	Roadway and bridge are major. Before dam failure no damage.
5 25,500'DS	4	135,000	21	225,000	26		11	1 cemetery 1 Bridge 13,000' of road	Bridge and roadway are major. Before dam failure 11 houses, 1 bridge & 13,000 ft. of road inundated.
6 29,500'DS	5	135,000	21	255,000	26		0	2 Bridges	One bridge is major, one bridge is secondary. Before failure 2 bridges inundated. Flood attenuated by being routed through Colebrook Reservoir.
7 36000'DS	6	---	--	---	--		---	---	Dam Failure will result in reservoir rising 8'±. Before failure no affect.



FROM: GENERAL HIGHWAY MAP,  
BERKSHIRE COUNTY

TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

## LOCATION AND DOWNSTREAM HAZARD MAP

CLAM LAKE DAM (MA 01052)  
BERKSHIRE COUNTY

SANDISFIELD  
MASSACHUSETTS

SCALE: AS NOTED

DATE: FEBRUARY 1980

## SECTION 6 - EVALUATION OF STRUCTURAL STABILITY

### 6.1 Visual Observation

The visual inspection of the dam embankments identified irregularities in the grade of the upstream slope embankment which are cause for concern. Erosion of sand and silt from beneath the riprap, protective layer on the downstream embankment slope was also noted.

The principal spillway structure was found to be unstable. Cracks were noted in the transition section and those cracks showed displacement.

The inlet structure wingwalls for the pond drain are cracked and displacement indicates differential movement of the sections.

The left slope of the emergency spillway is unstable due to a diversion ditch at the top of slope combined with the steep side slopes. The area of the emergency spillway at the transition from the grass surface to the riprap slope is eroded and the riprap is undercut.

The poor condition of the vegetative cover on slopes and channel bottom of the emergency spillway indicates that soil erosion could occur if the structure was in service.

### 6.2 Design and Construction Data

Design data for the emergency spillway side slopes and the spillway channel is not included in the SCS Design Report. From the design plans, it appears that a slope design at 2 horizontal to 1 vertical was utilized but under the field conditions at the site, this slope is too steep.

### 6.3 Post Construction Changes

There have been no post construction modifications to the structure but, due to the many embankment and structural problems recognized to date, extensive studies have been made by the Soil Conservation Service to determine the source of the problems and to recommend corrective actions.

### 6.4 Seismic Stability

The Clam Lake Dam is located in seismic zone 1. According to the recommended Corps of Engineers Guidelines, a seismic analysis is not warranted.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS  
AND REMEDIAL MEASURES

7.1 Dam Assessment

(a) Condition

The dam and its appurtenances are in POOR condition due to the recognized deficiencies in the emergency spillway and principal spillway as well as numerous other deficiencies noted during this inspection.

(b) Adequacy of Information

There is sufficient design and construction data to permit an assessment of dam safety when combined with visual inspection, past performance, and sound engineering judgment.

(c) Urgency

The recommendations and remedial measures described herein should be implemented by the owner within one year upon receipt of this Phase I Inspection Report.

7.2 Recommendations

The recommendations of this Phase I investigation are that the following additional studies be made, under the supervision of a qualified registered engineer:

- a) Determine the cause of erosion problems throughout the project site including:
  - i. Erosion of soil from beneath riprap on the downstream embankment slopes.
  - ii. Surface erosion on the upstream face of the dam.
  - iii. Erosion of the left slope of the emergency spillway.and determine what corrective measures are required and implement those corrective measures.
- b) Determine causes of the slope stability problems throughout the project site including:
  - i. Undercutting of the riprap slope at the transition section from the emergency spillway.
  - ii. Left slope of emergency spillway.and determine what corrective measures are required and implement those corrective measures.

- c) Determine the cause of the upstream embankment slope irregularities and what corrective measures are required and implement those corrective measures.
- d) Finalize and implement a suitable design for a new riser structure or a suitable repair of the existing structure.
- e) Develop reliable means of access to the top of the dam at all conditions of runoff.
- f) Determine why grout was placed in the first joint of the 60" diameter pipe out of the riser structure, determine what corrective measures are required and implement them.
- g) Determine what corrective measures are required to pitch side slope of emergency spillway away from face of dam and implement those corrective measures.
- h) Develop and implement a method to routinely monitor seepage through the dam embankment.

### 7.3 Remedial Measures

The recommendation of this Phase I investigation is that the following remedial and/or maintenance items be carried out:

- a) Repair right foundation drain outlet pipe at the endwall.
- b) Repair the right corner of the end wall.
- c) After erosion and stability problems are solved by a qualified registered engineer, place topsoil where necessary and seed all exposed earth surfaces on the dam embankment, spillway channel and spillway training dike embankment to prevent erosion of soil.
- d) Rebuild the inlet structure and trash racks.
- e) Repair and replace the stem guides for the pond drain gate.
- f) Lubricate and exercise the two gate operators on a regular basis.
- g) Prepare a formal written downstream emergency flood warning system.
- h) Implement measures to ensure 48 inch gate on low level spillway is kept in a fully open position and the reservoir normally kept "dry" until all of the above recommendation and remedial measures can be implemented. A program of monitoring during periods of intense rainfall should be initiated.

#### **7.4 Alternatives**

**There are no meaningful alternatives to the above recommendations.**

APPENDIX A  
VISUAL CHECK LIST WITH COMMENTS

INSPECTION CHECK LIST  
PARTY ORGANIZATION

PROJECT Clam Lake Dam

DATE 11/1/79

TIME 11:30 A.M.

WEATHER Clear and cool

W.S. ELEV. 1100<sup>+</sup> U.S. 1084<sup>+</sup> D.N.S.

PARTY:

- |  |           |
|--|-----------|
| 1. <u>J.W. Powers, P.E., Project Manager</u>         | 6. _____  |
| 2. <u>G.H. McDonnell, P.E., Hydrology/Hydraulics</u> | 7. _____  |
| 3. <u>D.M. Lenart, P.E., Civil</u>                   | 8. _____  |
| 4. <u>E.A. Moe, P.E., Soils/Hydraulics</u>           | 9. _____  |
| 5. <u>O.H. Dumais, Civil</u>                         | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>All features inspected by inspection party</u>		
2. _____		
3. _____		
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

Also present:

R. Curran, U.S.D.A., Soil Conservation Service



# INSPECTION CHECK LIST

## PARTY ORGANIZATION

PROJECT Clam Lake Dam

DATE 11/7/79\*

TIDE 1:00 P.M.

WEATHER Sunny and Cool

W.S. ELEV. 1100<sup>+</sup> U.S. 1084<sup>+</sup> DN.S.

### PARTY:

- |   |           |
|---|-----------|
| 1. <u>E.J. Harvey, P.E., Structural</u> | 6. _____  |
| 2. <u>O.H. Dumais, Civil</u>            | 7. _____  |
| 3. _____                                | 8. _____  |
| 4. _____                                | 9. _____  |
| 5. _____                                | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. Interior of principal spillway structure	Dumais & Harvey	
2. _____		
3. _____		
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

\* Special followup inspection with SCS personnel to inspect interior of principal spillway; arrangements made to accompany SCS personnel on this special inspection previously scheduled by SCS.

Inspection notes for this inspection are incorporated on the following pages with comments for our 11/1/79 inspection.

Also present:

C. Dodge	S.C.S. Amherst, MA office
D. Wallin	S.C.S. Penn. office
L. Thomas	S.C.S. Penn. office
E. Alling	S.C.S. Wash., D.C. office
G. Greenleaf	S.C.S. Pittsfield, MA office
C. Curran	S.C.S. Amherst office

## INSPECTION CHECK LIST

PROJECT Clam Lake Dam DATE 11/1/79  
 PROJECT FEATURE All Features NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	No access to gates if flood condition
Crest Elevation	1178.0
Current Pool Elevation	1100 (Invert of drain inlet)
Maximum Impoundment to Date	1134 (Debris and wave scars)
Surface Cracks	None
Pavement Condition (Rip Rap Faces)	Downstream slope good but some erosion under rock. Upstream slope near crest not uniform.
Movement or Settlement of Crest	None apparent
Lateral Movement	None apparent
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Intersection of dam & spillway slopes show erosion. Sand & silt washed from under rip rap at both abutments & around discharge end wall
Indications of Movement of Structural Items on Slopes	None apparent
Trespassing on Slopes	None apparent on rock slope, but below upstream face shows some vehicular traffic.
Vegetation on Slopes	Poor with add'l. vegetation required.
Sloughing or Erosion of Slopes or Abutments	Gravel washed out from under rip rap and rock has settled 396 ft. from right abutment.
Rock Slope Protection - Riprap Failures	Sand & silt wash out from under rip rap during rainfall.
Unusual Movement or Cracking at or near Toes	None apparent
Unusual Embankment or Downstream Seepage	Flow of water running right toe channel
Piping or Boils	None (No water impounded)
Foundation Drainage Features	Foundation drain outlet pipes dry & ends damaged by vandals.
Toe Drains	End of pipes damaged and pipes dry
Instrumentation System	None
Access to Crest	In event of flood no access to riser

# INSPECTION CHECK LIST

PROJECT Clam Lake Dam DATE 11/1/79  
 PROJECT FEATURE All Features NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	
General Condition	Good condition, needs grass cover
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Good condition but more grass required
b. Weir and Training Walls	Concrete crest flush with spillway floor No erosion protection on training wall slope. Good with some chips
General Condition of Concrete	
Rust or Staining	None apparent
Spalling	None
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None
Drain Holes	None
c. Discharge Channel	
General Condition	Channel floor good until the transition between soil floor and riprap. Under cutting noted & sloped section shows failure of rockfill.
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Good grade but requires more grass
Other Obstructions	Left slopes of spillway failing due to drainage ditch diversion along crest. Vehicular traffic noted on slopes far left. Slip outs & failures noted on left side.
d. Other	Training wall right no erosion protection. Also, s.w. floor pitch 6" in 100' to wall to cause rapid erosion.

## INSPECTION CHECK LIST

PROJECT Clam Lake DamDATE 11/1/79PROJECT FEATURE All Features

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	End wall cracked at centerline of pipe. Right corner cracked from vandals.
Rust or Staining	None
Spalling	None
Erosion or Cavitation	None
Visible Reinforcing	None
Any Seepage or Efflorescence	None
Condition at Joints	Good
Drain holes	None
Channel	
Loose Rock or Trees Overhanging Channel	None
Condition of Discharge Channel	Good
Conduit	Good condition. Joints in good condition.

## INSPECTION CHECK LIST

PROJECT Clam Lake Dam : DATE 11/1/79  
PROJECT FEATURE All Features NAME \_\_\_\_\_  
DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	Above embankment good. Cracks noted in transition section.
Rust or Staining on Concrete	Extensive staining in transition. Form ties exposed.
Spalling	No spalling noted in entire structure.
Erosion or Cavitation	Concrete eroded at sluice gate at base of riser.
Cracking	Numerous cracks in transition area.
Alignment of Monoliths	Good
Alignment of Joints	Pipe joints are in good condition. First joint out of riser grouted on 60" pipe.
Numbering of Monoliths	N/A

## INSPECTION CHECK LIST

PROJECT Clam Lake DamDATE 11/1/79PROJECT FEATURE All Features

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	Good condition
Slope Conditions	Good
Bottom Conditions	Good
Rock Slides or Falls	None
Log Boom	N/A
Debris	None
Condition of Concrete Lining	N/A
Drains or Weep Holes	N/A
b. Intake Structure	
Condition of Concrete	Wing walls are cracked
Stop Logs and Slots	Trash racks are damaged and debris could enter conduit.

## INSPECTION CHECK LIST

PROJECT Clam Lake Dam

PROJECT FEATURE All Features

DISCIPLINE \_\_\_\_\_

DATE 11/1/79

NAME \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Good
Condition of Joints	Good
Spalling	None
Visible Reinforcing	None
Rusting or Staining of Concrete	None
Any Seepage or Efflorescence	None
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	Structure not in use.
Cracks	None visible (no access to lower sections at time of first inspection) Second inspection noted numerous cracks
Rusting or Corrosion of Steel	None
b. Mechanical and Electrical	
Air Vents	N/A
Float Wells	N/A
Crane Hoist	N/A
Elevator	N/A
Hydraulic System	N/A
Service Gates	Rodney Hunt 43939-2 S-2600A One nut of 4 tight
Emergency Gates	Rodney Hunt 43939-2 Gear Assisted S-5020A (2 of 4 nuts on) both gates open.
Lightning Protection System	N/A
Emergency Power System	N/A
Wiring and Lighting System in Gate Chamber	N/A

## INSPECTION CHECK LIST

PROJECT Clam Lake DamDATE 11/1/79PROJECT FEATURE All Features

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	
Bearings	N/A
Anchor Bolts	N/A
Bridge Seat	N/A
Longitudinal Members	N/A
Under Side of Deck	N/A
Secondary Bracing	N/A
Deck	N/A
Drainage System	N/A
Railings	N/A
Expansion Joints	N/A
Paint	N/A
b. Abutment & Piers	
General Condition of Concrete	N/A
Alignment of Abutment	N/A
Approach to Bridge	N/A
Condition of Seat & Backwall	N/A



APPENDIX B  
ENGINEERING DATA

## APPENDIX B

### ENGINEERING DATA

#### INDEX

##### List of Available Documents

##### 1. Design and Construction Records

Design records include the following:

- construction drawings
- construction specifications
- construction revisions
- design criteria
- layout
- hydraulic design
- foundation and embankment design
- geology report
- soil testing report
- structural computations
- quantity estimates
- inspector's notes
- seeding schedule

Construction records include the following:

- inspector's and engineer's diaries
- soil testing reports
- concrete testing reports
- material certifications
- equipment guarantees
- correspondence
- quantities
- pay estimates

##### 2. Reports on problems with riser and emergency spillway slope

The following records are kept on file by the U.S. Department of Agriculture, Soil Conservation Service, and may be obtained through their office located on Cottage Street in Amherst, Massachusetts.

- 1/19/78 Final Report of the committee investigating potential deficiencies in the emergency spillway and associated areas, Clam Lake Dam Site, Clam River Watershed, Mass.
- 3/24/78 Engineering Investigation Report Clam River Watershed Project Clam Lake Site.

A brief summary of these reports is appended hereto.

### Construction Drawings

Copies of the following drawings are appended hereto:

3. <u>Drawings</u>	<u>Title</u>	<u>Page No.</u>
1	Cover sheet	B-3
2	Plan of Storage Area	B-4
5	Plan of dam site	B-5
6	Plan of Emergency Spillway	B-6
7	Fill Placement	B-7
9	Foundation Drain Detail	B-8
10	Principal Spillway plan and profile	B-9
11	Principal Spillway details	B-10
13	Emergency Spillway Profiles	B-11
18	Riser Details	B-12
25 & 26	Reservoir drain inlet detail	B-13,14
30, 31, 32		
33, 34	Logs of test holes	B-15,16,17,18,19

From U.S.D.A. Soil Conservation Service, Amherst, Massachusetts,  
March 24, 1978, "Engineering Investigation Report Clam River Watershed  
Project Clam Lake Site."

#### CONCLUSIONS AND RECOMMENDATIONS

1. At the time this riser was designed (late 1971) the horizontal embankment loading used in design was assumed to be that developed by active earth pressures. Design Note No. 17, published on April 1977, shows that active pressure assumptions underestimate the embankment moment when used in the design of a riser with a monolithic transition elbow. The vertical earth load imparted to the cantilevered transition elbow causes a restraining force which results in higher moments. Design Note No. 17 recommends that "at rest" lateral pressures be used for the embankment loading assumptions.

The Committee concludes that the effects of this loading condition, dealt with as item 3 on page 4 of Mr. Alling's memorandum, were the main cause of the cracking observed in the transition elbow.

Although it seems reasonable to use the At Rest Lateral Pressure Theory in this case, the Committee nevertheless recommends that future structures of this type be constructed in a manner that will allow movement of the vertically projected structural member. This will reduce the horizontal load to a minimum.

2. The November 23, 1977 memo by Alling notes several problem areas, either within the design computations or not covered in the design computations. Although the Committee has centered on cantilever embankment loading as the main cause of structural failure, these other areas should be taken into consideration in any design work for repair or reconstruction of this riser, or on future designs of this type.
3. The Committee recommends a follow-up check of the riser be made as soon as weather and terrain conditions permit. Sufficient additional measurements and photographs should be made so that detailed drawings can be prepared showing the location and sizes of the cracks. These should be similar to the drawings prepared as Exhibits 23 through 27 of the Engineering Investigation Report for Site 3A, Newton-Hoffman Creek Watershed, New York, September 15, 1976. This would include drawings showing any cracking that may have developed in the vertical section of the riser, at elevations above the special elbow, subsequent to earlier checks (which found no cracking in that section).

It is recommended that a grid system be marked off on the affected portions of the riser to assist in locating damage, preparing drawings, and providing a key to photographic records. This would speed up subsequent checks also.

An attempt should also be made to measure any displacement of the riser that may have taken place. Reports from earlier meetings indicate concern that displacement had taken place, but no measurements have been made.

The recommended documentation is needed to establish the severity extent of the damage to the riser and to correlate structure performance with that predicted from analysis of the design and with performance of other afflicted structures (e.g. Site 3A, Newton-Hoffman).

4. Concurrent with the Committees' work, studies of corrective measures for repair of the riser have been underway. Details of the current proposal for repair are contained in a March 2, 1978 memo to Cletus J. Gillman from Benjamin Isgur. Inasmuch as this proposal is well-grounded and has reached an advanced stage of discussion, the Committee spent little time on recommendations for repair and supports the proposal noted above.

From "Final Report of the Committee investigating potential deficiencies in the emergency spillway and associated areas, Clam Lake Site, Clam River Watershed, Massachusetts, January 10, 1978."

#### FINAL REPORT

"This is the final report of the committee investigating stability problems of the emergency spillway side slopes at Clam Lake Site in the Clam River Watershed, Berkshire County, Massachusetts. Construction was completed and the final inspection conducted on October 14, 1977. A copy of the memo from Dr. Isgur to Peter G. Waldo, October 7, 1977, which established this committee is in appendix C.

Nine problem areas were identified in a preliminary report (see memo from the committee to Cecil B. Currin, dated October 20, 1977, included in appendix C). These problem areas are located in figure 1 which is a plan view of the emergency spillway area. These nine problems were divided into two groups with the more serious labeled as primary problems. Table 1 presents the primary problems and lists apparent causes of these problems. Table 2 is similar and presents the less serious, or secondary, problems.

The committee thinks that the basic cause of the stability problems of the side slopes and the diversion channel was the design decision to leave Beech Plain Road undisturbed. In order to keep away from Beech Plain Road, the design called for 2:1 side slopes throughout a large portion of the outside edge of the spillway. These steep side slopes have since proven to be inadequate considering the proximity of the diversion to the spillway and the severe winter conditions at the site. The extent and history of these problems are documented in appendices A and B.

It is apparent to the committee that any solution to the primary problems will call for relocation of the road or installation of expensive retaining devices such as cribbing. The economics of installing such devices should be weighted against relocating portions of the road. Additional surveying and subsurface investigations appear to be necessary before a final design can be prepared."

# CLAM RIVER WATERSHED CLAM LAKE MULTIPLE-PURPOSE RECREATION AND FLOOD PREVENTION DAM

DRAINAGE AREA  
TOTAL STORAGE  
FLOODWATER RETARDING STORAGE  
TO EMERGENCY SPILLWAY CREST  
WATER SURFACE AREA  
AT PERMANENT POOL  
HEIGHT OF DAM  
VOLUME OF FILL 525

BUILT UNDER THE WATERSHED PROGRAM  
FLOOD PREVENTION ACT

by

MASSACHUSETTS DEPARTMENT OF NATURAL

and

MASSACHUSETTS WATER RESOURCES

and

BERKSHIRE CONSERVATION DISTRICT

of the

COMMONWEALTH of MASSACHUSETTS

with the assistance of

SOIL CONSERVATION SERVICE

of the

UNITED STATES DEPARTMENT of AGRICULTURE

1972

## INDEX

SHEET 1 - COVER SHEET	SHEET 14 - EME
SHEET 2 - PLAN OF STORAGE AREA	SHEET 15 - EME
SHEET 3 - AERIAL PLAN	SHEET 16 - ROCK
SHEET 4 - SITE LAYOUT DETAILS	SHEET 17 - FILL
SHEET 5 - PLAN OF DAM SITE	SHEETS 18 & 23 -
SHEET 6 - PLAN OF EMERGENCY SPILLWAY	SHEET 24 - HIGH
SHEET 7 - FILL PLACEMENT	SHEETS 25 & 26 -
SHEET 8 - PROFILE OF CUTOFF TRENCH	SHEET 27 - CON
SHEET 9 - FOUNDATION DRAIN DETAILS	SHEET 28 - MEA
SHEET 10 - PRINCIPAL SPILLWAY PLAN AND PROFILE	SHEET 29 - EME
SHEET 11 - PRINCIPAL SPILLWAY DETAILS	SHEETS 30 & 34 -
SHEET 12 - PRINCIPAL SPILLWAY EXCAVATION & E.S. FILL SECTION	SHEET 35 - STAI
SHEET 13 - EMERGENCY SPILLWAY PROFILES	SHEET 36 - JUT

# WATERSHED PROJECT MULTI-PURPOSE DAM FLOOD PREVENTION

6900 ACRES  
3050 ACRE FEET  
2300 ACRE FEET

47 ACRES

88 FEET  
525,000 CUBIC YARDS

FLOOD PROTECTION AND  
FLOOD CONTROL ACT

MANAGEMENT OF NATURAL RESOURCES

WATERSHED SOURCES COMMISSION



WATERSHED DISTRICT

COMMONWEALTH OF MASSACHUSETTS

Office of  
WATERSHED SERVICE

DEPARTMENT of AGRICULTURE

CLAM LAKE  
MULTIPLE-PURPOSE DAM



- SHEET 14 - EMERGENCY SPILLWAY DRAIN
- SHEET 15 - EMERGENCY SPILLWAY DRAINAGE DETAILS
- SHEET 16 - ROCK TREATMENT DETAILS
- SHEET 17 - FARM FIELD FENCE DETAILS
- SHEETS 18 TO 23 - RISER DETAILS
- SHEET 24 - HIGH & LOW STAGE TRASH RACK DETAILS
- SHEETS 25 & 26 - RESERVOIR DRAIN INLET DETAILS
- SHEET 27 - CONDUIT DETAILS
- SHEET 28 - HEADWALL DETAILS
- SHEET 29 - EMERGENCY SPILLWAY WEIR DETAILS
- SHEETS 30 TO 34 - LOGS OF TEST HOLES
- SHEET 35 - STABILIZATION OF STRUCTURES
- SHEET 36 - JUTE NETTING & CHAIN LINK FENCE DETAILS



<b>CLAM RIVER WATERSHED</b>	
CLAM LAKE MULTIPLE-PURPOSE SANDSFIELD, MASSACHUSETTS	
<b>COVER SHEET</b>	
<b>U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE</b>	
Designed by J. A. SHAW	Date 9-7-71
Drawn by P. J. WILSON	Scale 1" = 1/2 MI.
Checked by J. A. SHAW	Approved by J. A. SHAW
Reviewed by G. B. WICKS	8-9-71







LEGEND

MINOR ROAD	PERMANENT FLOOD
PERMANENT STREAM	DESIGN HIGH WATER
INTERMITTENT STREAM	SHRUB STATION
WOODS LINE	BRUSH MAAP
STONE WALL	DRILL HOLE
WIRE FENCE	TEST PIT
SWAMP	ROCK OUTCROP
GRAVEL PIT	BEDROCK
DEPRESSION	POWER LINE
APPROX LIMIT OF WORK AREA	TELEPHONE LINE
APPARENT PROPERTY LINE	PIPE LINE
CLEARING LIMITS	WELL
CLEARING & GRUBBING	SPRING
FOUNDATION EXCAVATION	DIVERSION DITCH
FOUNDATION CHAIN	BOUNDARY MONUMENT
	BEAVER DAMS






CLEARING REQUIREMENTS	
CLEARING CLASS "C"	ALONG THE EDGE OF THE PERMANENT POOL FROM THE 1140.3 CONTOUR TO 10' HORIZONTALLY BEYOND THE 1143.3 CONTOUR
CLEARING CLASS "B"	WITHIN THE DISPOSAL AREAS AND WITHIN THE PERMANENT POOL BELOW ELEVATION 1140.3
CLEARING & GRUBBING	DAM, EMERGENCY SPILLWAY, BORROW AREA, DIVERSION, INLET & OUTLET CHANNELS AND ROCK DISPOSAL

**NOTES:**

- 1 ORIGINAL TOPO SURVEYED BY M. NOYES
- 2 ADDED SURVEY (ABOVE ELEV 1160) BY 1
- 3 LOCATION OF BEAVER PONDS AS OF JULY 1961
- 4 NO WASTE MATERIAL SHALL BE LEFT @ POOL CONTOUR (ELEVATION 1143.3) AND
- 5 THE SURFACE OF THE BORROW AND DISPOSAL AREAS SHALL BE LEFT NEAT AND IN A SLIGHTLY CONCAVE TO PROVIDE POSITIVE DRAINAGE. SLOPES SHALL BE LEFT NO STEEPER THAN 2:1

TBM 1 (ELEV 1210.56) TOP OF 2' BOULDER 80' U/S OF STA 9+25  
 TBM 251 (ELEV 1277.72) TOP OF 2' x 4' BOULDER APPROX 90' WEST OF BEECH PLAIN ROAD.  
 TBM 341 (ELEV 1099.79) TOP OF 2' x 3' ROCK WEST SIDE CLAM RIVER, EAST SIDE LOGGING ROAD




**BORROW AREA DIVERSION  
TYPICAL SECTION**  
NOT TO SCALE

SCALE IN FEET  
0 100 200

CLAM RIVER WATERS CLAM LAKE MULTIPLE- SANDSFIELD, MASS			
PLAN OF STORAGE			
U. S. DEPARTMENT OF SOIL CONSERVATION			
Designed J. A. TIBBETTS	Date 8-71	Appr'd	
Drawn F. J. WILSON	Date 12-21-71	Check'd	
Traced F. J. WILSON	Date 9-10-72	Scale	
Checked J. J. ELABRAN	Date 3-9-72	Sheet	3 of 3

2173





NOTES
1. ORIGINAL TOPD SURVEYED BY M. NOTES 1962
2. ADDED SURVEY (ABOVE ELEV 1160) BY R. BROWN & ASSOC 1970
3. LOCATION OF BEAVER PONDS AS OF JULY 1970
4. NO WASTE MATERIAL SHALL BE LEFT BETWEEN THE PERMANENT POOL CONTOUR (ELEVATION 1143.3) AND ELEVATION 1100.0.
5. THE SURFACE OF THE BORROW AND DISPOSAL AREAS SHALL BE LEFT NEAT AND IN A SIGHTLY CONDITION AND SLOPED TO PROVIDE POSITIVE DRAINAGE. SIDE SLOPE SHALL BE LEFT NO STEEPER THAN 2:1

**NOTES:**

1. ORIGINAL TOPD SURVEYED BY M. NOTES 1962
2. ADDED SURVEY (ABOVE ELEV 1160) BY R. BROWN & ASSOC 1970
3. LOCATION OF BEAVER PONDS AS OF JULY 1970
4. NO WASTE MATERIAL SHALL BE LEFT BETWEEN THE PERMANENT POOL CONTOUR (ELEVATION 1143.3) AND ELEVATION 1100.0.
5. THE SURFACE OF THE BORROW AND DISPOSAL AREAS SHALL BE LEFT NEAT AND IN A SIGHTLY CONDITION AND SLOPED TO PROVIDE POSITIVE DRAINAGE. SIDE SLOPE SHALL BE LEFT NO STEEPER THAN 2:1

60 U/S OF  
 UNDER APPROX  
 ROCK WEST SIDE  
 ROAD



**WATER DIVERSION  
 TYPICAL SECTION**  
 NOT TO SCALE


<b>CLAM RIVER WATERSHED PROJECT</b>			
<b>CLAM LAKE MULTIPLE-PURPOSE DAM</b>			
<b>SANDSFIELD, MASSACHUSETTS</b>			
<b>PLAN OF STORAGE AREA</b>			
<b>U. S. DEPARTMENT OF AGRICULTURE</b>			
<b>SOIL CONSERVATION SERVICE</b>			
Designed: J. A. TIBBETTS	Date: 8-71	Approved by:	
Drawn: F. J. WILSON	Date: 10-21-71	Checked:	
Traced: F. J. WILSON	Date: 9-10-72	Shaded:	
Checked: J. E. ADAM	Date: 3-8-72	Scale:	
			<b>MA-387 P</b>

303

B-4



REPRODUCED AT GOVERNMENT EXPENSE




CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

PLAN OF DAMSITE

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE


Designed by J. A. FARRER	Scale	Approved by
Drawn by F. A. WILSON	8-71	Year
Traced by R. S. CLAYTON	8-71	Year
Checked by J. P. POLO	8-71	Year
		MA-387 P

B-5










TYPICAL SECTION I



TYPICAL SECTION II

## EARTH FILL REQUIREMENTS

ZONE	MATERIAL	MAXIMUM ROCK SIZE	MAXIMUM LIFT $\Delta$	MINIMUM WATER CONTENT	COMPACTION CLASS	COMPACTION DEFINITION
1	SAND, SILTY WITH GRAVEL REPRESENTED BY TP 156 (25'-10'), DM 3 (0.5'-23'), TP 656 (11.0'-12'), TP 256 (3'-10'), TP 154 (2.5'-10'), TP 651 (1'-10')	6"	9"	OPTIMUM	A	100% MAX DENSITY BY ASTM D 698 METHOD A
2	SILTY SAND AND GRAVELY SAND REPRESENTED BY TP 254 (3'-10'), TP 258 (3'-10'), TP 652 (0.5'-10'), TP 633 (1'-10'), TP 654 (1'-10'), DM 9 (0-12'), DM 10 (0-10')	8"	12"	OPTIMUM	C	4 PASSES PER LAYER OF FILL w/ PNEUMATIC TIRE ROLLER WEIGHING AT LEAST 50 TONS OR AN EQUIVALENT METHOD APPROVED BY THE ENGINEER
ES FILL	SAND, SILTY WITH GRAVEL SIMILAR TO THAT SHOWN IN ZONE 1.	12"	18"	OPTIMUM	C	EQUIVALENT METHOD APPROVED BY THE ENGINEER


 $\Delta$  MAXIMUM LIFT THICKNESS PRIOR TO COMPACTION

 $\Delta$  BASED ON STANDARD PROCTOR


## CONSTRUCTION NOTES:

- EQUIPMENT PLACED RIPRAP SHALL BE WELL GRADED, SIZE EQUAL TO THE DEPTH SHOWN. 60% TO 75% BE LARGER THAN  $\frac{3}{4}$ " OF THE DEPTH SHOWN.
- BEDDING SHALL BE WELL GRADED BETWEEN  $\frac{3}{4}$ " AND TO 70% PASSING THE  $\frac{3}{4}$ " SIEVE.
- REPRESENTATIVE ROCK SAMPLES FROM THIS WATER: ALL SAMPLES TESTED CONFORM TO MATERIAL SPE.

REPRODUCED AT GOVERNMENT EXPENSE.



CAL SECTION (VALLEY)



CAL SECTION (ABUTMENTS)

NOTE:  
DELETE FOUNDATION DRAIN ABOVE ELEV 1143.0

SHALL BE WELL GRADED AND HAVE A MAXIMUM  
SHOWN 60% TO 75% OF THE RIPRAP SHALL  
DEPTH SHOWN  
ADED BETWEEN  $\frac{3}{4}$ " AND  $3\frac{1}{2}$ " WITH 30%  
IEVE  
ES FROM THIS WATERSHED HAVE BEEN TESTED  
ORN TO MATERIAL SPECIFICATION 523.

20 0 20 40  
SCALE IN FEET

CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS	
FILL PLACEMENT	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by J. A. JIMMIE	Checked by
Drawn by F. J. WILSON	Reviewed by
Typed by	MA-367 P
Checked by J. F. FLEMING	



247

B-7

# CONSTRUCTION NOTES

1. ASBESTOS CEMENT PIPE SHALL CONFORM TO SPECIFICATION 545 AND SHALL BE 4" DIA. CLASS 4000
2. WHEN PERFORATED ASBESTOS CEMENT PIPE IS REQUIRED, THE ASBESTOS CEMENT PIPE SHALL BE PERFORATED WITH 1/4" HOLES. THE LOCATION AND NUMBER OF THESE HOLES SHALL BE SIMILAR TO THOSE IN ASBESTOS CEMENT UNDERDRAIN PIPE OF THE SAME DIAMETER.
3. THE EXCAVATION LIMITS ARE APPROXIMATE AND WILL BE ADJUSTED BY THE ENGINEER IN ACCORDANCE WITH THE CONDITIONS ENCOUNTERED.
4. THE DEPTH OF THE DRAIN TRENCH MAY BE INCREASED IN SOME AREAS IF UNSUITABLE OR PERVIOUS MATERIALS ARE ENCOUNTERED AS DIRECTED BY THE ENGINEER

3/8" DIA BOLTS  
w/ NUT & WASHER  
8" LONG



102

**SMALL ANIMAL GUARD DETAILS**  
NOT TO SCALE

**SECTION X-X**  
NOT TO SCALE

DRAIN FILL REQUIREMENTS	
SIEVE NO	% PASSING
3/4"	100%
1/2"	90-100
3/8"	40-75
#4	5-25
#8	0-10
#16	0-5

**FOUNDATION DRAIN DETAILS**


**TYPICAL SECTION**  
(18'4" L - 88' L)  
(18'4" H - 88' H)  
NOT TO SCALE

**TYPICAL SECTION**  
(18'4" L - 88' L)  
(18'4" H - 88' H)  
NOT TO SCALE

**CLAM RIVER WATERSHED PROJECT**  
**CLAM LAKE MULTIPLE-PURPOSE DAM**  
**SANDSFIELD, MASSACHUSETTS**  
**FOUNDATION DRAIN DETAILS**  
**U.S. DEPARTMENT OF AGRICULTURE**  
**SOIL CONSERVATION SERVICE**

Designed by J. A. TIBBETTS  
Drawn by F. J. WILDA  
Checked by J. P. POLAN  
Date 10/71  
Scale 1" = 10'-0"

Sheet No. 9 of 26  
Drawing No. MA-397 P



DETAIL OF BERM SLOPES @ RISER  
NOT TO SCALE

PLAN

SCALE IN FEET

48" PIPE DATA


48" REINFORCED CONCRETE WATER PIPE	
(2) 4.0' SECTIONS	8.0'
(2) 8.0' SECTIONS	16.0'
(16) 16.0' SECTIONS	256.0'
TOTAL = 280.0'	

PRESSURE HEAD = 73.7  
LOAD = 50,330 LBS PER LINEAR FOOT BASED ON OUTSIDE DIAMETER OF 60"  
MINIMUM 3-EDGE BEARING STRENGTH FOR 0.001" CRACK (PRESTRESSED) EQUALS 18,920 LBS PER LINEAR FOOT (AWWA C-301).  
MINIMUM 3-EDGE BEARING STRENGTH FOR 0.01" CRACK (NON-PRESTRESSED) EQUALS 25,163 LBS PER LINEAR FOOT (AWWA C-300).

48" PIPE JOINTS		
JOINT	4 DISTANCE FROM INLET	INVERT ELEVATION
INLET	0	1100.0
JA	16	1099.73
JB	32	1099.47
JC	48	1099.20
JD	64	1098.93
JE	80	1098.67
JF	96	1098.40
JG	104	1098.27
JH	112	1098.13
JI	116	1098.07
OUTLET	120	1098.00

PIPE SUPPLIER'S NOTE:

CAST INSIDE OF BELL RING JOINT WITH CONCRETE ON ONE (16) PIPE SECTION. THE O.D. OF PIPE ASSUMED IN DESIGN IS 60" WHERE THE PIPE FURNISHED HAS AN O.D. GREATER THAN ASSUMED IN DESIGN, THE THREE-EDGED BEARING STRENGTH OF THE PIPE FURNISHED MUST NOT BE LESS THAN THE SPECIFIED THREE-EDGED BEARING STRENGTH MULTIPLIED BY THE RATIO OF THE O.D. OF THE PIPE FURNISHED TO THE O.D. ASSUMED IN DESIGN.




PROFILE

SCALE IN FEET

4 DIMENSIONS OF CONCRETE PIPE LENGTHS ARE BASED ON NOMINAL LENGTHS AND DO NOT INCLUDE CREEP.

1072



COLLAR	DISTANCE FROM TRANSITION WALL	INVERT OF PIPE
I	12.33	1096.65
II	36.33	1095.96
III	60.33	1095.27
IV	84.33	1094.58
V	108.33	1093.88
VI	132.33	1093.19
VII	156.33	1092.50
VIII	180.33	1091.81
IX	204.33	1091.12

JOINT	DISTANCE FROM TRANSITION WALL	INVERT ELEVATION
J1	0.33	1097.00
J2	8.33	1096.77
J3	24.33	1096.31
J4	40.33	1095.85
J5	56.33	1095.38
J6	72.33	1094.92
J7	88.33	1094.46
J8	104.33	1094.00
J9	120.33	1093.54
J10	136.33	1093.08
J11	152.33	1092.62
J12	168.33	1092.15
J13	184.33	1091.69
J14	200.33	1091.23
J15	216.33	1090.77
J16	232.33	1090.31
J17	248.33	1089.85
J18	264.33	1089.38
J19	280.33	1088.92
J20	296.33	1088.46
OUTLET	312.33	1088.00


### 60" PIPE DATA

60" REINFORCED CONCRETE WATER PIPE  
 (1) 8.0' SECTION 8.0'  
 (19) 16.0' SECTIONS 304.0'  
 (1) WALL FITTING  
 TOTAL: 312.0'

PRESSURE HEAD = 83.2  
 LOAD = 164,742 LBS PER LINEAR FOOT BASED ON OUTSIDE DIAMETER OF 80"  
 MINIMUM 3-EDGE BEARING STRENGTH FOR 0.001" CRACK (PRESTRESSED) EQUALS 37,872 LBS PER LINEAR FOOT (AWWA C-301)  
 MINIMUM 3-EDGE BEARING STRENGTH FOR 0.01" CRACK (NON-PRESTRESSED) EQUALS 50,369 LBS PER LINEAR FOOT (AWWA C-300)

### PIPE SUPPLIER'S NOTE

CAST OUTSIDE OF SPIGOT JOINT RING WITH CONCRETE ON ONE PIPE SECTION  
 THE O.D. OF PIPE ASSUMED IN DESIGN IS 80". WHERE THE PIPE FURNISHED HAS AN O.D. GREATER THAN ASSUMED IN DESIGN, THE THREE EDGED BEARING STRENGTH OF THE PIPE FURNISHED MUST NOT BE LESS THAN THE SPECIFIED THREE EDGED BEARING STRENGTH MULTIPLIED BY THE RATIO OF THE O.D. OF THE PIPE FURNISHED TO THE O.D. ASSUMED IN DESIGN.



CLAM RIVER WATERWAYS PROJECT  
 CLAM LAKE MULTIPLE-PURPOSE DAM  
 SANDSFIELD, MASSACHUSETTS


PRINCIPAL SPILLWAY

U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

Designed by J. A. TIBBETTS	Scale 1/4" = 1'	Approved by
Drawn by P. A. WILSON	Date 1-20-55	Title
Checked by S. H. BRADY	Date	Project No. MA-387 P

202

89




**PRINCIPAL SPILLWAY WITH CRADLE  
IN AREAS REQUIRING ROCK EXCAVATION**

NOT TO SCALE

WHEN ROCK EXISTS ABOVE THE CENTERLINE OF THE PIPE, THE BEDDING SHALL EXTEND TO THE ROCK LINE BUT SHALL NOT BE HIGHER ABOVE CENTERLINE.

PAY LINE FOR EX AND CONCRE


PR  
IN 1



**PRINCIPAL SPILLWAY WITH CRADLE  
IN AREAS NOT REQUIRING ROCK EXCAVATION**


NOT TO SCALE

PR  
IN AR




**DETAIL OF RISER BASE**

NOT TO SCALE



**PRINCIPAL SPILLWAY WITH BEDDING  
IN AREAS REQUIRING ROCK EXCAVATION**  
NOT TO SCALE




**PRINCIPAL SPILLWAY WITH BEDDING  
IN AREAS NOT REQUIRING ROCK EXCAVATION**  
NOT TO SCALE


CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDISFIELD, MASSACHUSETTS	
PRINCIPAL SPILLWAY DETAILS	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
By: J. A. TIBBETTS	Date: 12/71
By: P. A. BULLER	Date: 12-71
By: J. E. FOLAN	Date: 1-72
Checked: J. E. FOLAN	Date: 1-72
Approved: MA-387 P	

202


B-10









2072




PLAN - TOP SLAB





SECTION AA




UPSTREAM ELEVATION




SECTION @ CENTERLINE



SECT. A




SECT. B



SECT. C



CONSTR. JOINT.



DOWNSTREAM ELEVATION

1/4" x 6" Carbon steel plate to conform to Spec. 441 Continuous thru constr. joint.  
Splices shall be either  
1. Butt welded  
2. Lapped 3" & bolted  
3. Lapped 3" & fillet welded.




PLATE  
CONSTR. JOINT

CONSTR. NOTES:

1/4" x 6" steel plate at the constr. joint shall be butt welded to the steel cylinder of the wall fittings & wall thimble.

0 1 2 3 4 5 6 ft  
Scale

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

RISER DETAILS

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Project: Clam Lake Multiple-Purpose Dam	Date: 12/1/57
Drawn: H. T. Brown, Jr.	Checked: H. T. Brown, Jr.
Scale: 1" = 10'	Sheet: NA-387 P

NE

292

B-14





CONSTRUCTION NOTES

- 1 Material in reservoir drain trash rack shall conform to Spec 581 for structural steel
- 2 Trash rack to be galvanized in accordance with Spec 582

NOTE

For construction details see sheet 10



BAR TYPES

BILL OF MATERIAL  
RESERVOIR DRAIN TRASH RACK


ITEM	SIZE	LENGTH	QUANTITY
Angle (1)	1/2" x 1/2" x 1/4"	6'-9"	3
Anchor Bolt	1/2" dia	2'-0"	6

RESERVOIR DRAIN STEEL SCHEDULE


MARK	QUAN	SIZE	LENGTH	TYPE	B	C	D	TOTAL LENGTH
1	6	4	6'-9"	21	4-7-2-3			40.50
2	6	4	10'-3"	19	7-0-3-3	2-10		61.50
3	4	4	2'-9"	1				11.00
4	2	4	3'-0"	1				6.00
5	4	4	3'-6"	1				14.00
6	2	4	3'-9"	1				7.50
7	2	4	4'-3"	1				8.50
8	2	4	4'-9"	1				9.50
10	6	4	6'-9"	21	3-4-3-3			40.50
11	2	4	7'-6"	21	4-3-3-3			15.00
12	2	4	7'-9"	21	4-6-3-3			15.50
13	2	4	8'-3"	21	5-0-3-3			16.50
14	2	4	10'-3"	19	5-3-3-3	2-6		20.50
15	2	4	8'-3"	19	3-3-3-3	2-6		16.50
16	2	4	5'-9"	19	0-9-3-3	2-6		11.50
17	2	4	3'-3"	1				6.00
18	2	4	1'-0"	1				2.00
19	2	4	12'-3"	19	7-3-3-3	2-6		24.50

QUANTITIES (this sheet only)

STEEL  
No 4 Bar 327.50 Ft = 218.77 lbs  
CONCRETE (Class 4000)  
Conduit I.D. 48" 3.0 Cu Yds




TRASH RACK



ANCHOR BOLT

ASTM A-276, 1/2" dia, Class 302 or 303,  
With Type-2 nuts and washers



ISOMETRIC

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

RESERVOIR DRAIN INLET DETAILS


U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Designed J A TIBBETTS	Date 1/77	Approved By
Checked F J WILDA	1-28-77	1-28-77
Drawn by	1-28-77	1-28-77
1-28-77	1-28-77	1-28-77


MA-357 P

29.2


B-13





ISOMETRIC VIEW




STOP LOG RETAINER  
NOT TO SCALE




STOP LOG DETAIL  
NOT TO SCALE




CONCRETE BEDDING  
(48\"/>



REINFORCED CONCRETE WATER PIPE JOINT



PLAN




FRONT ELEVATION

SUGGESTED SUPPORT BLOCK

NOTE: The Contractor shall determine the number and size of the blocks



192



**ANCHOR BOLT**

Stainless Steel (Class 303, 303 Se  
or 304, Condition A)  
Supply with washers and Type 2 nuts

LOG SHALL BE  
4" x 4" x 4-7"  
(3 REQ'D)



**BELL RING FITTING**

Support Block  
(Precast)

Subgrade

Footings

ON

K

CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS			
STOP LOG & RESERVOIR DRAIN INLET DETAILS			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Project: J.A. THURMOND	Date: 8/71	Approved by: _____	MA-387 P
Drawn: P.J. WILSON	Date: 8-71	Check: _____	
Checked: C.H. POORE	Date: 8-71	Scale: _____	

282

B-14



REPRODUCED AT GOVERNMENT EXPENSE

LOG OF TEST HOLE

DN-1, ELEV. 1212.0 6/8/65 D.E.H.  
 0.0 1.5 TOPSOIL  
 1.5 42.0 SAND, with gravel, about 10% fines, 15% fine sand, 30% medium sand, 30% coarse sand, 15% gravel, 8% cobbles, 2% boulders, angular to sub-rounded, maximum size 14", tan-brown, damp, high permeability, dense, some terraces.  
 42.0 59.0 SAND, silty with gravel, about 20% fines, 20% fine sand, 25% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, maximum size 6", olive-brown, damp, low permeability, to impermeable, dense to very dense, glacial till.  
 59.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	84
2.	1.5 - 3.0	115/6	50
3.	10.0 - 11.5	31	33

NOTE: Water level at 4.5 feet on 6/15/65. Hole dry at 28 feet on 6/16/65. Casing 28 feet. Hole at 29 feet on 6/15/65. Hole dry at 40 feet on 6/21/65. Pipe to 40 feet. Could not get tape below 55 feet on 7/16/65.

DN-2, ELEV. 1154.0 6/22/65 K.G.L.  
 0.0 7.0 TOPSOIL  
 7.0 16.5 SAND, silty with gravel, about 18% fines, 32% fine sand, 25% medium sand, 15% coarse sand, 10% gravel, angular, hard, maximum size 3", brown, damp, to moist at 4.0, low permeability, dense to very dense, glacial till.  
 16.5 52.0 SAND, silty with gravel, about 30% fines, 35% fine sand, 15% medium sand, 5% coarse sand, 10% gravel, 5% cobbles, angular, hard, maximum size 8", olive-brown, damp, impermeable, very dense, glacial till.  
 52.0 59.0 BEDROCK, hard, unweathered Pre-Cambrian Gneiss, fractures mostly horizontal, spaced 18 to 30 inches apart, foliation dipping about 45 degrees.  
 59.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	37	67
2.	1.5 - 3.0	84	56
3.	3.0 - 4.5	63	78
4.	4.5 - 6.0	22	56
5.	12.0 - 13.0	160/8	67
6.	22.0 - 23.0	172	88
7.	27.0 - 28.5	180	77
8.	32.0 - 33.0	323/9	100
9.	42.0 - 42.5	200/7	94
10.	47.5 - 48.5	903/10	100

Rock Core

No.	Depth	% Recovery
1.	52.0 - 54.0	100
2.	54.0 - 59.0	100

NOTE: Water level at 3 feet on 6/24/65, water level at 13 feet on 7/16/65.

DN-3, ELEV. 1124.8 6/18-21/65 K.G.L.  
 0.0 1.5 TOPSOIL  
 1.5 13.0 SAND, silty with gravel, about 18% fines, 25% fine sand, 10% medium sand, 15% coarse sand, 32% gravel, angular, hard, with some decomposed schist fragments, damp, low permeability, dense to very dense, colluvium.  
 13.0 23.0 SAND, silty with gravel, about 20% fines, 15% fine sand, 25% medium sand, 10% coarse sand, 15% gravel, 5% cobbles, 10% boulders, angular, hard, maximum size 12", gray, damp, impermeable, very dense, glacial till.  
 23.0 39.0 BEDROCK, gray, hard, quartz, biotite, feldspar gneiss, foliation dipping about 45 degrees, moderately to badly fractured, fractures spaced 1 to 8 inches, nearly horizontal and dipping about 45 degrees.  
 39.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	18	78
2.	1.5 - 3.0	50	89
3.	3.0 - 4.0	100/3	67
4.	10.0 - 11.5	84	45
5.	16.5 - 17.0	100/3	95

Rock Core

No.	Depth	% Recovery
1.	23.0 - 24.0	100
2.	24.0 - 29.0	100
3.	29.0 - 34.0	100
4.	34.0 - 39.0	100

Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	23.5 - 34.0	3 inches	25	18.3
2.	28.0 - 34.0	3 inches	25	15.3
3.	35.0 - 39.0	3 inches	25	.02

NOTE: Water level at 20.5 feet on 7/14/65, Hole dry to 16 feet on 6/21/65. Lost drilling water at 27.0 feet.

DN-4, ELEV. 1101.8

0.0 2.0 TOPSOIL  
 2.0 16.0 BEDROCK, hard, unweathered, gray gneiss, containing much quartz and biotite, fracturing mostly horizontal, some dipping about 60 degrees, foliation dipping about 45 degrees.  
 16.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	4	67
2.	1.5 - 2.1	104/7	100

Rock Core

No.	Depth	% Recovery
1.	2.0 - 4.0	88
2.	6.0 - 8.5	100
3.	8.5 - 13.0	100
4.	13.0 - 16.0	94

Pressure Test

No.	Depth	Psi	Q/gpm
1.	6.5 - 16.0	25	15

NOTE: Water level at 2 feet on 7/15/65.

DN-5, ELEV. 1089.7

0.0 7.0 TOPSOIL  
 7.0 17.0 BEDROCK, and cobbles with gravel and sand, angular, hard, maximum size 14", high permeability, alluvium.  
 17.0 BEDROCK, gray, hard, quartz, biotite, feldspar gneiss, foliation dipping about 60 degrees. Joints nearly horizontal and dipping about 45 degrees, spaced 1 to 30 inches.  
 Bottom of Hole.

Rock Core

No.	Depth	% Recovery
1.	7.0 - 8.0	100
2.	8.0 - 13.0	100
3.	13.0 - 17.0	100

Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	8.0 - 17.0	3 inches	25	14.4
2.	12.0 - 17.0	3 inches	25	0.88

NOTE: Water level at 0.3 feet on 7/15/65.

DN-6, ELEV. 1090.2

0.0 1.5 TOPSOIL and BOULDERS  
 1.5 9.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 30% coarse sand, 7% gravel, 7% cobbles, 1% boulders, angular to sub-rounded, maximum size 14", tan-brown, wet, low to medium permeability, dense, valley fill.  
 9.0 23.0 BEDROCK, hard, gray, biotite gneiss, unweathered, with fractures mostly horizontal and tight but some dipping about 60 degrees, fractures spaced 10 to 18 inches apart, foliation dipping about 45 degrees.  
 23.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	1.5 - 3.0	36	77
2.	3.0 - 4.5	59	0
3.	7.0 - 8.5	33	64

Rock Core

No.	Depth	% Recovery
1.	9.0 - 12.0	100
2.	12.0 - 13.0	10
3.	13.0 - 18.0	100
4.	18.0 - 23.0	100

Pressure Test

No.	Depth	Psi	Q/gpm
1.	10.0 - 23.0	25	5

NOTE: Water level at 0.5 feet on 7/15/65.

1082

REPRODUCED AT GOVERNMENT EXPENSE

Lat. $\phi$	Long.	Locality	Date	Collector
0.0	1.5	TURBULL and RUFF		
1.5	12.0	Red, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 15% coarse sand, 15% gravel, 7% cobbles, 3% boulders, soft, highly weathered, maximum size 16", tan-brown, damp, low permeability to impervious, dense to very dense, plasticity 15%.		
12.0	22.0	BEDROCK, dark gray, brittle, hard, fractures to 30 inches, mostly horizontal, foliation dipping about 40 degrees.		
22.0		Region of Nels.		

### Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	5	33
2.	1.5 - 3.0	23	77
3.	3.0 - 4.5	35	77

### Rock Core

No.	Depth	% Recovery
1.	12.0 -14.0	90
2.	14.0 -19.0	100
3.	19.0 -22.0	96

### Pressure Test

No.	Depth	Pat	Q/RP
1	13.0 - 22.0	25	trace

NOTE: Water level at 7 feet on 7/14/65.

DN-B	ELEV.	1124.3	6/15/65	D.E.M.
0.0	1.5	TOP OF OIL		
1.3	5.0	SAND, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 15% coarse sand, 15% gravel, 7% cobbles, 3% boulders, soft and weathered, maximum size 10", tan-brown, damp, low to medium permeability, dense to very dense, glacial till.		SH
5.0	18.0	BEDROCK, hard, dark gray biotite gneiss, fractures mostly horizontal, some dipping about 60 degrees, spaced 8 to 20 inches apart, foliation dipping about 80 degrees.		
18.0		Bottom of Hole.		

### Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	44
2.	1.5 - 3.0	28	777
3.	3.0 - 4.5	128/12	55

### Rock Core

No.	Depth	% Recovery
1.	5.0 - 9.0	100
2.	9.0 - 14.0	81
3.	14.0 - 18.0	70

### Pressure Test

No.	Depth	Psi	Q/gpm
1.	7.0 - 12.0	20	pecker failed
2.	12.0 - 18.0	20	10

NOTE: Water level-no measurement. Packers stuck in hole.

D.W. #	ELEV.	DATE	DESCRIPTION
0.0	12.0	6/16/65	D.E.M. BOULDERS, with silty sand matrix, about 31 fines, 7% fine sand, 3% medium sand, 3% coarse sand, 80% boulders, angular to sub-angular, hard, unweathered, maximum size 24", gray, damp, high permeability, dense, slope wash and residual.
12.0	30.0		BEDROCK, hard, dark gray, biotite gneiss, moderately weathered at top 2 feet, with separation of foliation planes, fractures mostly horizontal, some dipping about 60 degrees, spaced 10 to 20 inches apart. Foliation dipping about 80 degrees.
10.0			Bottom of Hole.

### Rock Core

No.	Depth	% Recovery
1.	11.0 - 12.0	100
2.	12.0 - 17.0	100
3.	17.0 - 22.0	80
4.	22.0 - 25.0	83
5.	25.0 - 30.0	100

### Pressure Test

No.	Depth	Fat	W/asm
1	16.0 - 30.0	25	0

NOTE: Water level at 2.5 feet on 7/14/65.

Centerline of dam  
Borrow Area  
Emergency Spillway  
Centerline of Outlet Structure  
Stream Channel  
Relief Wells

1 -99  
101-199  
201-299  
301-399  
401-499  
501-599  
601-699  
701-799

DN-Drill Holes  
TP-Test Pits

### UNIFIED SOIL CLASSIFICATION SYSTEM SYMBOLS

CV	Well graded gravel; gravel-sand mixtures
CP	Poorly graded gravel
GM	Silty gravel; gravel-and-silt mixtures
GC	Clayey gravel; gravel-and-clay-mixtures
SW	Well graded sands; sand-gravel mixtures
SP	Poorly graded sands
SM	Silty sands; sand-silt mixtures
SC	Clayey sands; sand-clay mixtures
ML	Silts; silty, very fine sands; sandy or clayey silts
CL	Clays of low to medium plasticity; silty, sandy or gravelly clays
CH	Clays of high plasticity; fat clays
MH	Elastic silts; micaceous or diatomaceous silts
OL	Organic silts and organic silty clays of low plasticity
OH	Organic clays or silts of medium to high plasticity

All Soil and Rock description and classifications were determined by visual examination in the field.

When possible, all holes were advanced by continuous drive sampling to 6.0 feet. Holes were then advanced by MX diamond drilling between drive samples. Drive samples taken with a 3-inch O.D. split spoon sampler.

**Location of Test Holes shown on Plan View**

NOTE: Water levels do not necessarily represent static water levels.

Psi = pounds per square inch water pressure  
 G/gpm = quantity of water in gallons per minute  
 K/ft/day = permeability in feet per day  
 D.S. = Disturbed Sample

The Unified Soil Classification System classifies only those materials which are smaller than three inches.

CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS		
LOGS OF TEST HOLES		
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE		
Investigator Georgann D. MILLER & J. L. LAMB	Date 1968	Approved by
Drawn		Title
Traced		Time
Checked	3-1-68	Sheet No. 30 of 30
		MA-357 P

SCS-313B (APRIL 1963)

202

**B-15**

# REPRODUCED AT GOVERNMENT EXPENSE

LOG OF TEST HOLE

DM-10, ELEV. 1138.0 5/17-18/63 R.G.L.  
 0.0 16.0 TOPSOIL  
 SAND, silty with gravel, about 16% fines, 32% fine sand, 25% medium sand, 15% coarse sand, 7% gravel, 1% cobbles, 1% boulders, angular, hard, maximum size 16", olive-brown, damp, low permeability, dense, slope wash.  
 10.0 20.0 BEDROCK, gray, hard, quartz, biotite foliation dipping about 45 degrees, joints spaced 1/2 to 16 inches dipping about 30 degrees.  
 20.0 Bottom of Hole.

## Rock Core

No.	Depth	% Recovery
1.	10.0 - 12.0	100
2.	12.0 - 15.0	100
3.	15.0 - 17.0	100
4.	17.0 - 20.0	100

## Pressure Test

No.	Depth	Hole Size	Pat	Q/psf
1.	12.0 - 20.0	3 inches	25	14.8
2.	16.5 - 20.0	3 inches	25	4.20

NOTE: Water level at 11 feet on 7/14/63

DM-101, ELEV. 1214.2 6/18-24/63 D.E.M.  
 0.0 1.5 TOPSOIL  
 1.5 40.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, soft, maximum size 4", olive-brown, damp, low permeability, dense to very dense, glacial till.  
 40.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	17	77
2.	1.5 - 3.0	15	88
3.	3.0 - 4.5	212	83
4.	4.5 - 5.2	196/8	33
5.	10.0 - 11.5	176	68
6.	15.0 - 16.5	176	50
7.	20.0 - 20.1	100/1	0
8.	30.0 - 30.9	198/9	10
9.	35.0 - 36.5	154	61
10.	38.5 - 40.0	276	33

NOTE: Water level at 25 feet on 6/24/63, water level at 13.5 feet on 7/14/63. Boulders from 35.0-38.5 feet.

DM-102, ELEV. 1160.0 6/21-24/63 D.E.M.  
 0.0 1.5 TOPSOIL and DUFF  
 1.5 30.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, maximum size 24", olive-brown, damp, low permeability to impermeable, very dense, glacial till.  
 30.0 40.0 BEDROCK, gray biotite gneiss, hard, fractures spaced 8 to 18 inches apart, mostly horizontal, some dipping about 70 degrees, foliation dipping about 70 degrees.  
 40.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	71	72
2.	1.5 - 3.0	145	67
3.	3.0 - 4.5	71	77
4.	4.5 - 6.0	74	94
5.	10.0 - 11.5	33	77
6.	15.0 - 16.5	697	94
7.	20.0 - 21.5	683	88

## Rock Core

No.	Depth	% Recovery
1.	30.0 - 34.0	100
2.	34.0 - 40.0	100

NOTE: Water level at 7 feet on 6/23/63, water level at 8 feet on 6/24/63, water level at 7.5 feet on 7/14/63.

DM-201, ELEV. 1181.3 6/23-24/63 D.E.M.  
 0.0 1.5 TOPSOIL  
 1.5 10.0 SAND, silty with gravel, about 16% fines, 32% fine sand, 25% medium sand, 15% coarse sand, 7% gravel, 1% cobbles, 1% boulders, angular, hard, maximum size 16", olive-brown, damp, low permeability, dense, slope wash.  
 10.0 42.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, hard, angular, to sub-angular, maximum size 8", olive-brown, damp, impermeable, very dense, glacial till.  
 42.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	67
2.	1.5 - 3.0	26	77
3.	3.0 - 4.5	38	77
4.	4.5 - 6.0	50	44
5.	10.0 - 11.5	48	44
6.	15.0 - 16.5	44	39
7.	20.0 - 21.5	39	8
8.	25.0 - 26.5	96	55
9.	30.0 - 31.5	73	34
10.	35.0 - 36.5	61	34

NOTE: Water level at 3 feet on 6/24/63, water level at 18.5 feet on 7/14/63.

DM-202, ELEV. 1182.3 6/23-24/63 K.G.L.  
 0.0 4.0 TOPSOIL  
 4.0 14.0 SAND, silty with gravel, about 15% fines, 20% fine sand, 25% medium sand, 20% coarse sand, 15% gravel, 5% cobbles, angular, hard, maximum size 6", olive-brown, damp, low permeability to impermeable, medium to dense, some terraces.  
 12.0 42.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, hard, angular, maximum size 18", olive-brown, damp, impermeable, very dense, glacial till.  
 42.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	2	78
2.	1.5 - 3.0	4	78
3.	3.0 - 4.5	4	78
4.	4.5 - 6.0	5	78
5.	10.0 - 11.5	29	78
6.	15.0 - 16.5	130/8	67
7.	20.0 - 21.5	96	77
8.	25.0 - 26.5	110	100
9.	30.0 - 31.5	131	67
10.	35.0 - 36.5	116	77
11.	40.5 - 42.0	163	34

NOTE: Water level at 13 feet on 7/14/63

DM-203, ELEV. 1163.1 6/24/63 D.E.M.  
 0.0 1.5 TOPSOIL  
 1.5 41.5 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 10% gravel, 7% cobbles, 3% boulders, angular, hard, maximum size 16", brown, damp, low to medium permeability, loose to very dense.  
 41.5 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	88
2.	1.5 - 3.0	2	67
3.	3.0 - 4.5	6	67
4.	4.5 - 6.0	8	88
5.	15.0 - 16.5	16	73
6.	20.0 - 21.5	36	77
7.	25.0 - 26.5	42	50
8.	30.0 - 31.5	34	77
9.	35.0 - 36.5	101	44
10.	40.0 - 41.5	137	77

NOTE: Water level at 15 feet on 7/14/63.

1072

DN-301, ELEV. 1095.0 6/21-22/65 K.G.L.  
0.0 7.0 GRAVEL, CUBBLES and Boulders in a silty sand matrix, angular to hard, maximum size 16", medium to high permeability, alluvium.  
SH 7.0 17.0 BEDROCK, quartz biotite feldspar gneiss, moderately hard from 7 to 12 then hard, sandy from 7 to 12, foliation dipping about 80 degrees. Joints horizontal spaced 1 to 24 inches, with a 6" weathered seam at 11 feet.  
SH 17.0 Bottom of Hole.

Rock Core

No.	Depth	% Recovery
1.	7.0 - 12.0	60
2.	12.0 - 17.0	100

Rock Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	7.2 - 17.0	3 inches	12	11.7
2.	Could not place pecker below 11.0 feet.			

NOTE: Water level at 3.5 feet on 7/14/65.

DN-302, ELEV. 1091.8 6/21/65 K.G.L.  
0.0 8.0 GRAVEL, CORNERS and BOULDERS with silty sand matrix, angular, hard, maximum size 16", medium to high permeability, alluvium.  
SH 8.0 18.0 BEDROCK, dark gray, biotite quartz, feldspar gneiss, moderately hard to hard below 11.0 feet, foliation dipping about 85 degrees, fractures spaced 1 to 18 inches generally horizontal with a few dipping about 30 degrees.  
SH 18.0 Bottom of Hole.

Rock Core

No.	Depth	% Recovery
1.	8.0 - 9.5	88
2.	9.0 - 11.5	100
3.	11.0 - 16.0	88
4.	16.0 - 18.0	100

Rock Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	9.5 - 18.0	3 inches	25	3.7

NOTE: Water level at surface on 7/14/65

DN-303, ELEV. 1098.7 6/15-16/65 D.E.M.  
0.0 9.0 SAND, silty with gravel, about 15% fines, 15% SH fine sand, 30% medium sand, 25% coarse sand, 10% gravel, 4% cobbles, 1" boulders, angular to sub-angular, hard, maximum size 18 inches, tan-brown, wet, high permeability, very dense.  
SH 9.0 19.0 BEDROCK, hard, gray biotite gneiss, fractures nearly horizontal some dipping 60 degrees, spaced 8 to 20 inches apart, foliation dipping about 80 degrees.  
SH 19.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	220/8	33
2.	6.0 - 7.5	141	55

Rock Core

No.	Depth	% Recovery
1.	9.0 - 14.5	100
2.	14.0 - 19.0	100

Pressure Test

No.	Depth	Psi	Q/gpm
1.	9.5 - 19.0	25	23
2.	14.0 - 19.0	25	0

NOTE: Water level at surface on 7/14/65

DN-304, ELEV. 1090.6 6/11/65 D.E.M.  
0.0 1.5 TOPSOIL and DUFF  
SH 1.5 13.0 SAND, silty with gravel, about 18% fines, 22% fine sand, 40% medium sand, 10% coarse sand, 10% gravel, angular to sub-rounded, maximum size 1", tan-brown, low to medium permeability, wet, firm to very dense, valley fill.  
SH 13.0 23.0 BEDROCK, firm, dark, gray biotite gneiss, with quartz stringers, fractures nearly horizontal, spaced 8 to 20 inches apart, foliation dipping about 80 degrees.  
SH 23.0 Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	4	77
2.	1.5 - 3.0	34	67
3.	3.0 - 4.5	34	67
4.	5.0 - 6.5	152	72

Rock Core

No.	Depth	% Recovery
1.	13.0 - 14.0	85
2.	14.0 - 15.0	100
3.	15.0 - 20.0	85
4.	20.0 - 23.0	100

Pressure Test

No.	Depth	Psi	Q/gpm
1.	14.0 - 19.0	25	18
2.	19.0 - 23.0	25	trace

NOTE: Water level at 6 feet on 6/14/65, at 3 feet on 7/14/65

TP-131, ELEV. 1184.7 6/24/65 K.G.L.  
0.0 7.0 TOPSOIL  
SH 7.0 10.0 GRAVEL, sandy with silt, cobbles and boulders about 15% fines, 10% fine sand, 10% medium sand, 10% coarse sand, 30% gravel, 17% cobbles, 8% boulders, angular, hard, maximum size 18", brown, damp, low permeability, very dense, ground moraine. Bottom of Pit.  
SH 10.0 D.S. 151.1 2.0 to 10.0 (2 bags), 15% larger than 6" discarded.

NOTE: Water level-no pipe.

TP-132, ELEV. 1160.0 6/24/65 K.G.L.  
0.0 3.0 TOPSOIL  
SH 3.0 10.0 SAND, silty with gravel, about 30% fines, 35% fine sand, 17% medium sand, 3% coarse sand, 10% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 16", olive-brown, damp to moist, low permeability, dense, glacial till. Bottom of Pit.  
SH 10.0 D.S. 152.1 3.0 to 10.0 6% larger than 6" discarded.

NOTE: Seepage at 9.5 feet. Estimated flow less than .5 gpm. Water level dry on 7/14/65.

TP-133, ELEV. 1170.8 6/24/65 K.G.L.  
0.0 5.0 BOULDERS and CORNERS, in an organic silty sand matrix, about 5% fines, 5% fine sand, 5% medium sand, 5% coarse sand, 10% gravel, 20% cobbles, 30% boulders, sub-rounded to angular, maximum size 30", black, wet, high permeability, loose, alluvium.  
SH 5.0 10.0 SAND, silty with gravel, about 18% fines, 22% fine sand, 10% medium sand, 5% coarse sand, 3% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 14", gray, moist, impermeable, very dense, glacial till. Bottom of Pit.  
SH 10.0 D.S. 153.1, 5.0-10.0 6% larger than 6" discarded.

NOTE: Water entering pit at 3.0. Estimated flow 1.5 gpm. Water level at 5 feet on 7/14/65.

TP-134, ELEV. 1208.7 6/24/65 K.G.L.  
0.0 2.5 BOULDER TOPSOIL  
SH 2.5 10.0 SAND, silty with gravel, about 15% fines, 35% fine sand, 15% medium sand, 5% coarse sand, 20% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 16", light brown, damp, low, very dense, ground moraine. Bottom of Pit.  
SH 10.0 D.S. 154.1, 2.5-10.0 6% larger than 6" discarded.

NOTE: Water level dry on 7/14/65.

TP-135, ELEV. 1189.6 6/24/65 K.G.L.  
0.0 4.5 BOULDERS and CORNERS, in an organic silty sand matrix, about 5% fines, 2% fine sand, 2% medium sand, 2% coarse sand, 4% gravel, 10% cobbles, 7% boulders, angular to sub-rounded, hard, maximum size 36", black, wet, medium, loose, alluvium.  
SH 4.5 10.0 SAND, silty with gravel, about 18% fines, 25% fine sand, 15% medium sand, 5% coarse sand, 20% gravel, 15% cobbles, 2% boulders, angular to sub-angular, hard, maximum size 14", brown, moist, low permeability, very dense, ground moraine. Bottom of Pit.  
SH 10.0 D.S. 155.1, 4.5-10.0 10% larger than 6" discarded.

NOTE: Water entering pit 1.0-4.5. Estimated flow less than 1 gpm. Water level at 3.5 on 7/14/65

TP-136, ELEV. 1214.1 6/24/65 K.G.L.  
0.0 2.5 TOPSOIL  
SH 2.5 10.0 SAND, silty with gravel, about 15% fines, 25% fine sand, 15% medium sand, 5% coarse sand, 30% gravel, 5% cobbles, 2% boulders, angular, hard, maximum size 17", olive-brown, damp, low permeability, very dense, glacial till. Bottom of Pit.  
SH 10.0 D.S. 156.1, 2.5-10.0 5% larger than 6" discarded.

NOTE: Water level dry on 7/14/65.

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

LOGS OF TEST MOLES

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Investigator D. MILLS & K. LUND	Date (1965)	Approved by Time
Drawn	Time	
Traced	Sheet No.	
Checked D. MILLS	3-1-66	NA 357 P

# REPRODUCED AT GOVERNMENT EXPENSE

CLAN RIVER				Elev. 1212.2				7/29 to 7/31/70				Elev. 1212.2			
IN-61	Elev. 1203.0	7/29 to 8/3/70	PAW/DM	0.0	2.0	TOPSOIL.		0.0	2.0	TOPSOIL.		0.0	2.0	TOPSOIL.	
0.0	7.5	Decomposed boulder, gneiss Tan brown, dry, low permeability, dense, Decomposed Rock		2.0	26.0	SAND, silty with gravel, about 70% fines, 15% fine sand, 15% medium sand, 35% coarse sand, 15% gravel, subangular, SM highly decomposed rock bits, light olive brown, moist, medium permeability, loose, weathered till, to 5 feet olive- brown, wet, low permeability, very dense, GLACIAL TILL.		1.0				1.0			
1.5	9.5	Boulder.													
9.5	30.0	SAND, silty with gravel, about 20% fines, 10% fine sand, 20% medium sand, 35% coarse sand, 15% gravel, subangular, decomposed rock bits, 3/4-inch maximum size, gray, moist, low permeability, very dense, GLACIAL TILL.	SM	26.0	46.5	SAND, silty, about 45% fines, 75% fine sand, 20% medium sand, 75% coarse sand, 3% gravel, olive-gray, moist, low permeability, very dense, Glacial Till.		26.0				26.0			
30.0	32.5	Boulder.		34.0	35.0	Boulder.									
32.5		Bottom of Hole.		46.5		Bottom of Hole.									
Drive Samples				Drive Samples				Drive Samples				Drive Samples			
No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery
1.	0.0-1.5'	54	100	1.	0.0-1.5'	16	67	1.	0.0-1.5'	16	67	1.	0.0-1.5'	16	67
2.	1.5-3.0'	101	78	2.	1.5-3.0'	134	72	2.	1.5-3.0'	134	72	2.	1.5-3.0'	134	72
3.	3.0-4.5'	134	72	3.	3.0-4.5'	134	72	3.	3.0-4.5'	134	72	3.	3.0-4.5'	134	72
4.	4.5-6.0'	134/6" ref.	0	4.	4.5-6.0'	134/6" ref.	0	4.	4.5-6.0'	134/6" ref.	0	4.	4.5-6.0'	134/6" ref.	0
5.	6.0-7.5'	105	67	5.	6.0-7.5'	105	67	5.	6.0-7.5'	105	67	5.	6.0-7.5'	105	67
6.	7.5-9.0'	87	34	6.	7.5-9.0'	87	34	6.	7.5-9.0'	87	34	6.	7.5-9.0'	87	34
7.	9.0-10.5'	100/3" ref.	50	7.	9.0-10.5'	100/3" ref.	50	7.	9.0-10.5'	100/3" ref.	50	7.	9.0-10.5'	100/3" ref.	50
8.	10.5-12.0'	70	50	8.	10.5-12.0'	70	50	8.	10.5-12.0'	70	50	8.	10.5-12.0'	70	50
9.	12.0-13.5'	100/6" ref.	100	9.	12.0-13.5'	100/6" ref.	100	9.	12.0-13.5'	100/6" ref.	100	9.	12.0-13.5'	100/6" ref.	100
NOTE: Water level at 14 feet 8 inches on 8/3/70.				NOTE: Water level at 14 feet 8 inches on 8/3/70.				NOTE: Water level at 14 feet 8 inches on 8/3/70.				NOTE: Water level at 14 feet 8 inches on 8/3/70.			
IN-605 Elev. 1194.9				IN-605 Elev. 1194.9				IN-605 Elev. 1194.9				IN-605 Elev. 1194.9			
8/10 to 8/11/70 DM				8/10 to 8/11/70 DM				8/10 to 8/11/70 DM				8/10 to 8/11/70 DM			
0.0	1.0	TOPSOIL and SILT.		0.0	1.0	TOPSOIL and SILT.		0.0	1.0	TOPSOIL and SILT.		0.0	1.0	TOPSOIL and SILT.	
1.0	12.5	SAND, silty with gravel, about 15% fines, 15% fine sand, 20% medium sand, 40% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.	SM	1.0	12.5	SAND, silty with gravel, about 15% fines, 15% fine sand, 20% medium sand, 40% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.	SM	1.0	12.5	SAND, silty with gravel, about 15% fines, 15% fine sand, 20% medium sand, 40% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.	SM	1.0	12.5	SAND, silty with gravel, about 15% fines, 15% fine sand, 20% medium sand, 40% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.	SM
12.5	41.5	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray-green, damp, low permeability, dense to very dense, GLACIAL TILL.	SM	12.5	41.5	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray-green, damp, low permeability, dense to very dense, GLACIAL TILL.	SM	12.5	41.5	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray-green, damp, low permeability, dense to very dense, GLACIAL TILL.	SM	12.5	41.5	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, gray-green, damp, low permeability, dense to very dense, GLACIAL TILL.	SM
41.5		Bottom of Hole.		41.5		Bottom of Hole.		41.5		Bottom of Hole.		41.5		Bottom of Hole.	
Drive Samples				Drive Samples				Drive Samples				Drive Samples			
No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery
1.	0.0-1.5'	16	100	1.	0.0-1.5'	16	100	1.	0.0-1.5'	16	100	1.	0.0-1.5'	16	100
2.	1.5-3.0'	12	100	2.	1.5-3.0'	12	100	2.	1.5-3.0'	12	100	2.	1.5-3.0'	12	100
3.	3.0-4.5'	100/3" ref.	0	3.	3.0-4.5'	100/3" ref.	0	3.	3.0-4.5'	100/3" ref.	0	3.	3.0-4.5'	100/3" ref.	0
4.	4.5-6.0'	23	70	4.	4.5-6.0'	23	70	4.	4.5-6.0'	23	70	4.	4.5-6.0'	23	70
5.	6.0-7.5'	100/1" ref.	0	5.	6.0-7.5'	100/1" ref.	0	5.	6.0-7.5'	100/1" ref.	0	5.	6.0-7.5'	100/1" ref.	0
6.	7.5-9.0'	103/6" ref.	60	6.	7.5-9.0'	103/6" ref.	60	6.	7.5-9.0'	103/6" ref.	60	6.	7.5-9.0'	103/6" ref.	60
7.	9.0-10.5'	100/6" ref.	40	7.	9.0-10.5'	100/6" ref.	40	7.	9.0-10.5'	100/6" ref.	40	7.	9.0-10.5'	100/6" ref.	40
8.	10.5-12.0'	100/4" ref.	0	8.	10.5-12.0'	100/4" ref.	0	8.	10.5-12.0'	100/4" ref.	0	8.	10.5-12.0'	100/4" ref.	0
9.	12.0-13.5'	137/10"	60	9.	12.0-13.5'	137/10"	60	9.	12.0-13.5'	137/10"	60	9.	12.0-13.5'	137/10"	60
IN-610 Elev. 1199.5				IN-610 Elev. 1199.5				IN-610 Elev. 1199.5				IN-610 Elev. 1199.5			
8/3 to 8/6/70 DM				8/3 to 8/6/70 DM				8/3 to 8/6/70 DM				8/3 to 8/6/70 DM			
0.0	3.0	TOPSOIL and SLOPEWASH.		0.0	3.0	TOPSOIL and SLOPEWASH.		0.0	3.0	TOPSOIL and SLOPEWASH.		0.0	3.0	TOPSOIL and SLOPEWASH.	
3.0	36.5	SAND, silty with gravel, about 20% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 15% gravel, subangular, SM 2-inch maximum size, brown to blue-gray at 6 feet, damp, medium permeability, dense to very dense, GLACIAL TILL with decrease in coarse sand and gravel at 22 feet.	SM	3.0	36.5	SAND, silty with gravel, about 20% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 15% gravel, subangular, SM 2-inch maximum size, brown to blue-gray at 6 feet, damp, medium permeability, dense to very dense, GLACIAL TILL with decrease in coarse sand and gravel at 22 feet.	SM	3.0	36.5	SAND, silty with gravel, about 20% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 15% gravel, subangular, SM 2-inch maximum size, brown to blue-gray at 6 feet, damp, medium permeability, dense to very dense, GLACIAL TILL with decrease in coarse sand and gravel at 22 feet.	SM	3.0	36.5	SAND, silty with gravel, about 20% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 15% gravel, subangular, SM 2-inch maximum size, brown to blue-gray at 6 feet, damp, medium permeability, dense to very dense, GLACIAL TILL with decrease in coarse sand and gravel at 22 feet.	SM
36.5		Bottom of Hole.		36.5		Bottom of Hole.		36.5		Bottom of Hole.		36.5		Bottom of Hole.	
Drive Samples				Drive Samples				Drive Samples				Drive Samples			
No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery
1.	0.0-1.5'	11	100	1.	0.0-1.5'	11	100	1.	0.0-1.5'	11	100	1.	0.0-1.5'	11	100
2.	1.5-3.0'	19	72	2.	1.5-3.0'	19	72	2.	1.5-3.0'	19	72	2.	1.5-3.0'	19	72
3.	3.0-4.5'	36	80	3.	3.0-4.5'	36	80	3.	3.0-4.5'	36	80	3.	3.0-4.5'	36	80
4.	4.5-6.0'	47	70	4.	4.5-6.0'	47	70	4.	4.5-6.0'	47	70	4.	4.5-6.0'	47	70
5.	6.0-7.5'	20	70	5.	6.0-7.5'	20	70	5.	6.0-7.5'	20	70	5.	6.0-7.5'	20	70
6.	7.5-9.0'	22	67	6.	7.5-9.0'	22	67	6.	7.5-9.0'	22	67	6.	7.5-9.0'	22	67
7.	9.0-10.5'	73	90	7.	9.0-10.5'	73	90	7.	9.0-10.5'	73	90	7.	9.0-10.5'	73	90
8.	10.5-12.0'	66	80	8.	10.5-12.0'	66	80	8.	10.5-12.0'	66	80	8.	10.5-12.0'	66	80
9.	12.0-13.5'	59	67	9.	12.0-13.5'	59	67	9.	12.0-13.5'	59	67	9.	12.0-13.5'	59	67
10.	13.5-15.0'	59	100	10.	13.5-15.0'	59	100	10.	13.5-15.0'	59	100	10.	13.5-15.0'	59	100
IN-611 Elev. 1189.9				IN-611 Elev. 1189.9				IN-611 Elev. 1189.9				IN-611 Elev. 1189.9			
8/11 to 8/11/70 DM				8/11 to 8/11/70 DM				8/11 to 8/11/70 DM				8/11 to 8/11/70 DM			
0.0	1.0	TOPSOIL.		0.0	1.0	TOPSOIL.		0.0	1.0	TOPSOIL.		0.0	1.0	TOPSOIL.	
1.0	5.0	SAND, with gravel, about 8% fines, 12% fine sand, 30% medium sand, 40% coarse sand, 10% gravel, subangular, 2-inch SM- maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.		1.0	5.0	SAND, with gravel, about 8% fines, 12% fine sand, 30% medium sand, 40% coarse sand, 10% gravel, subangular, 2-inch SM- maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.		1.0	5.0	SAND, with gravel, about 8% fines, 12% fine sand, 30% medium sand, 40% coarse sand, 10% gravel, subangular, 2-inch SM- maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.		1.0	5.0	SAND, with gravel, about 8% fines, 12% fine sand, 30% medium sand, 40% coarse sand, 10% gravel, subangular, 2-inch SM- maximum size, gray, damp, medium permeability, loose to dense, OUTWASH.	
5.0	30.0	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 1/4-inch SM maximum size, olive to green-gray, damp, low permeability, dense, GLACIAL TILL.	SM	5.0	30.0	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 1/4-inch SM maximum size, olive to green-gray, damp, low permeability, dense, GLACIAL TILL.	SM	5.0	30.0	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 1/4-inch SM maximum size, olive to green-gray, damp, low permeability, dense, GLACIAL TILL.	SM	5.0	30.0	SAND, silty with gravel, about 40% fines, 15% fine sand, 15% medium sand, 20% coarse sand, 10% gravel, subangular, 1/4-inch SM maximum size, olive to green-gray, damp, low permeability, dense, GLACIAL TILL.	SM
30.0		Bottom of Hole.		30.0		Bottom of Hole.		30.0		Bottom of Hole.		30.0		Bottom of Hole.	
Drive Samples				Drive Samples				Drive Samples				Drive Samples			
No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery	No.	Depth	Blows/ft.	% Recovery
1.	0.0-1.5'	14	100	1.	0.0-1.5'	14	100	1.	0.0-1.5'	14	100	1.	0.0-1.5'	14	100
2.	1.5-3.0'	44	70	2.	1.5-3.0'	44	70	2.	1.5-3.0'	44	70	2.	1.5-3.0'	44	70
3.	3.0-4.5'	32	70	3.	3.0-4.5'	32	70	3.	3.0-4.5'	32	70	3.	3.0-4.5'	32	70
4.	4.5-6.0'	72	67	4.	4.5-6.0'	72	67	4.	4.5-6.0'	72	67	4.	4.5-6.0'	72	67
5.	6.0-7.5'	62	67	5.	6.0-7.5'	62	67	5.	6.0-7.5'	62	67	5.	6.0-7.5'	62	67
6.	7.5-9.0'	98	67	6.	7.5-9.0'	98	67	6.	7.5-9.0'	98	67	6.	7.5-9.0'	98	67
7.	9.0-10.5'	96	67	7.	9.0-10.5'	96	67	7.	9.0-10.5'	96	67	7.	9.0-10.5'	96	67

REPRODUCED AT GOVERNMENT EXPENSE

IN 612	Elev. 1181.7	8/6 to 8/10/70	DM																																						
0.0	1.0	TOPSOIL.																																							
1.0	28.0	SAND, silty with gravel, about 45% fines, 10% fine sand, 10% medium sand, 30% coarse sand, 5% gravel, subangular, 1-inch maximum size, olive-brown, damp, low permeability, dense to very dense, GLACIAL TILL.	SM																																						
28.0		Bottom of Hole.																																							
<table><tr><th colspan="2">Drive Samples</th><th rowspan="2">Blows/ft.</th><th rowspan="2">% Recovery</th></tr><tr><th>No.</th><th>Depth</th></tr><tr><td>1.</td><td>0.0 - 1.0'</td><td>2</td><td>100</td></tr><tr><td>2.</td><td>1.5 - 3.0'</td><td>6</td><td>100</td></tr><tr><td>3.</td><td>3.0 - 4.5'</td><td>11</td><td>90</td></tr><tr><td>4.</td><td>4.5 - 6.0'</td><td>22</td><td>90</td></tr><tr><td>5.</td><td>10.0 - 11.5'</td><td>30</td><td>80</td></tr><tr><td>6.</td><td>15.0 - 15.8'</td><td>165/9" ref.</td><td>67</td></tr><tr><td>7.</td><td>20.0 - 20.9'</td><td>174/8" ref.</td><td>70</td></tr><tr><td>8.</td><td>25.0 - 25.5'</td><td>100/6" ref.</td><td>60</td></tr></table>				Drive Samples		Blows/ft.	% Recovery	No.	Depth	1.	0.0 - 1.0'	2	100	2.	1.5 - 3.0'	6	100	3.	3.0 - 4.5'	11	90	4.	4.5 - 6.0'	22	90	5.	10.0 - 11.5'	30	80	6.	15.0 - 15.8'	165/9" ref.	67	7.	20.0 - 20.9'	174/8" ref.	70	8.	25.0 - 25.5'	100/6" ref.	60
Drive Samples		Blows/ft.	% Recovery																																						
No.	Depth																																								
1.	0.0 - 1.0'	2	100																																						
2.	1.5 - 3.0'	6	100																																						
3.	3.0 - 4.5'	11	90																																						
4.	4.5 - 6.0'	22	90																																						
5.	10.0 - 11.5'	30	80																																						
6.	15.0 - 15.8'	165/9" ref.	67																																						
7.	20.0 - 20.9'	174/8" ref.	70																																						
8.	25.0 - 25.5'	100/6" ref.	60																																						

IN-615	Elev. 1183.28	8/3 to 8/10/70	PAB	
0.0	1.0	TOPSOIL.		
1.0	3.0	TOPSOIL.		
3.0	15.0	SAND, silty with gravel, about 25% fines, 15% fine sand, 10% medium sand, 40% coarse sand, 10% gravel, subangular, some particles decomposed, olive-brown, moist, low permeability, very dense, Weathered Till.	SM	
15.0	18.0	SAND, silty with gravel, about 25% fines, 15% fine sand, 10% medium sand, 30% coarse sand, 20% gravel, decomposed rock particles, olive-gray, moist, low permeability, very dense, GLACIAL TILL.	SM	
18.0	29.0	DIORITE, gray, biotite hornblende gneiss, foliations dipping about 70°. From 18 to 21 feet, highly fractured. Fractures spaced about 1/2-inch to 2-inches apart. 21 to 29 feet -- moderately fractured. Fractures spaced about 8 to 14 inches.		
29.0		Bottom of Hole.		
<u>Drive Samples</u>				
No.	Depth	Blows/ft.	% Recovery	
1.	1.0 - 2.4'	98/5" ref.	66	
2.	4.0 - 5.5'	101	66	
3.	10.0 - 11.5'	71	44	
4.	15.0 - 16.5'	131/6" ref.	66	
<u>Rock Core Runs</u>				
No.	Depth	Recovery		
1.	18.0 - 19.0'	50		
2.	19.0 - 20.0'	90		
3.	20.0 - 24.0'	100		
4.	24.0 - 29.0'	90		
<u>Permeability Test</u>				
No.	Depth	Hole Size	Head	Loss
1.	10.5'	2" x 18"	Ground	Slight
e head - pipe above ground				

IN-616	Elev. 1196.03	8/5 to 8/6/70	PAB
0.0	2.0	No drilling - Removed boulders by hand.	
2.0	4.0	TOPSOIL.	
4.0	8.0	SAND, silty with gravel, about 25% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, subangular, some decomposed rock particles, 1 1/2-inch maximum size, olive-brown, moist, low permeability, dense, Weathered Till.	SM
8.0	15.0	SILT, sandy with about 55% fines, 22% fine sand, 15% medium sand, 5% coarse sand, 3% gravel, 1/2-inch maximum size, olive brown, moist, low permeability, medium dense, GLACIAL TILL.	ML
15.0	28.0	SEDROCK, gray biotite hornblende gneiss, foliations dipping about 70°. Fractures are about 12 to 18-inches apart -- mostly horizontal; all tight.	
28.0		Bottom of Hole.	
<u>Drive Samples</u>			
	<u>No.</u>	<u>Depth</u>	<u>Blows/ft.</u>
	1.	2.0 - 3.5'	39
	2.	3.5' - 5.0'	58
	3.	10.0' - 11.5'	29
			<u>% Recovery</u>
			83
			66
			44

IN-617	Elev. 1191.98	8/6 to 8/11/70	PAB
0.0	3.0	TOPSOIL.	
3.0	16.0	SAND, silty with gravel, about 20% fines, 25% fine sand, 25% medium sand, 15% coarse sand, 15% gravel, decomposed rock, 1-inch maximum size, olive-brown, wet, medium permeability, very dense, GLACIAL TILL.	SM
	8.5 to 10.0	BOULDER.	
	14.9 to 16.0	BOULDER.	
16.0	28.0	DIORITE, gray, biotite hornblende gneiss. Foliations dipping about 70°. Moderately fractured -- spaced about 12 to 18 inches apart -- mostly horizontal; all tight.	
28.0		Bottom of Hole.	
<u>Drive Samples</u>			
No.	Depth	Blows/ft.	% Recovery
1.	0.5 - 2.0'	23	78
2.	2.0 - 3.0'	94/8" ref.	33
3.	4.5 - 6.0'	72	78
4.	10.0 - 11.5'	71	66

NOTE: Water level at 5.5 feet on 8/6/70.

IN-618	Elev. 1185.72	8/10 to 8/11/70	PAB
0.0	3.5	TOPSOIL.	
3.5	10.0	SAND, silty with gravel, about 15% fines, 20% fine sand, 25% medium sand, 25% coarse sand, 15% gravel, subangular, with some decomposed rock bits, 3/4-inch maximum size, light olive-brown, moist, low permeability, very dense, GLACIAL TILL.	SM
6.0	8.0	Cobbles and Boulders.	
10.0	26.0	DIORITE -- gray biotite hornblende gneiss, foliations dipping about 70°. Moderately fractured. Fractures spaced about 6 to 14 inches apart, mostly horizontal.	
26.0		Bottom of Hole.	
<u>Drive Samples</u>			
No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	18	66
2.	1.5 - 2.9'	101/11" ref.	78
3.	5.0 - 6.5'	129	66
<u>Rock Core Runs</u>			
No.	Depth	Recovery	
1.	10.0 - 13.5'	76	
2.	13.5 - 18.5'	95	
3.	18.5 - 23.5'	100	
4.	23.5 - 26.0'	100	

NOTE: Water level at 6.92 feet on 8/11/70.

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

LOSS OF TEST MOLES

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Investigated by R. W. HILL & R. E. HARRISON, JR.	Date 8/11/70
Typed by M. LANCZOS	Typed by
Traced by	Traced by
Checked by R. W. HILL	Checked by
MA-357 P	

SCS-3138 (APRIL 1963)

292

B-17

# REPRODUCED AT GOVERNMENT EXPENSE

Elev. 1171.1  
 0.0 3.0  
 3.0 11.5  
 6 to 10'  
 10.5 to 11.5'  
 11.5 25.0  
 25.0  
 TOPSOIL AND MUDFLAT.  
 SILTY SAND, gravelly, about 15% fines, 10% fine sand, 25% medium sand, 30% coarse sand, 20% gravel, subangular, 3/4-inch maximum size, olive-brown, moist, medium-low permeability, very dense, GLACIAL TILL.  
 Boulders.  
 Boulders.  
 BECKROCK, gray, biotite hornblende gneiss, foliations dipping about 70°. Highly fractured. Fractures spaced about 1 to 8 inches apart. Fractures are not all tight.

Bottom of Hole.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	0.5 - 2.0'	26	66	
2.	4.0 - 5.5'	99	66	

Rock Core Runs	No.	Depth	% Recovery
1.	6.0 - 10.0'	60	
2.	11.5 - 16.5'	97	
3.	16.5 - 21.5'	100	
4.	21.5 - 25.0'	100	

Elev. 1158.7  
 0.0 1.5  
 1.5 5.0  
 5.0 9.5  
 9.5 17.5  
 17.5  
 8/12 to 8/12/70  
 PAB  
 TOPSOIL, ROOTS.  
 Boulders.  
 SAND, silty, with gravel, about 20% fines, 15% fine sand, 25% medium sand, 30% coarse sand, 10% gravel, subangular, 1-inch maximum size, olive-brown, moist, medium-low permeability, dense, GLACIAL TILL.  
 BECKROCK, gray, biotite, hornblende, gneiss. Foliations dipping about 70°. Highly fractured with sand seams. Fractures spaced 1/2-inch to 6 inches apart.

Bottom of Hole.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	1.0 - 1.5'	18	100	
2.	5.0 - 5.8'	60/10" ref.	78	

Rock Core Runs	No.	Depth	% Recovery
1.	9.5 - 12.5'	93	
2.	12.5 - 17.5'	83	

NOTE: Water level at 9.5 feet on 8/12/70.

Elev. 1171.82  
 0.0 1.5  
 1.5 9.0  
 9.0 21.0  
 21.0  
 8/13 to 8/13/70  
 DEN  
 TOPSOIL.  
 COBBLES and BOULDERS, with some silt and gravel matrix, GLACIAL DRIFT.  
 BECKROCK, gray, biotite hornblende gneiss, moderately fractured, fractures spaced 12 to 18 inches apart, most fractures dipping about 70 degrees, some horizontal.

Bottom of Hole.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	4	100	
2.	1.5 - 2.2'	41/7" ref.	40	

Rock Core Runs	No.	Depth	% Recovery
1.	9.0 - 11.0'	75	
2.	11.0 - 16.0'	100	
3.	16.0 - 21.0'	93	

NOTE: Water level at 9 feet on 8/13/70.

Elev. 1179.2  
 0.0 11.0  
 11.0 21.0  
 21.0  
 8/13 to 8/14/70  
 DEN  
 COBBLES and BOULDERS, with some silt and gravel matrix, unable to obtain drive samples. GLACIAL DRIFT.  
 BECKROCK, gray, biotite hornblende gneiss, moderately fractured. Fractures spaced 12 to 18 inches apart. Most fractures dipping about 70°. Some horizontal.

Bottom of Hole.

Rock Core Run	No.	Depth	% Recovery
1.	11.0 - 16.0'	80	
2.	16.0 - 21.0'	100	

Elev. 1101.8  
 0.0 1.5  
 1.5 6.5  
 6.5 16.5  
 16.5  
 8/17 to 8/12/70  
 DEN  
 TOPSOIL and MUDFLAT.  
 SAND, with gravel, about 45% fines, 10% fine sand, 10% medium sand, 50% coarse sand, 20% gravel, subangular, 2-inch maximum size, red-brown, damp, medium permeability, dense, FLOODPLAIN.  
 BECKROCK, gray, biotite hornblende gneiss, moderately fractured, fractures dipping about 60 degrees. Some horizontal. All fractures tight. BECKROCK.

Bottom of Hole.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	15	100	
2.	1.5 - 3.0'	82	70	
3.	3.0 - 4.5'	24	80	
4.	5.0 - 5.3'	100/4" ref.	100	

Rock Core Runs	No.	Depth	% Recovery
1.	16.5 - 10.5'	57	
2.	10.5 - 16.5'	70	

NOTE: Water level at 2.75 on 8/12/70.

Elev. 1098.4  
 0.0 2.0  
 2.0 3.5  
 3.5 14.5  
 14.5  
 8/13 to 8/13/70  
 PAB  
 TOPSOIL.  
 SAND, silty with gravel, about 25% fines, 20% fine sand, 25% medium sand, 30% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, red-brown, damp, medium permeability, medium dense, Floodplain Deposits.  
 BECKROCK, gray, biotite hornblende gneiss, foliations dipping about 80°. Highly fractured from 3'6" to 8'6". Fractures spaced about 3 to 5 inches apart. Very slightly fractured from 8'6" to 14'6".

Bottom of Hole.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	17	70	
2.	1.5 - 3.0'	26	83	
3.	3.0 - 3.5'	100/6" ref.	27	

Rock Core Runs	No.	Depth	% Recovery
1.	3.5 - 8.5'	73	
2.	8.5 - 14.5'	100	

NOTE: Water level at 4.58 feet on 8/13/70.

Elev. 1095.2  
 0.0 1.5  
 1.5 7.0  
 7.0 17.0  
 17.0  
 8/13 to 8/14/70  
 PAB  
 TOPSOIL and MUD FLAT.  
 SAND, with gravels, about 5% fines, 15% fine sand, 35% medium sand, 30% coarse sand, 15% gravel, subangular, 3/4-inch maximum size, red-brown, damp, high permeability, dense, Floodplain Deposits.  
 BECKROCK, gray, biotite hornblende gneiss, moderately fractured, foliations dipping about 60°. Most fractures are horizontal. All tight. BECKROCK.

Bottom of Boring.

Drive Samples	No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	8	80	
2.	1.5 - 3.0'	28	83	
3.	3.0 - 4.5'	98	83	
4.	5.0 - 5.5'	100/6" ref.	33	

Rock Core Runs	No.	Depth	% Recovery
1.	7.0 - 12.0'	100	
2.	12.0 - 17.0'	100	

1012

# REPRODUCED AT GOVERNMENT EXPENSE

TEST PIT  
CLAM LAKE, CLAM RIVER WATERSHED

TP-651 6/8 to 6/8/71 DEN  
0.0 1.0 TOPSOIL and ROOT MAT.

1.0 10.0 SAND, silty with gravel, about 2% fines, 15% fine sand, 2% medium sand, 30% coarse sand, 10% gravel, sub-angular, 18-inch maximum size, olive-brown, damp, low permeability, very dense, GLACIAL TILL est. 20% + 6-inch size. Disturbed Sample: 1 to 9 feet. Bottom of Pit.

TP-652 6/8 to 6/8/71 DEN  
0.0 0.5 TOPSOIL and ROOT MAT.

0.5 10.0 SAND and gravel, some silt, about 10% fines, 10% fine sand, 15% medium sand, 35% coarse sand, 30% gravel, sub-rounded, 24-inch maximum size, tan-brown, damp, medium-high permeability, dense, ice contact sand and gravel with cobbles and boulders to 6' est. 40% cobbles and boulders then about 25% + 6-inch size. Some rock fragments highly weathered. Disturbed Sample: 3 to 10 feet. Bottom of Pit.

TP-653 6/8 to 6/8/71 DEN  
0.0 1.0 TOPSOIL and ROOT MAT.

1.0 10.0 SAND and GRAVEL, some silt, about 10% fines, 10% fine sand, 15% medium sand, 35% coarse sand, 30% gravel, sub-rounded, 18-inch maximum size, tan-brown, damp, medium-high permeability, dense, ice contact sand and gravel, est. 25% + 6-inch size. Some rock fragments highly weathered. Disturbed Sample: 2 to 9 feet. Bottom of Pit.

TP-654 6/8 to 6/8/71 DEN  
0.0 1.0 TOPSOIL and ROOT MAT.

1.0 10.0 SAND and GRAVEL, with some silt, about 10% fines, 10% fine sand, 15% medium sand, 35% coarse sand, 30% gravel, sub-rounded, 20-inch maximum size, tan-brown, damp, medium-high permeability, dense, ice contact sand and gravel, est. 25% + 6-inch size. Some rock fragments highly weathered. Disturbed Sample: 3 to 10 feet. Bottom of Pit.

TP-655 6/10/71 DEN  
0.0 1.0 TOPSOIL and ROOT MAT.

1.0 12.0 SAND, silty with gravel and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 15-inch maximum size, olive-brown to 7 foot then blue-gray, damp to wet, low permeability, very dense, GLACIAL TILL weathered to 7 foot with water. Deep at 7 foot. Disturbed Sample 7 to 11 feet. Bottom of Pit.

TP-656 6/10/71 DEN  
0.0 1.0 TOPSOIL and ROOT MAT.

1.0 12.0 SAND, silty with gravel and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 5-inch maximum size, olive-brown, damp, low permeability, very dense, GLACIAL TILL. Disturbed Sample 2 to 12 feet. Bottom of Pit.

TP-657 6/10/71 DEN  
0.0 3.0 TOPSOIL and ROOT MAT and FILL.

3.0 10.0 SAND, silty with gravel and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 14-inch maximum size, olive-brown, damp, low permeability, very dense, GLACIAL TILL. Disturbed Sample: 3 to 9 feet. Bottom of Pit.

Test Pit (cont'd) CLAM RIVER WATERSHED CLAM LAKE SITE

TP-658 6/10/71 DEN

0.0 1.0 TOPSOIL and ROOT MAT, with sand and gravel, matrix water entering pit at est. 4' deep. Bottom and bottom of pit.

TP-659 6/10/71 DEN

0.0 1.0 TOPSOIL and ROOT MAT.

1.0 3.0 SAND, silty with gravel and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 14-inch maximum size, red-brown, wet, medium permeability, loose, WEATHERED GLACIAL TILL.

TP-660 6/10/71 DEN

0.0 1.0 TOPSOIL and ROOT MAT.

1.0 5.0 SAND, silty with gravel and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 30-inch maximum size, red-brown, wet, medium permeability, loose, WEATHERED GLACIAL TILL. Bottom of Pit.

TP-661 6/10/71 DEN

0.0 1.0 TOPSOIL and ROOT MAT.

1.0 11.0 SAND, silty with gravel, and cobbles, about 25% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 10% gravel, sub-angular, 22-inch maximum size, olive-brown, damp, low permeability, very dense, GLACIAL TILL. Bottom of Pit.

## CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS

### LOGS OF TEST HOLES

### U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

Investigator D. M. HILLS & P. BRINMAN 8/70	Date 8/70	Approved by .....
Type N LONGZAN	Title .....	.....
Sheet .....	Sheet No 33	Drawing No MA 357-P
Checked C. M. DOOGIE	Sheet of 26	

SCS-313B (APRIL 1963)

B-N



LOG OF TEST HOLE

**TP-71, ELEV. 1151.1** 6/24/65 R.C.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 20% fines, 20% fine sand, 15% medium sand, 10% coarse sand, 15% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 18", damp, low permeability, very dense, glacial till. Bottom of Pit.  
 10.0  
 D.S. 157.1, 3.0-10.0 6% larger than 6" discarded.  
 NOTE: Water level at 7.3' on 7/14/65

**TP-72, ELEV. 1151.1** 6/24/65 R.C.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 15% fines, 27% fine sand, 15% medium sand, 15% coarse sand, 20% gravel, 10% cobbles, 5% boulders, angular, hard, maximum size 14", olive-brown, damp, low permeability, very dense, ground moraine. Bottom of Pit.  
 10.0  
 D.S. 251.1, 3.0-10.0 5% larger than 6" discarded.  
 NOTE: Water level at 8' on 7/14/65

**TP-252, ELEV. 1151.0** 6/25/65 R.C.L.  
 0.0 2.5 TOPSOIL  
 2.5 10.0 SAND, gravelly with silt, about 10% fines, 25% fine sand, 15% medium sand, 5% coarse sand, 30% gravel, 10% cobbles, 5% boulders, angular to sub-rounded, maximum size 24", brown, moist to wet, low to medium permeability, dense, ground moraine. Bottom of Pit.  
 10.0  
 D.S. 252.1 (2 bags) 2.5-10.0 8% larger than 6" discarded.  
 NOTE: Water level at 0.5' on 7/14/65.

**TP-253, ELEV. 1145.3** 6/25/65 R.C.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 25% fines, 35% fine sand, 15% medium sand, 5% coarse sand, 15% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 13", olive-brown, damp, impermeable, very dense, glacial till. Bottom of Pit.  
 10.0  
 D.S. 253.1, 3.0-10.0 3% larger than 6" discarded.  
 NOTE: Water level dry on 7/14/65.

**TP-254, ELEV. 1199.3** 6/25/65 R.C.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 10% fines, 25% fine sand, 10% medium sand, 10% coarse sand, 35% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 14", brown, damp, low permeability, very dense, ground moraine. Bottom of Pit.  
 10.0  
 D.S. 254.1, 3.0-10.0 6% larger than 6" discarded.  
 NOTE: Water level dry on 7/14/65.

**TP-255, ELEV. 1194.6** 6/25/65 R.C.L.  
 0.0 3.0 BULKY TOPSOIL  
 3.0 10.0 SAND, gravelly with cobbles, about 7% fines, 20% fine sand, 15% medium sand, 10% coarse sand, 35% gravel, 15% cobbles, 5% boulders, sub-round to sub-angular, maximum size 17", brown, damp, high permeability, dense, knee terrace. Bottom of Pit.  
 10.0  
 D.S. 255.1 (2 bags) 3.0-10.0, 8% larger than 6" discarded.  
 NOTE: Water dry on 7/14/65.




**TP-256, ELEV. 1174.4** 6/25/65 R.C.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 25% fines, 35% fine sand, 10% medium sand, 2% coarse sand, 25% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 16", olive-brown, damp, impermeable, very dense, glacial till. Bottom of Pit.  
 10.0  
 D.S. 256.1, 3.0-10.0 5% larger than 6" discarded.  
 NOTE: Water level at 7.0' on 7/14/65.







**TP-91, ELEV.** 6/24/66  
 0.0 1.0 TOPSOIL.  
 1.0 5.0 SAND, silty, cobbles and boulders, dark, ALLUVIAL VALLEY FILL.  
 5.0 Bedrock at bottom of test pit.

**TP-92, ELEV.**  
 0.0 1.0 TOPSOIL.  
 1.0 5.0 SAND, silty, gravel, cobbles and boulders, grey, ALLUVIAL VALLEY FILL.  
 5.0 Bottom of pit. Bedrock. Water standing at 5.0.

**TP-93, ELEV.**  
 0.0 1.0 TOPSOIL.  
 1.0 5.0 SAND, silty, gravel, cobbles and boulders, grey, ALLUVIAL FILL.  
 5.0 Bottom of pit. Bedrock. Water entering at 5.0.

**TP-94, ELEV.**  
 0.0 1.5 TOPSOIL.  
 1.5 4.0 SAND, silty, dark, ALLUVIAL VALLEY FILL.  
 4.0 Bedrock at bottom of pit.





CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS			
LOSS OF TEST HOLES			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Investigator R. H. H. S. L. W. H. 1958	Date 1958	Approved by Title	
Type Soil		Title	
Traced		Sheet No. 24	Drawing No. MA 357-P
Checked DONALD MILLER	Date 8-2-58	at 24	

AD-A155 793

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
CLAM LAKE DAM (MA 010...101) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV FEB 80


2/2

UNCLASSIFIED

F/G 13/23

NL

END  
DATE  
FILMED  
8 85



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

APPENDIX C  
SELECTED PHOTOGRAPHS  
OF  
PROJECT






Photo 1

Overview of downstream  
channel looking south  
from top of dam.



Photo 2

Overview of reservoir  
area, upstream embankment  
and principal spillway  
structure looking north-  
westerly from embankment.



Photo 3

Overview of emergency spillway  
crest, weir wall and dam crest  
looking west from top of left  
slope of emergency spillway.

Photo 4

Overview of emergency spillway  
approach channel looking  
northerly from toe of spillway  
discharge channel.




Photo 5

Overview of downstream embankment  
looking westerly from training wall  
of emergency spillway.



Photo 6

Overview of emergency spillway  
training wall slope looking  
southerly from dam crest.  
Note: Erosion of slope.







Photo 7

Overview of downstream embankment, spillway discharge channel and left slope of emergency spillway. Note: The sloughing of left spillway slope.



Photo 8

60-inch outlet conduit and end wall. Note the crack above pipe and missing foundation drain pipe outlet to the left of the 60-inch conduit.




Photo 9

Pond drain inlet structure. Note damaged trash racks.

Photo 10

Pond drain inlet structure wing wall. Note cracks in concrete.



Photo 11

Gate well of principal spillway structure. Note the lower two stem guides are damaged.



Photo 12

Crack on right wall of riser transition.





Photo 13

Cracks and efflorescence  
on transition of principal  
spillway riser.



Photo 14

Crack in transition near  
the vertical downstream  
face of the principal  
spillway riser.



Photo 15

Closeup of silt from beneath  
rip rap on downstream side  
of embankment.

REPRODUCED AT GOVERNMENT EXPENSE

Photo 16

Closeup of left slope toe of  
emergency spillway at crest.  
Note groundwater seepage from  
slope.



Photo 17

Left slope of emergency spillway.  
Note slope failure and erosion.



REPRODUCED AT GOVERNMENT EXPENSE



Photo 18



Left slope of emergency spillway.  
Note erosion.



Photo 19

Transition of grass covered  
channel to riprap slope of  
emergency spillway. Note  
erosion and undercutting of  
rip rap by runoff.

APPENDIX D  
OUTLINE OF DRAINAGE AREA  
AND COMPUTATIONS



FROM: U.S.G.S. MONTEREY, AND  
OTIS, MASS. QUADRANGLE  
MAPS



QUADRANGLE LOCATION

TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS



## DRAINAGE AREA MAP

CLAM LAKE DAM (MA 01052)  
BERKSHIRE COUNTY

SANDISFIELD  
MASSACHUSETTS

SCALE: FEBRUARY 1980

DATE: AS NOTED



FROM: GENERAL HIGHWAY MAP,  
BERKSHIRE COUNTY

TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

## LOCATION AND DOWNSTREAM HAZARD MAP

CLAM LAKE DAM (MA 01052)  
BERKSHIRE COUNTY

SANDISFIELD  
MASSACHUSETTS

SCALE: AS NOTED

DATE: FEBRUARY 1990



120 January 2, 1980

Hydraulic/Hydrologic Computations

Computed by U. Lehnert

Checked by Moe

10 ft

Clan Lake Dam Sandisfield Mass.

Drainage Area = 6900 Acres = 10.85 mi

Water surface = 47 Acres

Size Classification

To Spillway { Height of Dam = 88 ft (Intermediate)  
Elev { Storage at E.S. Crest = 3050 A.F. (Intermediate)  
Top of Dam { Height of Dam = 94 ft  
Storage = 3840 A.F. } Intermediate  
Use Intermediate

Hazard Potential - High  
Test Flood - PHF

Drainage Area

Basin has mostly steep slopes  
with some hilly terrain.

Use the mountainous curve to  
find the PHF

$$\begin{aligned} \text{PHF} &= 1950 \text{ CFS} \times 10.8 \text{ mi} \\ &= 21,060 \text{ CFS} \end{aligned}$$

January 3, 1980

Computations

Checked By

Zof

## Reservoir Routing Computations

### Elevation Data

Dam Crest - 1178

Emergency Spill. Crest - 1172

Riser Crest - 1153

Orifice - 1143.3

Sediment Pool - 1107.0

Original Ground - 1097.0

### Storage Data

Sediment storage (1097-1107) - 12 AF

Multi Purpose Pool (1107-1143.3) - 738 AF

Flood Stor(1) (1143.3-1153) - 560 AF

Flood Stor(2) (1153-1172) - 1750 AF

### Area Data

Sediment Storage - 3 A

Multi Purpose - 47 A


Flood Stor 1 - 67 A

Flood Stor 2 - 120.5 A

Stage - Storage and spillway rating information contained in the hydrologic/hydrology section of the Design Folder prepared by the Soil Conservation Service has been reviewed and found valid for this analysis.

D.5

D-5



D-6

305

0-6

store-discharge (Used to study effects of Cold Water Release on the Routings)

1143.3	1143.4	1143.5	1143.6	1143.7	1143.8	1143.9	1144.0	1144.1	1144.2	1144.3	1144.4	1144.5	1144.6	1144.7	1144.8	1144.9	1145.0	1145.1	1145.2	1145.3	1145.4	1145.5	1145.6	1145.7	1145.8	1145.9	1146.0	1146.1	1146.2	1146.3	1146.4	1146.5	1146.6	1146.7	1146.8	1146.9	1147.0	1147.1	1147.2	1147.3	1147.4	1147.5	1147.6	1147.7	1147.8	1147.9	1148.0	1148.1	1148.2	1148.3	1148.4	1148.5	1148.6	1148.7	1148.8	1148.9	1149.0	1149.1	1149.2	1149.3	1149.4	1149.5	1149.6	1149.7	1149.8	1149.9	1150.0	1150.1	1150.2	1150.3	1150.4	1150.5	1150.6	1150.7	1150.8	1150.9	1151.0	1151.1	1151.2	1151.3	1151.4	1151.5	1151.6	1151.7	1151.8	1151.9	1152.0	1152.1	1152.2	1152.3	1152.4	1152.5	1152.6	1152.7	1152.8	1152.9	1153.0	1153.1	1153.2	1153.3	1153.4	1153.5	1153.6	1153.7	1153.8	1153.9	1154.0	1154.1	1154.2	1154.3	1154.4	1154.5	1154.6	1154.7	1154.8	1154.9	1155.0	1155.1	1155.2	1155.3	1155.4	1155.5	1155.6	1155.7	1155.8	1155.9	1156.0	1156.1	1156.2	1156.3	1156.4	1156.5	1156.6	1156.7	1156.8	1156.9	1157.0	1157.1	1157.2	1157.3	1157.4	1157.5	1157.6	1157.7	1157.8	1157.9	1158.0	1158.1	1158.2	1158.3	1158.4	1158.5	1158.6	1158.7	1158.8	1158.9	1159.0	1159.1	1159.2	1159.3	1159.4	1159.5	1159.6	1159.7	1159.8	1159.9	1160.0	1160.1	1160.2	1160.3	1160.4	1160.5	1160.6	1160.7	1160.8	1160.9	1161.0	1161.1	1161.2	1161.3	1161.4	1161.5	1161.6	1161.7	1161.8	1161.9	1162.0	1162.1	1162.2	1162.3	1162.4	1162.5	1162.6	1162.7	1162.8	1162.9	1163.0	1163.1	1163.2	1163.3	1163.4	1163.5	1163.6	1163.7	1163.8	1163.9	1164.0	1164.1	1164.2	1164.3	1164.4	1164.5	1164.6	1164.7	1164.8	1164.9	1165.0	1165.1	1165.2	1165.3	1165.4	1165.5	1165.6	1165.7	1165.8	1165.9	1166.0	1166.1	1166.2	1166.3	1166.4	1166.5	1166.6	1166.7	1166.8	1166.9	1167.0	1167.1	1167.2	1167.3	1167.4	1167.5	1167.6	1167.7	1167.8	1167.9	1168.0	1168.1	1168.2	1168.3	1168.4	1168.5	1168.6	1168.7	1168.8	1168.9	1169.0	1169.1	1169.2	1169.3	1169.4	1169.5	1169.6	1169.7	1169.8	1169.9	1170.0	1170.1	1170.2	1170.3	1170.4	1170.5	1170.6	1170.7	1170.8	1170.9	1171.0	1171.1	1171.2	1171.3	1171.4	1171.5	1171.6	1171.7	1171.8	1171.9	1172.0	1172.1	1172.2	1172.3	1172.4	1172.5	1172.6	1172.7	1172.8	1172.9	1173.0	1173.1	1173.2	1173.3	1173.4	1173.5	1173.6	1173.7	1173.8	1173.9	1174.0	1174.1	1174.2	1174.3	1174.4	1174.5	1174.6	1174.7	1174.8	1174.9	1175.0	1175.1	1175.2	1175.3	1175.4	1175.5	1175.6	1175.7	1175.8	1175.9	1176.0	1176.1	1176.2	1176.3	1176.4	1176.5	1176.6	1176.7	1176.8	1176.9	1177.0	1177.1	1177.2	1177.3	1177.4	1177.5	1177.6	1177.7	1177.8	1177.9	1178.0	1178.1	1178.2	1178.3	1178.4	1178.5	1178.6	1178.7	1178.8	1178.9	1179.0	1179.1	1179.2	1179.3	1179.4	1179.5	1179.6	1179.7	1179.8	1179.9	1180.0	1180.1	1180.2	1180.3	1180.4	1180.5	1180.6	1180.7	1180.8	1180.9	1181.0	1181.1	1181.2	1181.3	1181.4	1181.5	1181.6	1181.7	1181.8	1181.9	1182.0	1182.1	1182.2	1182.3	1182.4	1182.5	1182.6	1182.7	1182.8	1182.9	1183.0	1183.1	1183.2	1183.3	1183.4	1183.5	1183.6	1183.7	1183.8	1183.9	1184.0	1184.1	1184.2	1184.3	1184.4	1184.5	1184.6	1184.7	1184.8	1184.9	1185.0	1185.1	1185.2	1185.3	1185.4	1185.5	1185.6	1185.7	1185.8	1185.9	1186.0	1186.1	1186.2	1186.3	1186.4	1186.5	1186.6	1186.7	1186.8	1186.9	1187.0	1187.1	1187.2	1187.3	1187.4	1187.5	1187.6	1187.7	1187.8	1187.9	1188.0	1188.1	1188.2	1188.3	1188.4	1188.5	1188.6	1188.7	1188.8	1188.9	1189.0	1189.1	1189.2	1189.3	1189.4	1189.5	1189.6	1189.7	1189.8	1189.9	1190.0	1190.1	1190.2	1190.3	1190.4	1190.5	1190.6	1190.7	1190.8	1190.9	1191.0	1191.1	1191.2	1191.3	1191.4	1191.5	1191.6	1191.7	1191.8	1191.9	1192.0	1192.1	1192.2	1192.3	1192.4	1192.5	1192.6	1192.7	1192.8	1192.9	1193.0	1193.1	1193.2	1193.3	1193.4	1193.5	1193.6	1193.7	1193.8	1193.9	1194.0	1194.1	1194.2	1194.3	1194.4	1194.5	1194.6	1194.7	1194.8	1194.9	1195.0	1195.1	1195.2	1195.3	1195.4	1195.5	1195.6	1195.7	1195.8	1195.9	1196.0	1196.1	1196.2	1196.3	1196.4	1196.5	1196.6	1196.7	1196.8	1196.9	1197.0	1197.1	1197.2	1197.3	1197.4	1197.5	1197.6	1197.7	1197.8	1197.9	1198.0	1198.1	1198.2	1198.3	1198.4	1198.5	1198.6	1198.7	1198.8	1198.9	1199.0	1199.1	1199.2	1199.3	1199.4	1199.5	1199.6	1199.7	1199.8	1199.9	1200.0	1200.1	1200.2	1200.3	1200.4	1200.5	1200.6	1200.7	1200.8	1200.9	1201.0	1201.1	1201.2	1201.3	1201.4	1201.5	1201.6	1201.7	1201.8	1201.9	1202.0	1202.1	1202.2	1202.3	1202.4	1202.5	1202.6	1202.7	1202.8	1202.9	1203.0	1203.1	1203.2	1203.3	1203.4	1203.5	1203.6	1203.7	1203.8	1203.9	1204.0	1204.1	1204.2	1204.3	1204.4	1204.5	1204.6	1204.7	1204.8	1204.9	1205.0	1205.1	1205.2	1205.3	1205.4	1205.5	1205.6	1205.7	1205.8	1205.9	1206.0	1206.1	1206.2	1206.3	1206.4	1206.5	1206.6	1206.7	1206.8	1206.9	1207.0	1207.1	1207.2	1207.3	1207.4	1207.5	1207.6	1207.7	1207.8	1207.9	1208.0	1208.1	1208.2	1208.3	1208.4	1208.5	1208.6	1208.7	1208.8	1208.9	1209.0	1209.1	1209.2	1209.3	1209.4	1209.5	1209.6	1209.7	1209.8	1209.9	1210.0	1210.1	1210.2	1210.3	1210.4	1210.5	1210.6	1210.7	1210.8	1210.9	1211.0	1211.1	1211.2	1211.3	1211.4	1211.5	1211.6	1211.7	1211.8	1211.9	1212.0	1212.1	1212.2	1212.3	1212.4	1212.5	1212.6	1212.7	1212.8	1212.9	1213.0	1213.1	1213.2	1213.3	1213.4	1213.5	1213.6	1213.7	1213.8	1213.9	1214.0	1214.1	1214.2	1214.3	1214.4	1214.5	1214.6	1214.7	1214.8	1214.9	1215.0	1215.1	1215.2	1215.3	1215.4	1215.5	1215.6	1215.7	1215.8	1215.9	1216.0	1216.1	1216.2	1216.3	1216.4	1216.5	1216.6	1216.7	1216.8	1216.9	1217.0	1217.1	1217.2	1217.3	1217.4	1217.5	1217.6	1217.7	1217.8	1217.9	1218.0	1218.1	1218.2	1218.3	1218.4	1218.5	1218.6	1218.7	1218.8	1218.9	1219.0	1219.1	1219.2	1219.3	1219.4	1219.5	1219.6	1219.7	1219.8	1219.9	1220.0	1220.1	1220.2	1220.3	1220.4	1220.5	1220.6	1220.7	1220.8	1220.9	1221.0	1221.1	1221.2	1221.3	1221.4	1221.5	1221.6	1221.7	1221.8	1221.9	1222.0	1222.1	1222.2	1222.3	1222.4	1222.5	1222.6	1222.7	1222.8	1222.9	1223.0	1223.1	1223.2	1223.3	1223.4	1223.5	1223.6	1223.7	1223.8	1223.9	1224.0	1224.1	1224.2	1224.3	1224.4	1224.5	1224.6	1224.7	1224.8	1224.9	1225.0	1225.1	1225.2	1225.3	1225.4	1225.5	1225.6	1225.7	1225.8	1225.9	1226.0	1226.1	1226.2	1226.3	1226.4	1226.5	1226.6	1226.7	1226.8	1226.9	1227.0	1227.1	1227.2	1227.3	1227.4	1227.5	1227.6	1227.7	1227.8	1227.9	1228.0	1228.1	1228.2	1228.3	1228.4	1228.5	1228.6	1228.7	1228.8	1228.9	1229.0	1229.1	1229.2	1229.3	1229.4	1229.5	1229.6	1229.7	1229.8	1229.9	1230.0	1230.1	1230.2	1230.3	1230.4	1230.5	1230.6	1230.7	1230.8	1230.9	1231.0	1231.1	1231.2	1231.3	1231.4	1231.5	1231.6	1231.7	1231.8	1231.9	1232.0	1232.1	1232.2	1232.3	1232.4	1232.5	1232.6	1232.7	1232.8	1232.9	1233.0	1233.1	1233.2	1233.3	1233.4	1233.5	1233.6	1233.7	1233.8	1233.9	1234.0	1234.1	1234.2	1234.3	1234.4	1234.5	1234.6	1234.7	1234.8	1234.9	1235.0	1235.1	1235.2	1235.3	1235.4	1235.5	1235.6	1235.7	1235.8	1235.9	1236.0	1236.1	1236.2	1236.3	1236.4	1236.5	1236.6	1236.7	1236.8	1236.9	1237.0	1237.1	1237.2	1237.3	1237.4	1237.5	1237.6	1237.7	1237.8	1237.9	1238.0	1238.1	1238.2	1238.3	1238.4	1238.5	1238.6	1238.7	1238.8	1238.9	1239.0	1239.1	1239.2	1239.3	1239.4	1239.5	1239.6	1239.7	1239.8	1239.9	1240.0	1240.1	1240.2	1240.3	1240.4	1240.5	1240.6	1240.7	1240.8	1240.9	1241.0	1241.1	1241.2	1241.3	1241.4	1241.5	1241.6	1241.7	1241.8	1241.9	1242.0	1242.1	1242.2	1242.3	1242.4	1242.5	1242.6	1242.7	1242.8	1242.9	1243.0	1243.1	1243.2	1243.3	1243.4	1243.5	1243.6	1243.7	1243.8	1243.9	1244.0	1244.1	1244.2	1244.3	1244.4	1244.5	1244.6	1244.7	1244.8	1244.9	1245.0	1245.1	1245.2	1245.3	1245.4	1245.5	1245.6	1245.7	1245.8	1245.9	1246.0	1246.1	1246.2	1246.3	1246.4	1246.5	1246.6	1246.7	1246.8	1246.9	1247.0	1247.1	1247.2	1247.3	1247.4	1247.5	1247.6	1247.7	1247.8	1247.9	1248.0	1248.1	1248.2	1248.3	1248.4	1248.5	1248.6	1248.7	1248.8	1248.9	1249.0	1249.1	1249.2	1249.3	1249.4	1249.5	1249.6	1249.7	1249.8	1249.9	1250.0	1250.1	1250.2	1250.3	1250.4	1250.5	1250.6	1250.7	1250.8	1250.9	1251.0	1251.1	1251.2	1251.3	1251.4	1251.5	1251.6	1251.7	1251.8	1251.9	1252.0	1252.1	1252.2	1252.3	1252.4	1252.5	1252.6	1252.7	1252.8	1252.9	1253.0	1253.1	1253.2	1253.3	1253.4	1253.5	1253.6	1253.7	1253.8	1253.9	1254.0	1254.1	1254.2	1254.3	1254.4	1254.5	1254.6	1254.7	1254.8	1254.9	1255.0	1255.1	1255.2	1255.3	1255.4	1255.5	1255.6	1255.7	125
--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	-----

D..

D-7

A. 431

[illegible]

50431

D-8

D-5

January 3, 1980

Hydrologic/Hydraulic

Computations

Computed By

Checked By

606

## Spillway and Conduit Rating

The principal spillway has three sets of orifices for water release at normal pool elevations. The first orifice (gated) is set at elevation 1141.3 and is 1' x 1.42'. The second orifice is set at 1143.3 and is 1' x 4.12'. The third orifice is set at 1144.3 and consists of two (2) openings 1' x 4.4'. All one foot dimensions being the height of the openings.

The riser also has a first stage flood weir at 1153.0 on each side of the riser. The weir on each side of the riser is 15' long. This weir acts as an orifice once the stage gets to 1156.

The emergency spillway for the dam is cut into the left abutment and is 385 ft wide. The approach channel has a slope of -2.3% from the crest and the discharge channel has a slope of 1.8% away from

D-9

D-9

January 3, 1980

Hydrologic/Hydraulic  
Computation:

Computed by W. L. L. L.  
Checked by

7043

the crest. The crest is flat for 50' and a concrete weir is at the down stream edge of the flat crest. Slopes to each side of the spillway

one on a 2 horizontal to 1 vertical. The E.S. crest is set at elevation 1172.0 NSL


A 5' diameter conduit carries water from the principal spillway under the dam to a plunge pool on the down stream side. The discharge of the principal spillway is limited by the capacity of the conduit.

A 48" pond drain carries water to the river from the inlet structure but normally the gate will be closed and the only contribution this conduit will have to discharge is the release of bottom water thru the gate well on the up stream side of the river.

D-16

D-10

508



BASE FLOW 1 CSM  
CLAM RIVER WATERSHED  
CLAM LAKE SITE  
SKETCH OF COLD WATER RELEASE

P.C.F. 6-29-71

24 00 00

D-11

D-11



January 3, 1980


Hydrologic/Hydraulic

Computation

Checked By

9 of 3

# Spillway Rating Curve



Q (CFS)

Elevation	h	Q (conduit)	h	Q (ES)	h	Q (Dam)
1176	85.5	943.2	4	7750	-	-
1177	86.5	948.7	5	11,200	-	-
1178	87.5	954.1	6	15,200	-	-
1179	88.5	959.6	7	19,200	1	2569
					2	7565.7

Q Tot  
8693.2  
17,148.7  
16,154.1  
22,728.6

D-1a

D-12

January 4, 1980

Computations

Checked by:

1003

Computation of additional points

$$\text{Conduit } Q = C P H^{1/2} \quad (1143.3)$$

$$Q = 102 H^{1/2}$$

$$Q = 102(85.5)^{1/2} = 943.2$$

$$Q = 102(86.5)^{1/2} = 948.7$$

$$Q = 102(87.5)^{1/2} = 954.1$$

$$Q = 102(88.5)^{1/2} = 959.6$$

$$\text{Spillway } Q = C L H^{3/2} \quad (1172)$$

(Using data in SCS Folder)

$$H_p - Q$$

$$4 \quad 7750$$

$$5 \quad 11,200$$

$$6 \quad 15,200$$

$$7 \quad 19,200$$

$$\text{Dam } Q = C L H^{3/2} \quad (1178)$$

$$C = 2.6, L = 988 \text{ ft}$$

$$1179 \quad Q = (2.6)(988)(1)^{3/2} = 2568.8$$

$$1180 \quad Q = (2.6)(988)(2) = 7565.7$$

$$1181 \quad Q = (2.6)(988)(3) = 13,347.9$$

D-13

D-13

January 4, 1980

Hydrologic/Hydrologic

Computation/Computation

Computation

Checked By

1105

## Reservoir Routing

Surcharge elevation to pass 21,060 cfs  
 is 1178.8 - 1143.3 = 35.5 ft

From SCS Surface Area - Elevation  
 Curve

$$\text{Area @ 1178.8} = 142 \text{ A}$$

$$\text{Area @ 1143.3} = 47 \text{ A}$$

$$\text{Volume of Surcharge } \left( \frac{142 + 47}{2} \right) \times 35.5 \\ = 3355 \text{ AF} \checkmark$$

$$Q_{p1} = 21,060 \text{ cfs} \checkmark$$

$$\text{Stor}_1 = \frac{3355}{6900} = 0.49' \times 12 = 5.8''$$

$$Q_{p2} = 21,060 \left( 1 - \frac{5.8''}{12} \right) =$$

$$= 14,631 \text{ CFS} \checkmark$$

$$\text{Surcharge height for } Q_{p2}, H = \frac{1177.5 - 1143.3}{1177.5} \checkmark$$

$$\text{Volume of Surcharge } \left( \frac{138 + 47}{2} \right) \times 34.2'$$

$$= 3164 \text{ AF}$$

$$\text{Stor}_2 = \frac{3164}{6900} = .46 \times 12 = 5.5''$$

$$Q_{p3} = 21,060 \left( 1 - \frac{5.5''}{12} \right) =$$

$$= 14,963 \text{ CFS}$$

$$H = 34.4'$$

$$\frac{1177.7 - 1143.3}{1177.7} = 34.4$$

D-14

D-14

January 4, 1980

Hydrologic/Hydraulic

Computations

Checked By

Moe

120

H for  $Q_{p2}$  and  $Q_{p3}$  agree

∴ Surge Height  $H = 34.4$   
on  $1143.3 + 34.4 = 1177.70$

Crest of dam is at 1178.00

therefore the dam will not be overtopped  
and the spillway is adequate.

D-15

January 4, 1980

Computations

Checked by Moe

305

$$Q_p = \frac{8}{27} W_b \sqrt{y} y^{3/2}$$

$W_b$  = breach width at mid height of dam (40% of 590) = 236

$y$  = height from riverbed to pool at failure. Assume WL at dam crest 1178.0


$$Q_{p1} = \frac{8}{27} (236) (5.68) (94)^{3/2}$$

$$Q_{p1} = 301,975 \text{ CFS}$$

The first major impact area to be considered is the Town of West New Boston at the confluence of the Clan River, Silver Brook and the Buck River.

The reach is 14,000 ft long

Looking up Valley



$$A: \frac{1}{2} (6y^2 + 8y^2) = 7y^2$$

$$W_P = \sqrt{37} y^2 + \sqrt{65} y^2 = 14.1y$$

Average  $\times$  Section  $R = 0.5 y$

D-16

January 4, 1980

Computation

Checked by


145

$$n = 0.04$$

$$(Mountain Stream)$$

$$S = 0.014 \text{ ft/ft}$$

Plot Stage - Discharge Curve



Try 20'

$$Q = \frac{1.486}{n} A R^{2/3} S^{1/2}$$

$$Q = \left( \frac{1.486}{0.04} \right) (2800) (10.0)^{2/3} (0.12)$$

$$Q = 57,982.7 \text{ CFS}$$

Try 30'

$$Q = \frac{1.486}{0.04} (6300) (15.0)^{2/3} (0.12)$$

$$Q = 170,975.3 \text{ CFS}$$

D-17

D-17

January 4, 1984

Computation

Checked By

150-2

Reach Outflow ①

$$Q_{p1} = 361,975 \text{ CFS}$$

$$Y \approx 39' \quad \text{Use only } \frac{1}{2} \text{ reach (Uniform \& sect.)}$$

$$V = \frac{(7000)(39)^2(7)}{43560} = 1711 \text{ AF}$$

$$\text{Storage at Down Cross} = 3840 \text{ AF}$$

$$Q(\text{trial}) = 361,975 \left(1 - \frac{V_1}{S}\right)$$

$$= 361,975 \left(1 - \frac{1711}{3840}\right) =$$

$$= 200,688 \text{ CFS}, Y \approx 32'$$

$$V_2 = \frac{(7000)(32)^2(7)}{43560}$$

$$= 1152 \text{ AF}$$

$$V_{\text{ave}} = (1711 + 1152) \div 2 = 1432$$

$$Q_{p2} = (361,975) \left(1 - \frac{1432}{3840}\right) =$$

$$* \quad Q_{p2} = 226,989 \quad Y \approx 33'$$

Reach Outflow ②

$$Q_{p2} = 226,989 \quad Y \approx 33'$$

$$V_1 = \frac{(7000)(33)^2(7)}{43560} = 1225 \text{ AF}$$

$$Q(\text{trial}) = 226,989 \left(1 - \frac{1225}{3840}\right) = 154,577 \text{ CFS}$$

$$Y \approx 25'$$

$$V_2 = \frac{(7000)(25)^2(7)}{43560} = 946 \text{ AF}$$

$$V_{\text{ave}} (1225 + 946) \div 2 = 1086 \text{ AF}$$

$$Q_{p3} = 226,989 \left(1 - \frac{1086}{3840}\right) = 162,794 \text{ CFS}$$

D-16

\*

$$* \quad Q_{p3} = 162,794 \text{ CFS} \quad Y \approx 30'$$

D-14

January 4, 1980

Hydraulic, hydrologic

Computation, Design


Computation

Checked by

16043

The third reach that is of significance is 2000 ft downstream the Clin River below West New Boston. Since the Buck River watershed is not large the MPF flow from that area will not be included in this analysis and due to existing flood control structures (dams) the flood impact will not be significant. The  $Q_p$  from the Buck River is negligible compared to the  $Q_p$  of the dam failure.

Reach X Section (looking up valley)



$$A = 50y + \frac{1}{2}(20y^2 + 10y^2) = 50y + 15y^2$$

$$WP = 50 + \sqrt{401y^2} + \sqrt{101y^2} = 50 + 30.1y$$

$$R = \frac{50y + 15y^2}{50 + 30.1y} = \frac{y(50 + 15y)}{50 + 30.1y}$$

$$n = 0.03$$

$$S = 0.01$$

D-19

D-19




January 4, 1980

Computations

Check by

Dof3

Plot Q vs Stage



Try 10'

$$Q = \frac{1.486}{0.03} A R^{2/3} S^{1/2}$$

$$Q = \frac{1.486}{0.03} (2000) (5.6)^{2/3} (0.1)^{1/2}$$

$$Q = 131,259 \text{ CFS}$$

Try 20'

$$Q = \frac{1.486}{0.03} (7000) (10.7)^{2/3} (0.1)^{1/2}$$

$$Q = 168,498 \text{ CFS}$$

$$Q_{p3} = 162,794 \text{ CFS}$$

Reach Outflow (3)

$$H_A = 19.5'$$

$$V = (2000)(6679) = 43560 = 307 \text{ AF}$$

$$Q(\text{level}) = 162,794 \left(1 - \frac{307}{3840}\right) = 149,779 \text{ CFS D-20}$$

$$H = 19.0 \text{ ft D-20}$$

January 4, 1980

Hydrologic / Hydraulic Computations

Checked by: Moe

18 of 2


$$V = (2000)(6365) \div 43500 = 292 \text{ AF}$$

$$Q_{p4} = 162,794 \left(1 - \frac{300}{3840}\right) = 150,074 \text{ CFS}$$

\*

$$Q_{p4} = 150,074 \text{ CFS} \quad H \approx 19'$$

The fourth reach is 7000' downstream of West New Boston on the Cien River. This reach is 5000 ft downstream of the previous.



$$A = 50y + \frac{1}{2}(12y^2 + 20y^2) = y(50 + 16y)$$

$$WP = 50 + \sqrt{144y^2} + \sqrt{400y^2}$$

$$= 50 + 32.1y$$

$$R = \frac{y(50 + 32y)}{(50 + 32.1y)} \quad 10500$$

$$n = 0.03 \quad S = 0.01$$

Determine Points on Stage vs Flow

Try 10'

$$Q = \frac{1.486}{0.03} (3700) (9.97)^{2/3} (0.1)$$

$$Q = 184,963 \text{ CFS}$$

Try 5'

$$Q = \frac{1.486}{0.03} (1050) (4.9)^{2/3} (0.1)$$

$$Q = 15,012 \text{ CFS}$$

D-21


January 4, 1980

Computation

Checked by

1980

## Plot Stage vs Flow Curve



$$Q_{p4} = 150,074 \text{ CFS} \quad H \approx 11 \text{ ft}$$

Reach out flow ④

$$V = (5000') (4422) \div 43560 = 508 \text{ AF}$$

$$Q(\text{trial}) = 150,074 \left(1 - \frac{508}{3840}\right) = 130,221 \text{ CFS}$$

$$H \approx 10.5'$$

$$V = (5000) (4053) \div 43560 = 465 \text{ AF}$$

$$V_{\text{ave}} = (508 + 465) \div 2 = 487 \text{ AF}$$

$$Q_{p5} = (150,074) \left(1 - \frac{487}{3840}\right) =$$

$$* \quad \underline{Q_{p5} = 131,041 \text{ CFS} \quad H \approx 10.5'}$$

The fish reach will extend from 7000' downstream of West New Boston to the confluence of the Clam River with the West Branch of the Farmington River and along the WPF River to a bridge

D-22

January 2, 1980

Comp.

checked by.


2063

Just south of P-8

The reach is 8500 ft long.

The RPF for the WBF River and  
the Clear River is, from COE Curve  
 $1200 \text{ cfs/sm} \times 92 \text{ sm} = 110,400 \text{ cfs}$

X Section Looking up the Valley



$$A = 100y + \frac{1}{2}(20y^2 + 2.5y^2) = 100y + 11.25y^2$$

$$WP = 100 + \sqrt{401y^2} + \sqrt{7.25y^2} = 100 + 22.7y$$

$$R = \frac{100y + 11.25y^2}{100 + 22.7y}$$

$$S = 0.0054$$

$$n = 0.03$$

Determine Stage vs Flow curve for Reach

Try  $H = 10'$ 

$$Q = \frac{1.486}{n} (A) (R)^{2/3} (S)^{1/2}$$

$$Q = \frac{1.486}{0.03} (2125) (0.5)^{2/3} (0.0054)^{1/2}$$

$$Q = 25,678 \text{ cfs}$$

D-23

D-23

January 4, 1986

Hydrology - Hydrology

Comps

Checked by


2125

Try H: 20'

$$Q = \frac{1.486}{0.03} (6500) (5.16) (0.07)$$

$$Q = 116,255 \text{ CFS}$$

Plot Stage vs Discharge



$$Q_{P5} = 131,041 \text{ CFS} \quad H \approx 20.5 \text{ ft}$$

Reach Outflow (5)

$$V = (8500) (6778) \div 43560 = 1323 \text{ AF}$$

$$Q_{P(A=1)} = 131,041 \left(1 - \frac{1323}{3540}\right) = 85,893 \text{ CFS}$$

$$H = 18'$$

$$V = (8500) (5448) \div 43560 = 1063 \text{ AF}$$

$$V_{\text{out}} = (1323 + 1063) \div 2 = 1193$$

$$Q_{P6} = 131,041 \left(1 - \frac{1193}{3840}\right) = 90,338 \text{ CFS}$$

D-24

D-25

January 4, 1980

Computation

Checked by

22 of

\* 
$$Q_{PL} = 90,330 \text{ CFS} \quad H \approx 18.25'$$

(Without PMF of Farmington River  
and other adjacent areas.)

The attenuated flow from the fifth  
reach is 90,330 CFS without the  
PMF from the Farmington River. With  
the Farmington River PMF the  
flow would be 225,330 CFS.

D-25

January 4, 1980

Hydrology/Hydrologic

Computations

computed by D. L. Lencore

checked by

23 of 2

Beyond the Sift Creek is the Cole Brook Res. The dam failure flow from Claw Lake will amount to 3840 AF. The normal surface area of the Cole Brook Res is about 460 A. Therefore, the Colebrook Reservoir surface will rise about 8 ft to store the failure volume of 3840 AF. The normal pool elevation of Cole Brook Res is 701 and the crest of the dam is about 780. Therefore the storage requirement of 8 ft for the failure volume is less than 10% of the flood storage available for flood detention.

D-26

Feb 8, 1980

Hydrology/Hydrologic  
Comps

Comparison of  
Checked by

256

major roadways, and a cemetery.

- 4) The dam failure flow in the fifth reach will result in a stage of about 18.25 ft with an attenuated flow of 90,330 CFS. If the PMF of the W. Branch of the Farmington River is included the stage will be about 26 ft and the flow will be 225,330 CFS. This flood will result in damage to about 11 homes and buildings, two major highway bridges, one secondary road bridge and about 13,000 feet of road.
- 5) Because of the existence of Cole Brook Reservoir, a flood control structure, the failure flow will be stored and no further downstream damage will likely occur.

D-27

D-27



FEB 8, 1966

Hydraulic/Hydrologics  
Camp-

Computed by  
Checked by

260

# Summary of Flow Due to Dam Failure

Area Location	Flow CF's
① At Dam	341,975
② 2000' DS	226,989
③ 14000' DS	162,754
④ 18,000' DS	131,041
⑤ 25,500' DS	90,330
⑥ 29,500' DS	90,330
⑦ 34,000' DS	Flood stored

D-28

February 8, 1980

Hydrologic/Hydraulic  
Comps

Computed by D. L. L. L.  
Checked by

2485

Conclusions  
(Not including PMF for adjacent DAs)

- 1) The spillways for the dam are adequate to handle the PMF and the structure will not be overtopped.
- 2) Dam failure flow in the first + second reaches from the dam to the confluence of the Clin River and the Buck River will result in a stage of 30 to 33' with an attenuated failure flow from 226,989 to 162,794 CFS. The failure flow will result in the loss of a wooden bridge on Montville Beech - Plain Rd.
- 3) The dam failure flow in the third + fourth reach from the confluence of the Clin and Buck River in West New Boston to the confluence of the Clin River with the West Branch of the Fannington River will result in a stage of about 19 to 21 and an attenuated flow of 150,074 to 131,041 CFS. The flow will result in damage to about 25 ± houses and buildings, two major bridges, about 9000 ft of

D-29

Feb 2, 1965

Lapeer

Mackinac

Mee

27.5

# Significant Tributary Drainage Area Data

Location	DA (Sq. Mi.)	P.M.F. (CFS)
1) From Don To Confluence of Buck River and Clan River		
a) Clan River		
1) To Don	10.8 sm	15,000
2) To Buck R	2.2 sm	5,500
	<u>13.0 sm</u>	<u>20,500</u>
2) From confluence of Buck River to W Branch of Farmington River		
a) Clan to Buck	13.0 sm	20,500
b) Clan Buck to W Branch Farm.	2.5 sm	6,200
c) Silver Brook	5.0 sm	11,250
d) Buck River	8.6 sm	14,900
	<u>29.1 sm</u>	<u>52,850</u>
3) W Branch Farmington River to Colebrook R.		
a) Clan River	15.5 sm	24,700
b) Silver Brook	5.0 sm	11,250
c) Buck River	8.6 sm	14,900
d) Farmington River	62.9 sm	81,770
	<u>92.0 sm</u>	<u>134,620</u>

D-30

Feb 8, 1930

Hydrologic

Engineering

Stage

Inundation

285-

## Flood Stage Inventory

Area Location	Priority Flood Flow	Stage Prior	Area Failure of Dam	Stage
1 At Dam	15,000	5.7 (Capillary)	262,000	Dam Fail
2 2000' DS	15,000	8'	242,000	34
3 14,000 DS	20,500	9'	151,500	19
4 18,000' DS	53,000	8	184,000	11
5 25,500 DS	135,000	21	225,000	26
6 29,500 DS	135,000	21	255,000	26
7 36,000 DS	Flood Stored			

D-31

Feb 2, 1980

Hydrology / hydrology

Camp

checked by U. L. L. L.

29053

## Bridge Crossing Data

## 1) Mountville-Beck Plain Road Bridge

Area Loc  
2Stream bed elevation  $\approx 1060$ Road bed elevation  $\approx 1070$ Dam failure flood elevation  $\approx 1093$ Dam failure flood + PMF elevation  $\approx 1094$ 

## 2) West New Boston - Sandisfield Rd Bridge

Area Loc  
3

Stream bed elevation

-  $\approx 868$ 

Road bed elevation

-  $\approx 887$ Dam failure flood elevation -  $\approx 887.0$ Dam failure flood + PMF elevation -  $\approx 887.0$ 

## 3) New Boston - New Hartford Rd Bridge

Area Loc  
4

Stream bed elevation

-  $\approx 827$ 

Road bed elevation

-  $\approx 837$ Dam failure flood elevation -  $\approx 837.5$ Dam failure + PMF elevation  $\approx 837.5$ 

## 4) Bridge at Roosterville

Area Loc  
5

Stream bed elevation -

 $\approx 765$ 

Road bed elevation -

 $\approx 775$ Dam failure flood elevation -  $\approx 786$ 

Dam failure flood

 $\approx 791$ 

D-32

Feb 8, 1980

Hydrologic/Hydrographic  
Comp

Comparison of Section  
Checked by:

30

5) R+8 Bridge over W Branch Farmington R

Amc Loc  
6

Stream bed elevation -  $\approx$  744

Road bed elevation -  $\approx$  758

Dam failure flood elev -  $\approx$  765

Dam failure + Ph. F elev -  $\approx$  770

6) Access Road Bridge South of R+8

Amc Loc  
6

Stream bed elevation  $\approx$  740

Road bed elevation  $\approx$  750

Dam failure flood elev  $\approx$  761

Dam failure + Ph. F elev  $\approx$  766

D-33

APPENDIX E  
INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS

U.S. DEPT. OF AGRICULTURE

# INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	DIVISION	STATE	COUNTY	CORNER	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY   MO   YR
4A 1053 1E7		MA	000	0	CLAM LAKE DAM	4208.3	7306.0	19FEB80

POPULAR NAME	NAME OF IMPONDMENT			
	CLAM LAKE			
REGION BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01 OR CLAM RIVER		SANDISFIELD (W. NEW BOSTON)	3	650

TYPE OF DAM	YEAR COMPLETED	PURPOSES	HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES (ACRE-FT.)	MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)
REPG	1977	RC	94	93	3810	750

DIST OWN FED R PRV/FED SCS A VER/DATE  
MED N N N B

REMARKS

D/S WAS	SPELLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CY)	POWER CAPACITY (KW)	INSTALLED (KW)	PROPOSED (KW)	NO.	LENGTH (FT.)	WIDTH (FT.)	DEPTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	DEPTH (FT.)
1	950	11	385	16150									


OWNER	ENGINEERING BY	CONSTRUCTION BY
COMM OF MASSACHUSETTS	US DEPT AGRICULTURE SCS	

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
US DEPT AGRIC SCS	US DEPT AGRIC SCS	COMM MASS DIV F&P	COMM MASS DIV F&P

INSPECTION BY	INSPECTION DATE DAY   MO   YR	AUTHORITY FOR INSPECTION
TIGHE & BOND DIV OF SCI	01NOV79	P.L. 92 - 367

REMARKS
51-52 DIV OF FORESTS & PARKS





# CLAM RIVER WATERSHED PROJECT

## CLAM LAKE MULTIPLE-PURPOSE DAM

### RECREATION AND FLOOD PREVENTION

DRAINAGE AREA	6900 ACRES
TOTAL STORAGE	3050 ACRE FEET
FLOODWATER RETARDING STORAGE TO EMERGENCY SPILLWAY CREST	2300 ACRE FEET
WATER SURFACE AREA AT PERMANENT POOL	47 ACRES
HEIGHT OF DAM	88 FEET
VOLUME OF FILL	525,000 CUBIC YARDS

BUILT UNDER THE WATERSHED PROTECTION AND  
FLOOD PREVENTION ACT

by

MASSACHUSETTS DEPARTMENT of NATURAL RESOURCES

and

MASSACHUSETTS WATER RESOURCES COMMISSION

and

BERKSHIRE CONSERVATION DISTRICT

of the

COMMONWEALTH of MASSACHUSETTS

with the assistance of

SOIL CONSERVATION SERVICE

of the

UNITED STATES DEPARTMENT of AGRICULTURE

1972

#### INDEX

SHEET 1 - COVER SHEET	SHEET 14 - EMERGENCY SPILLWAY DRAIN
SHEET 2 - PLAN OF STORAGE AREA	SHEET 15 - EMERGENCY SPILLWAY DRAINAGE DETAILS
SHEET 3 - AERIAL PLAN	SHEET 16 - ROCK TREATMENT DETAILS
SHEET 4 - SITE LAYOUT DETAILS	SHEET 17 - FARM FIELD FENCE DETAILS
SHEET 5 - PLAN OF DAM SITE	SHEETS 18 to 23 - RISER DETAILS
SHEET 6 - PLAN OF EMERGENCY SPILLWAY	SHEET 24 - HIGH & LOW STAGE TRASH RACK DETAILS
SHEET 7 - FILL PLACEMENT	SHEETS 25 & 26 - RESERVOIR DRAIN INLET DETAILS
SHEET 8 - PROFILE OF CUTOFF TRENCH	SHEET 27 - CONDUIT DETAILS
SHEET 9 - FOUNDATION DRAIN DETAILS	SHEET 28 - HEADWALL DETAILS
SHEET 10 - PRINCIPAL SPILLWAY PLAN AND PROFILE	SHEET 29 - EMERGENCY SPILLWAY WEIR DETAILS
SHEET 11 - PRINCIPAL SPILLWAY DETAILS	SHEETS 30 to 34 - LOGS OF TEST HOLES
SHEET 12 - PRINCIPAL SPILLWAY EXCAVATION & E.S. FILL SECTION	SHEET 35 - STABILIZATION OF STRUCTURES
SHEET 13 - EMERGENCY SPILLWAY PROFILES	SHEET 36 - JUTE NETTING & CHAIN LINK FENCE DETAILS

MULTIF

# D PROJECT POSE DAM VENTION

900 ACRES  
050 ACRE FEET  
300 ACRE FEET  
47 ACRES  
88 FEET  
000 CUBIC YARDS

## TECTION AND T

## L RESOURCES


## COMMISSION

## RICT

## ETTS

## ICULTURE




GENCY SPILLWAY DRAIN  
GENCY SPILLWAY DRAINAGE DETAILS  
TREATMENT DETAILS  
FIELD FENCE DETAILS  
ISER DETAILS  
LOW STAGE TRASH RACK DETAILS  
ESERVOIR DRAIN INLET DETAILS  
UIT DETAILS  
WALL DETAILS  
GENCY SPILLWAY WEIR DETAILS  
OOS OF TEST HOLES  
ILIZATION OF STRUCTURES  
NETTING & CHAIN LINK FENCE DETAILS



CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS	
COVER SHEET	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by <u>A. J. IMBETTA</u>	Date <u>9-7-71</u>
Drawn by <u>P. J. WILDA</u>	Scale <u>1" = 1/2 MI.</u>
Traced by <u>J. J. ELASHMAR</u>	Sheet <u>MA-397 P</u>
Checked by <u>D. W. STOCKWELL</u>	Project <u>MA-397 P</u>


# LEGEND

- |                            |                   |
|----------------------------|-------------------|
| IMPROVED ROAD              | PERMANENT POOL    |
| POOR ROAD                  | DESIGN HIGH WATER |
| PERMANENT STREAM           | SURVEY STATION    |
| INTERMITTENT STREAM        | BENCH MARK        |
| WOODS LINE                 | DRILL HOLE        |
| STONE WALL                 | TEST PIT          |
| WIRE FENCE                 | ROCK OUTCROP      |
| SWAMP                      | BEDROCK           |
| GRAVEL PIT                 | POWER LINE        |
| DEPRESSION                 | TELEPHONE LINE    |
| APPROX LIMIT OF WORK AREA  | PIPE LINE         |
| APPROXIMATE PROPERTY LINES | WELL              |
| CLEARING LIMITS            | SPRING            |
| CLEARING & GRUBBING        | DIVERSION DITCH   |
| FOUNDATION EXCAVATION      | BOUNDARY MONUMENT |
| FOUNDATION DRAIN           | BEAVER DAMS       |



CLEARING	
CLEARING CLASS 'C'	ALONG THE E.C. FROM THE 1143.3 BEYOND THE 1173.8
CLEARING CLASS 'B'	WITHIN THE DESIGN HIGH WATER
CLEARING CLASS 'A' & GRUBBING	DAM, EMERGENCY DIVERSION, IN ROCK DISPOSAL

TBM 1 (ELEV 1210.56) TOP STA 9+25  
 TBM 251 (ELEV 1277.72) TOP 90' WEST OF BECK  
 TBM 341 (ELEV 1099.79) TOP CLAM RIVER, EAST



#### CLEARING REQUIREMENTS


CLEARING CLASS C	ALONG THE EDGE OF THE PERMANENT POOL FROM THE 1140.3 CONTOUR TO 10' HORIZONTALLY BEYOND THE 1143.3 CONTOUR
CLEARING CLASS B	WITHIN THE DISPOSAL AREAS AND WITHIN THE PERMANENT POOL BELOW ELEVATION 1140.3
CLEARING & GRUBBING	DAM, EMERGENCY SPILLWAY, BORROW AREA, DIVERSION, INLET & OUTLET CHANNELS AND ROCK DISPOSAL

#### NOTES:

- 1 ORIGINAL TOPO SURVEYED BY M NOYES 1962
- 2 ADDED SURVEY (ABOVE ELEV 1160) BY R BROWN & ASSOC 1970
- 3 LOCATION OF BEAVER PONDS AS OF JULY 1970
- 4 NO WASTE MATERIAL SHALL BE LEFT BETWEEN THE PERMANENT POOL CONTOUR (ELEVATION 1143.3) AND ELEVATION 1100.0.
- 5 THE SURFACE OF THE BORROW AND DISPOSAL AREAS SHALL BE LEFT NEAT AND IN A SLIGHTLY CONDITION AND SLOPED TO PROVIDE POSITIVE DRAINAGE. SIDE SLOPE SHALL BE LEFT NO STEEPER THAN 2:1

- TBM 1 (ELEV 1210.56) TOP OF 2' BOULDER 60' U/S OF STA 9+25
- TBM 251 (ELEV 1277.72) TOP OF 2' x 4' BOULDER APPROX 90' WEST OF BEECH PLAIN ROAD
- TBM 341 (ELEV 1099.79) TOP OF 2' x 3' ROCK WEST SIDE CLAM RIVER, EAST SIDE LOGGING ROAD

200 0 200 400  
SCALE IN FEET



**BORROW AREA DIVERSION**  
**TYPICAL SECTION**  
NOT TO SCALE

#### CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDISFIELD, MASSACHUSETTS

#### PLAN OF STORAGE AREA


#### U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

Designed J. A. YIDDETT	Date 8-71	Approved by
Drawn F. J. WILDA	12-21-71	
Traced F. J. WILDA	9-18-72	
Checked J. J. ELAMER	8-9-72	
Sheet 2 of 36		MA-387 P


B-4

# **CONSTRUCTION NOTES:**


- 1 BOULDERS ARE SCATTERED THROUGHOUT THE ENTIRE WORK AREA
- 2 THE CONTRACTOR SHALL EXCAVATE ENTIRE PRINCIPAL SPILLWAY PRIOR TO PLACING ANY CONCRETE OR PIPE.
- 3 THE CONTRACTOR WILL NOT BE PERMITTED TO WORK IN THE RIVER CHANNEL UNTIL THE PRINCIPAL SPILLWAY SYSTEM HAS BEEN COMPLETED AND THE RIVER FLOW HAS BEEN DIVERTED INTO IT, UNLESS OTHERWISE APPROVED IN WRITING BY THE ENGINEER.




**TYPICAL SECTION INLET CHANNEL**  
NOT TO SCALE




**TYPICAL SECTION OUTLET CHANNEL (IN ROCK CUT)**  
NOT TO SCALE





**TYPICAL SECTION OUTLET CHANNEL (IN EARTH CUT FROM END OF ROCK CUT TO STA 304+25)**




**TYPICAL SECTION OUTLET CHANNEL (IN EARTH CUT FROM STA 304+25 TO END)**















**TYPICAL SECTION (I)**




**TYPICAL SECTION (AE)**

EARTH FILL REQUIREMENTS					
ZONE	MATERIAL	MAXIMUM ROCK SIZE	MAXIMUM LIFT <sup>Δ</sup>	MINIMUM <sup>Δ</sup> WATERCONTENT	COMPACTION CLASS DEFINITION
1	SAND, SILTY WITH GRAVEL REPRESENTED BY TP 196 (2.5'-10'), DH 3 (11.5'-23'), TP 656 (11.0'-12'), TP 256 (3'-10'), TP 154 (2.5'-10'), TP 651 (11'-10')	6"	9"	OPTIMUM	A 100% MAX DENSITY BY ASTM D 698 METHOD A
2	SILTY SAND AND GRAVELY SAND REPRESENTED BY TP 294 (3'-10'), TP 296 (3'-10'), TP 652 (10.5'-10'), TP 453 (11'-10'), TP 654 (11'-10'), DH 9 (10'-12'), DH 10 (10'-10')	8"	12"	OPTIMUM	C 4 PASSES PER LAYER OF FILL w/ PNEUMATIC TIRE ROLLER WEIGHING AT LEAST 50 TONS OR AN EQUIVALENT METHOD APPROVED BY THE ENGINEER
E.S. FILL	SAND, SILTY WITH GRAVEL SIMILAR TO THAT SHOWN IN ZONE 1.	12"	18"	OPTIMUM	C


<sup>Δ</sup> MAXIMUM LIFT THICKNESS PRIOR TO COMPACTION  
<sup>Δ</sup> BASED ON STANDARD PROCTOR

**CONSTRUCTION NOTES:**

1. EQUIPMENT PLACED RIPRAP SHALL BE WELL GRADED AND HAVE SIZE EQUAL TO THE DEPTH SHOWN. 60% TO 75% OF THE RIPRAP SHALL BE LARGER THAN 3/4" OF THE DEPTH SHOWN.
2. BEDDING SHALL BE WELL GRADED BETWEEN 3/4" AND 3 1/2" AND 70% TO 75% PASSING THE 3/4" SIEVE.
3. REPRESENTATIVE ROCK SAMPLES FROM THIS WATERSHED HAVE ALL SAMPLES TESTED CONFORM TO MATERIAL SPECIFICATION.




CROSS SECTION (VALLEY)



CROSS SECTION (ABUTMENTS)


NOTE:  
DELETE FOUNDATION DRAIN ABOVE ELEV 1143.0

SHALL BE WELL GRADED AND HAVE A MAXIMUM  
H SHOWN 60% TO 75% OF THE RIPRAP SHALL  
ME DEPTH SHOWN.  
GRADED BETWEEN 3/4" AND 3 1/2" WITH 30%  
SIEVE  
MPLES FROM THIS WATERSHED HAVE BEEN TESTED  
NFORM TO MATERIAL SPECIFICATION 523.




CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS	
FILL PLACEMENT	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by A.A. TROBRIE	Date 8/21
Drawn by F.J. WILSON	Date 11/27
Checked by J.E. PRATT	Date 11/27
Approved by	Date
MA-567 P	

1. ASBESTOS CEMENT PIPE SHALL CONFORM TO SPECIFICATION 545 AND SHALL BE 4" DIA, CLASS 4000.
2. WHEN PERFORATED ASBESTOS CEMENT PIPE IS REQUIRED, THE ASBESTOS CEMENT PIPE SHALL BE PERFORATED WITH 1/2" HOLES. THE LOCATION AND NUMBER OF THESE HOLES SHALL BE SIMILAR TO THOSE IN ASBESTOS CEMENT UNDERDRAIN PIPE OF THE SAME DIAMETER.
3. THE EXCAVATION LIMITS ARE APPROXIMATE AND WILL BE ADJUSTED BY THE ENGINEER IN ACCORDANCE WITH THE CONDITIONS ENCOUNTERED.
4. THE DEPTH OF THE DRAIN TRENCH MAY BE INCREASED IN SOME AREAS IF UNSUITABLE OR PERVIOUS MATERIALS ARE ENCOUNTERED AS DIRECTED BY THE ENGINEER





3/8" DIA BOLTS  
w/ NUT & WASHER  
6" LONG



### SMALL ANIMAL GUARD DETAILS


NOT TO SCALE

4" DRAIN  
PIPE



60" PRINCIPAL  
SPILLWAY


4" DRAIN  
PIPE



### SECTION X-X

NOT TO SCALE


FOUNDATION DRAIN



VIEW

100  
FEET

DRAIN FILL REQUIREMENTS	
SIEVE NO.	% PASSING
3/4"	100%
1/2"	90-100
3/8"	40-75
#4	5-25
#8	0-10
#16	0-5




CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS


FOUNDATION DRAIN DETAILS

U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Designed by J. A. TIPPETTS	Date 10/71	Approved by
Drawn by P. J. WILDA	Date 8-1972	Title
Checked by J. F. POLAN	Date 8-8-72	Sheet No. 56
Drawing No. MA-357 P		



**DETAIL OF BERM SLOPES @ RISER**  
NOT TO SCALE



**PLAN**

**48" PIPE DATA**

48" REINFORCED CONCRETE WATER PIPE	
(2) 4.0' SECTIONS	8.0'
(2) 8.0' SECTIONS	16.0'
(6) 16.0' SECTIONS	96.0'
<b>TOTAL</b>	<b>120.0'</b>

PRESSURE HEAD = 73.7

LOAD = 50,330 LBS PER LINEAR FOOT BASED ON OUTSIDE DIAMETER OF 60"


MINIMUM 3-EDGE BEARING STRENGTH FOR 0.001" CRACK (PRESTRESSED) EQUALS 18,920 LBS PER LINEAR FOOT (AWWA C-301).

MINIMUM 3-EDGE BEARING STRENGTH FOR 0.01" CRACK (NON-PRESTRESSED) EQUALS 25,163 LBS PER LINEAR FOOT (AWWA C-300).

48" PIPE JOINTS		
JOINT	1/2 DISTANCE FROM INLET	INVERT ELEVATION
INLET	0	1100.0
JA	16	1099.73
JB	32	1099.47
JC	48	1099.20
JD	64	1098.93
JE	80	1098.67
JF	96	1098.40
JG	104	1098.27
JH	112	1098.13
JI	116	1098.07
OUTLET	120	1098.00


**PIPE SUPPLIER'S NOTE:**

CAST INSIDE OF BELL RING JOINT WITH CONCRETE ON ONE (16) PIPE SECTION. THE O.D. OF PIPE ASSUMED IN DESIGN IS 60". WHERE THE PIPE FURNISHED HAS AN O.D. GREATER THAN ASSUMED IN DESIGN, THE THREE-EDGED BEARING STRENGTH OF THE PIPE FURNISHED MUST NOT BE LESS THAN THE SPECIFIED THREE-EDGED BEARING STRENGTH MULTIPLIED BY THE RATIO OF THE O.D. OF THE PIPE FURNISHED TO THE O.D. ASSUMED IN DESIGN.



**PROFILE**

4 DIMENSIONS OF CONCRETE PIPE LENGTHS ARE BASED ON NOMINAL LENGTHS AND DO NOT INCLUDE CREEP



ANTI-SEEP COLLARS		
COLLAR	DISTANCE FROM TRANSITION WALL	INVERT OF PIPE
I	12.33	1096.65
II	36.33	1095.96
III	60.33	1095.27
IV	84.33	1094.58
V	108.33	1093.88
VI	132.33	1093.19
VII	156.33	1092.50
VIII	180.33	1091.81
IX	204.33	1091.12

60" PIPE JOINTS		
JOINT	DISTANCE FROM TRANSITION WALL	INVERT ELEVATION
J1	0.33	1097.00
J2	8.33	1096.77
J3	24.33	1096.31
J4	40.33	1095.85
J5	56.33	1095.38
J6	72.33	1094.92
J7	88.33	1094.46
J8	104.33	1094.00
J9	120.33	1093.54
J10	136.33	1093.08
J11	152.33	1092.62
J12	168.33	1092.15
J13	184.33	1091.69
J14	200.33	1091.23
J15	216.33	1090.77
J16	232.33	1090.31
J17	248.33	1089.85
J18	264.33	1089.38
J19	280.33	1088.92
J20	296.33	1088.46
OUTLET	312.33	1088.00

**60" PIPE DATA**

60" REINFORCED CONCRETE WATER PIPE  
(1) 8.0' SECTION 8.0'  
(19) 16.0' SECTIONS 304.0'  
(1) WALL FITTING  
TOTAL = 312.0'

PRESSURE HEAD = 83.2

LOAD = 164,742 LBS PER LINEAR FOOT BASED ON OUTSIDE DIAMETER OF 80"


MINIMUM 3-EDGE BEARING STRENGTH FOR 0.001" CRACK (PRESTRESSED) EQUALS 37,872 LBS PER LINEAR FOOT (AWWA C-301).

MINIMUM 3-EDGE BEARING STRENGTH FOR 0.01" CRACK (NON-PRESTRESSED) EQUALS 50,369 LBS PER LINEAR FOOT (AWWA C-300)


**PIPE SUPPLIER'S NOTE**

CAST OUTSIDE OF SPIGOT JOINT RING WITH CONCRETE ON ONE PIPE SECTION

THE O.D. OF PIPE ASSUMED IN DESIGN IS 80". WHERE THE PIPE FURNISHED HAS AN O.D. GREATER THAN ASSUMED IN DESIGN, THE THREE EDGED BEARING STRENGTH OF THE PIPE FURNISHED MUST NOT BE LESS THAN THE SPECIFIED THREE EDGED BEARING STRENGTH MULTIPLIED BY THE RATIO OF THE O.D. OF THE PIPE FURNISHED TO THE O.D. ASSUMED IN DESIGN.




CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS			
PRINCIPAL SPILLWAY			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Designed by J. A. TIDDETT	Scale 1/4" = 1'	Approved by	
Drawn by F. A. WILDA	2-1982	Checked by	
Typed by		Project No.	MA-387 P
Checked by S. N. BARR	1/10/82	Sheet No.	8-9




**PRINCIPAL SPILLWAY WITH CRADLE  
IN AREAS REQUIRING ROCK EXCAVATION**

NOT TO SCALE




**PRINCIPAL  
IN AREAS RE**




**PRINCIPAL SPILLWAY WITH CRADLE  
IN AREAS NOT REQUIRING ROCK EXCAVATION**

NOT TO SCALE




**PRINCIPAL  
IN AREAS NOT**




**DETAIL OF RISER BASE**

NOT TO SCALE






**PRINCIPAL SPILLWAY WITH BEDDING  
IN AREAS REQUIRING ROCK EXCAVATION**  
NOT TO SCALE




**PRINCIPAL SPILLWAY WITH BEDDING  
IN AREAS NOT REQUIRING ROCK EXCAVATION**  
NOT TO SCALE

CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS	
PRINCIPAL SPILLWAY DETAILS	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed: J.A. TIBBETTS	Scale: 1/2\"/>

B-10




**CONSTRUCTION NOTES:**  
 1. FOR LOGS OF TEST HOLES SEE SHEETS 30 & 34.  
 2. EQUIPMENT PLACED IN RAP AND GRAVEL BEDDING SHALL CONFORM TO CONSTRUCTION NOTES 1 & 2 ON SHEET 1.



**RIGHT EDGE PROFILE**

2



CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS



EMERGENCY SPILLWAY PROFILES


U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE








Designed <u>J. A. TIRRETT</u>	Date <u>10/71</u>	Approved by _____
Drawn <u>P. J. WILGA</u>	Sheet <u>10-27-21</u>	Title _____
Traced _____	Sheet <u>No. 13</u>	Drawing No. <u>MA-357 P</u>
Checked <u>G. T. GUTEAU</u>	Scale <u>1" = 20'</u>	of <u>30</u>

SCS-BIS-316 (Rev. 2-69)

B-11









ASTM A  
With Typ

heavy smooth  
shell treated  
so roofing felt




# CONSTRUCTION NOTES

- 1 Material in reservoir drain trash rack shall conform to Spec 581 for structural steel
- 2 Trash rack to be galvanized in accordance with Spec 582

## NOTE

For construction details see sheet 10



## BAR TYPES

## BILL OF MATERIAL RESERVOIR DRAIN TRASH RACK


ITEM	SIZE	LENGTH	QUANTITY
Angle ②	1/2" x 1/2" x 1/4"	6'-9"	3
Anchor Bolt	1/2" dia	2'-8"	6

## RESERVOIR DRAIN STEEL SCHEDULE


MARK	QUAN	SIZE	LENGTH	TYPE	B	C	D	TOTAL LENGTH
1	6	4	6'-9"	21	4-7	2-2		40.50
2	6	4	10'-3"	19	7-0	3-3	2-10	61.50
3	4	4	2'-9"	1				11.00
4	2	4	3'-0"	1				6.00
5	4	4	3'-6"	1				14.00
6	2	4	3'-9"	1				7.50
7	2	4	4'-3"	1				8.50
8	2	4	4'-9"	1				9.50
10	6	4	6'-9"	21	3-6	3-3		40.50
11	2	4	7'-6"	21	4-3	3-3		15.00
12	2	4	7'-9"	21	4-6	3-3		15.50
13	2	4	8'-3"	21	5-0	3-3		16.50
14	2	4	10'-3"	19	5-3	5-0	2-6	20.50
15	2	4	8'-3"	19	5-3	5-0	2-6	16.50
16	2	4	3'-9"	19	0-9	5-0	2-6	11.50
17	2	4	3'-3"	1				6.50
18	2	4	1'-0"	1				2.00
19	2	4	12'-3"	19	7-3	5-0	2-6	24.50

## QUANTITIES (this sheet only)

STEEL  
No 4 Bar 327.50 Ft = 218.77 lbs  
CONCRETE (Class 4000)  
Conduit I.D. 48" 3.8 Cu Yds




## TRASH RACK



## ANCHOR BOLT

ASTM A-276, 1/2" dia, Class 302 or 303,  
With Type-2 nuts and washers



## ISOMETRIC


## CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS

## RESERVOIR DRAIN INLET DETAILS


## U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

Designed J. A. TIBBETTS	Date 1/78	Approved By
Accepted F. J. WILDA	1-20-78	1-20-78
Drawn By	1-20-78	NA-357 P


U.S. GPO (APRIL 1964)





**ISOMETRIC VIEW**




**STOP LOG RETAINER**  
NOT TO SCALE




**STOP LOG DETAIL**  
NOT TO SCALE




**CONCRETE BEDDING**  
(48" POND DRAIN)



**REINFORCED CONCRETE WATER PIPE JOINT**



**PLAN**




**FRONT ELEVATION**

**SUGGESTED SUPPORT BLOCK**

**NOTE**  
The Contractor shall determine the number and size of the blocks






**ANCHOR BOLT**

Stainless Steel (Class 303, 303 Se  
or 304, Condition A)  
Supply with washers and Type 2 nuts

EYES - 4 REQ'D  
EYES IN (2) OF  
STOP LOGS


STOP LOG SHALL BE  
S&S 4" x 4" x 4'-7"  
(3 REQ'D)



**EDDING**

(IN)


ET



**IONT ELEVATION**

**ORT BLOCK**

I determine the  
locks



**BELL RING FITTING**

CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDISFIELD, MASSACHUSETTS			
STOP LOG & RESERVOIR DRAIN INLET DETAILS			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Designed: A. A. TIBBETTS	Date: 12/71	Approved by:	
Drawn: F. J. WILDA	Date: 12/71	File:	
Checked: C. H. BOWEN	Date: 12/71	Project No.:	MA-357 P

## LOG OF TEST HOLES

DN-1, ELEV. 1212.0		6/8/65	D.E.M.
0.0	1.5	TOPSOIL	
1.5	42.0	SAND, with gravel, about 10% fines, 15% fine sand, 20% medium sand, 30% coarse sand, 15% gravel, 2% cobbles, 2% boulders, angular to sub-rounded, maximum size 14", tan-brown, damp, high permeability, dense, base terrace.	SM-GW or SM-GH
42.0	59.0	SAND, silty with gravel, about 20% fines, 20% fine sand, 25% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, maximum size 6", olive-brown, damp, low permeability, to impermeable, dense to very dense, glacial till.	SM
59.0		Bottom of Hole.	

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	84
2.	1.5 - 3.0	115/6	50
3.	10.0 - 11.5	51	33

NOTE: Water level at 4.5 feet on 6/15/65. Hole dry at 28 feet on 6/16/65. Casing 28 feet. Hole at 29 feet on 6/15/65. Hole dry at 40 feet on 6/21/65. Pipe to 40 feet. Could not get tape below 35 feet on 7/14/65.

DN-2, ELEV. 1154.0		6/22/65	K.G.L.
0.0	2.0	TOPSOIL	
2.0	16.5	SAND, silty with gravel, about 18% fines, 32% fine sand, 25% medium sand, 15% coarse sand, 10% gravel, angular, hard, maximum size 3", brown, damp, to moist at 4.0, low permeability, dense to very dense, glacial till.	SM
16.5	52.0	SAND, silty with gravel, about 30% fines, 35% fine sand, 15% medium sand, 5% coarse sand, 10% gravel, 5% cobbles, angular, hard, maximum size 8", olive-brown, damp, impermeable, very dense, glacial till.	SM
52.0	59.0	BEDROCK, hard, unweathered Pre-Cambrian Gneiss, fractures mostly horizontal, spaced 18 to 30 inches apart, foliation dipping about 45 degrees.	
59.0		Bottom of Hole.	

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	37	67
2.	1.5 - 3.0	84	56
3.	3.0 - 4.5	63	78
4.	4.5 - 6.0	22	56
5.	12.0 - 13.0	160/8	67
6.	22.0 - 23.6	172	88
7.	27.0 - 28.5	180	77
8.	32.0 - 33.0	323/9	100
9.	42.0 - 42.5	200/7	94
10.	47.5 - 48.5	903/10	100

## Rock Core

No.	Depth	% Recovery
1.	52.0 - 54.0	100
2.	34.0 - 59.0	100

NOTE: Water level at 3 feet on 6/24/65, water level at 13 feet on 7/16/65.

DN-3, ELEV. 1124.8		6/18-21/65	K.G.L.
0.0	1.5	TOPSOIL	
1.5	13.0	SAND, silty with gravel, about 18% fines, 25% fine sand, 10% medium sand, 15% coarse sand, 32% gravel, angular, hard, with some decomposed Schist fragments, damp, low permeability, dense to very dense, colluvium.	SM
13.0	23.0	SAND, silty with gravel, about 20% fines, 15% fine sand, 25% medium sand, 10% coarse sand, 15% gravel, 5% cobbles, 10% boulders, angular, hard, maximum size 12", gray, damp, impermeable, very dense, glacial till.	SM
23.0	39.0	BEDROCK, gray, hard, quartz, biotite, feldspar gneiss, foliation dipping about 45 degrees, moderately to badly fractured, fractures spaced 1 to 8 inches, nearly horizontal and dipping about 45 degrees.	
39.0		Bottom of Hole.	

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	18	78
2.	1.5 - 3.0	30	89
3.	3.0 - 4.0	100/5	67
4.	10.0 - 11.5	84	45
5.	16.5 - 17.0	100/5	95

## Rock Core

No.	Depth	% Recovery
1.	23.0 - 24.0	100
2.	24.0 - 29.0	100
3.	29.0 - 34.0	100
4.	34.0 - 39.0	100

## Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	23.5 - 34.0	3 inches	25	18.3
2.	28.0 - 34.0	3 inches	25	15.3
3.	35.0 - 39.0	3 inches	25	.02

NOTE: Water level at 20.5 feet on 7/14/65, Hole dry to 14 feet on 6/21/65. Lost drilling water at 27.0 feet.

DN-4, ELEV. 1102.8		6/16/65	D.E.M.
0.0	2.0	TOPSOIL	
2.0	16.0	BEDROCK, hard, unweathered, gray gneiss, containing much quartz and biotite, fracturing mostly horizontal, some dipping about 60 degrees, foliation dipping about 45 degrees.	
16.0		Bottom of Hole.	

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	4	67
2.	1.5 - 2.1	104/7	100

## Rock Core

No.	Depth	% Recovery
1.	2.0 - 6.0	88
2.	6.0 - 8.5	100
3.	8.5 - 13.0	100
4.	13.0 - 16.0	94

## Pressure Test

No.	Depth	Psi	Q/gpm
1.	6.5 - 16.0	25	12

NOTE: Water level at 2 feet on 7/13/65.

DN-5, ELEV. 1089.7		5/17-18/65	K.G.L.
0.0	7.0	BOULDERS, and cobbles with gravel and sand, angular, hard, maximum size 14", high permeability, alluvium.	
7.0	17.0	BEDROCK, gray, hard, quartz, biotite, feldspar gneiss, foliation dipping about 60 degrees. Joints nearly horizontal and dipping about 45 degrees, spaced 1 to 30 inches.	
17.0		Bottom of Hole.	

## Rock Core

No.	Depth	% Recovery
1.	7.0 - 8.0	100
2.	8.0 - 13.0	100
3.	13.0 - 17.0	100

## Pressure Test

No.	Depth	Hole Size	Psi	Q/gpm
1.	9.0 - 17.0	3 inches	25	14.4
2.	12.0 - 17.0	3 inches	25	0.88

NOTE: Water level at 0.3 feet on 7/13/65

DN-6, ELEV. 1090.2		6/16/65	D.E.M.
0.0	1.5	TOPSOIL and BOULDERS	
1.5	9.0	SAND, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 30% coarse sand, 7% gravel, 2% cobbles, 1% boulders, angular to sub-rounded, maximum size 14", tan-brown, wet, low to medium permeability, dense, valley fill.	SM
9.0	23.0	BEDROCK, hard, gray, biotite gneiss, unweathered, with fractures mostly horizontal and tight but some dipping about 60 degrees, fractures spaced 10 to 18 inches apart, foliation dipping about 45 degrees.	
23.0		Bottom of Hole.	

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	1.5 - 3.0	36	77
2.	3.0 - 4.5	59	0
3.	7.0 - 8.5	33	44

## Rock Core

No.	Depth	% Recovery
1.	9.0 - 12.0	100
2.	12.0 - 13.0	10
3.	13.0 - 18.0	100
4.	18.0 - 23.0	100

## Pressure Test

No.	Depth	Psi	Q/gpm
1.	10.0 - 23.0	25	1

NOTE: Water level at 0.5 feet on 7/13/65.

DN-7, ELEV. 1088.0			
0.0	1.5	TOPSOIL	
1.5	12.0	SAND, sand, 7% cobbles, maximum to 1mp	
12.0	22.0	BEDROCK to 30	
22.0		dipping	
		Bottom	

## Standard Penetration Test

No.	Depth	% Recovery
1.		
2.		
3.		

## Rock Core

No.	Depth	% Recovery
1.		
2.		
3.		

## Pressure Test

No.	Depth	Psi	Q/gpm
1.			
2.			
3.			

NOTE:

DN-8, ELEV. 1124.5			
0.0	1.5	TOPSOIL	
1.5	5.0	SAND, fine s	
5.0	18.0	maxim	
18.0		perme	
		BEDROCK	
		mostly	
		spaced	
		80 deg	
		Bottom	

## Standard Penetration Test

No.	Depth	% Recovery
1.		
2.		
3.		

## Rock Core

No.	Depth	% Recovery
1.		
2.		
3.		

## Pressure Test

No.	Depth	Psi	Q/gpm
1.			
2.			
3.			

NOTE:

DN-9, ELEV. 1136.0			
0.0	12.0	BOULDER	
12.0	30.0	7% fine	
30.0		boulders	
		maximum	
		dense,	
		BEDROCK	
		weather	
		planes	
		about	
		Folia	
		Bottom	

## Standard Penetration Test

No.	Depth	% Recovery
1.		
2.		
3.		

## Rock Core

No.	Depth	% Recovery
1.		
2.		
3.		

## Pressure Test

No.	Depth	Psi	Q/gpm
1.			
2.			
3.			

NOTE:

D.E.M. 4/10-14/65 D.E.M.  
DH-7 ELEV. 1488.0  
D.O 1.3 TOPSOIL and DUFF  
1.5 12.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 15% coarse sand, 15% gravel, 7% cobbles, 3% boulders, soft, highly weathered, maximum size 16", tan-brown, damp, low permeability to impermeable, dense to very dense, glacial till.  
BEDROCK, dark gray, biotite gneiss, hard, fractures 6 to 30 inches apart, mostly horizontal, foliation dipping about 80 degrees.  
Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	33
2.	1.5 - 3.0	23	77
3.	3.0 - 4.5	33	77

Rock Core

No.	Depth	% Recovery
1.	12.0 - 14.0	90
2.	14.0 - 19.0	100
3.	19.0 - 22.0	96

Pressure Test

No.	Depth	Psi	Q/apm
1.	13.0 - 22.0	25	trace

NOTE: Water level at 7 feet on 7/14/65.

K.G.L.  
sd sand, angular, blitty, alluvium, s, feldspar gneiss, joints nearly roon, spaced 1 to 30

D.E.M. 6/15/65 D.E.M.  
DH-8 ELEV. 1124.5  
D.O 1.5 TOPSOIL  
1.5 5.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 15% medium sand, 15% coarse sand, 15% gravel, 7% cobbles, 3% boulders, soft and weathered, maximum size 16", tan-brown, damp, low to medium permeability, dense to very dense, glacial till.  
BEDROCK, hard, dark gray biotite gneiss, fractures mostly horizontal, some dipping about 60 degrees, spaced 8 to 20 inches apart, foliation dipping about 80 degrees.  
Bottom of Hole.

Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	44
2.	1.5 - 3.0	28	777
3.	3.0 - 4.5	128/12	55

Rock Core

No.	Depth	% Recovery
1.	5.0 - 9.0	100
2.	9.0 - 14.0	81
3.	14.0 - 18.0	70

Pressure Test

No.	Depth	Psi	Q/apm
1.	7.0 - 12.0	20	packer failed
2.	12.0 - 18.0	20	10

NOTE: Water level-no measurement. Packers stuck in hole.

Q/apm  
23 14.4  
25 0.88

D.E.M.  
s, fines, 25% coarse sand, 7% angular to sub-angular, wet, low to fill.  
s, unweathered, and tight but some spaced 10 to 18 out 45 degrees.

D.E.M. 6/16/65 D.E.M.  
DH-9 ELEV. 1136.0  
D.O 12.0 BOULDERS, with silty sand matrix, about 3% fines, 7% fine sand, 5% medium sand, 5% coarse sand, 80% boulders, angular to sub-angular, hard, unweathered, maximum size 24", gray, damp, high permeability, dense, slope wash and residual.  
BEDROCK, hard, dark gray, biotite gneiss, moderately weathered at top 2 feet, with separation of foliation planes, fractures mostly horizontal, some dipping about 60 degrees, spaced 10 to 20 inches apart.  
Foliation dipping about 80 degrees.  
Bottom of Hole.

Rock Core

No.	Depth	% Recovery
1.	11.0 - 12.0	100
2.	12.0 - 17.0	100
3.	17.0 - 22.0	80
4.	22.0 - 25.0	83
5.	25.0 - 30.0	100

Pressure Test

No.	Depth	Psi	Q/apm
1.	14.0 - 30.0	25	0

NOTE: Water level at 2.5 feet on 7/14/65.

Q/apm  
1  
7/13/65.

LEGEND  
TEST HOLE NUMBERING SYSTEM

Centerline of dam  
Borrow Area  
Emergency Spillway  
Centerline of Outlet Structure  
Stream Channel  
Relief Wells  
1 - 99  
101-199  
201-299  
301-399  
401-499  
501-599  
601-699  
701-799

DH-Drill Hole  
TP-Test Pits

UNIFIED SOIL CLASSIFICATION SYSTEM SYMBOLS

GW Well graded gravel; gravel-sand mixtures  
GP Poorly graded gravels  
GM Silty gravels; gravel-and-silt mixtures  
GC Clayey gravels; gravel-and-clay-mixtures  
SW Well graded sands; sand-gravel mixtures  
SP Poorly graded sands  
SM Silty sands; sand-silt mixtures  
SC Clayey sands; sand-clay mixtures  
ML Silty, silty, very fine sand; sandy or clayey silt  
CL Clays of low to medium plasticity; silty, sandy or gravelly clays  
CH Clays of high plasticity; fat clays  
MH Elastic silts; micaceous or diatomaceous silts  
OL Organic silts and organic silty clays of low plasticity  
OH Organic clays or silts of medium to high plasticity

All Soil and Rock description and classifications were determined by visual examination in the field.

When possible, all holes were advanced by continuous drive sampling to 4.0 feet. Holes were then advanced by NX diamond drilling between drive samples. Drive samples taken with a 3-inch O.D. split spoon sampler.

Location of Test Holes shown on Plan View

NOTE: Water levels do not necessarily represent static water levels.

Psi = pounds per square inch water pressure  
Q/apm = quantity of water in gallons per minute  
K/ft/day = permeability in feet per day  
D.S. = Disturbed Sample

The Unified Soil Classification System classifies only those materials which are smaller than three inches.

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

LOGS OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Investigated Checked D. MILLER	Date 1965	Approved by Title
Drawn		Title
Traced		Sheet No. 30 of 30
Checked D. MILLER	2-199	Drawing No. MA-357 P

## LOG OF TEST HOLES

DN-10, ELEV. 1154.8 5/17-18/65 D.E.M.  
 0.0 10.0 COARSE, GRAVEL and Boulders, about 3% fines, 7% fine sand, 3% medium sand, 5% coarse sand, 50% gravel, 10% cobbles, 10% boulders, sub-round to angular, hard, slope weak.  
 10.0 20.0 BEDROCK, gray, hard, quartz, biotite feldspar gneiss, foliation dipping about 45 degrees, joints spaced 1/2 to 1 inch dipping about 30 degrees.  
 20.0 Bottom of Hole.

## Rock Core

No.	Depth	% Recovery
1.	10.0 - 12.0	100
2.	12.0 - 15.0	100
3.	15.0 - 17.0	100
4.	17.0 - 20.0	100

## Pressure Test

No.	Depth	Hole Size	Psi	Q/Inch
1.	12.0 - 20.0	3 inches	25	14.8
2.	16.5 - 20.0	3 inches	25	4.20

NOTE: Water level at 11 feet on 7/14/65

DN-101, ELEV. 1214.2 6/18-24/65 D.E.M.

0.0 1.5 TOPSOIL  
 1.5 40.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, soft, maximum size 42", olive-brown, damp, low permeability, dense to very dense, glacial till.  
 40.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	17	77
2.	1.5 - 3.0	15	88
3.	3.0 - 4.5	212	83
4.	4.5 - 5.2	196/8	37
5.	10.0 - 11.5	176	88
6.	15.0 - 16.5	176	50
7.	20.0 - 20.1	100/1	0
8.	30.0 - 30.9	198/9	10
9.	35.0 - 36.5	154	61
10.	38.5 - 40.0	276	33

NOTE: Water level at 25 feet on 6/24/65, water level at 13.5 feet on 7/14/65. Boulders from 35.0-38.5 feet.

DN-102, ELEV. 1160.0 6/21-24/65 D.E.M.

0.0 1.5 TOPSOIL and DUFF  
 1.5 30.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, angular to sub-rounded, maximum size 24", olive-brown, damp, low permeability to impermeable, very dense, glacial till.  
 30.0 40.0 BEDROCK, gray biotite gneiss, hard, fractures spaced 8 to 18 inches apart, mostly horizontal, some dipping about 70 degrees, foliation dipping about 70 degrees.  
 40.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	71	77
2.	1.5 - 3.0	145	67
3.	3.0 - 4.5	71	77
4.	4.5 - 6.0	74	94
5.	10.0 - 11.5	53	77
6.	15.0 - 16.5	697	94
7.	20.0 - 21.5	683	88

## Rock Core

No.	Depth	% Recovery
1.	30.0 - 34.0	100
2.	34.0 - 40.0	100

NOTE: Water level at 7 feet on 6/23/65, water level at 8 feet on 6/24/65, water level at 7.5 feet on 7/14/65.

DN-201, ELEV. 1181.3

6/23-24/65

D.E.M.

0.0 1.5 TOPSOIL  
 1.5 10.0 SAND, silty with gravel, about 18% fines, 37% fine sand, 25% medium sand, 15% coarse sand, 7% gravel, 2% cobbles, 1% boulders, angular, hard, maximum size 18", olive-brown, damp, low permeability, dense, slope weak.  
 10.0 42.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, hard, angular, to sub-angular, maximum size 8", olive-brown, damp, impermeable, very dense, glacial till.  
 42.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	2	67
2.	1.5 - 3.0	26	77
3.	3.0 - 4.5	38	77
4.	4.5 - 6.0	50	44
5.	10.0 - 11.5	48	44
6.	15.0 - 16.5	44	39
7.	20.0 - 21.5	59	0
8.	25.0 - 26.5	96	55
9.	30.0 - 31.5	73	34
10.	35.0 - 36.5	61	34

NOTE: Water level at 5 feet on 6/24/65, water level at 16.5 feet on 7/14/65.

DN-202, ELEV. 1182.5

6/23-24/65

R.G.L.

0.0 4.0 TOPSOIL  
 4.0 12.0 SAND, silty with gravel, about 15% fines, 20% fine sand, 25% medium sand, 20% coarse sand, 15% gravel, 5% cobbles, angular, hard, maximum size 6", olive-brown, damp, low permeability to impermeable, medium to dense, some terraces.  
 12.0 42.0 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, 4% cobbles, 1% boulders, hard, angular, maximum size 18", olive-brown, damp, impermeable, very dense, glacial till.  
 42.0 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	2	78
2.	1.5 - 3.0	4	78
3.	3.0 - 4.5	4	78
4.	4.5 - 6.0	5	78
5.	10.0 - 11.5	29	78
6.	15.0 - 16.5	130/8	67
7.	20.0 - 21.5	96	77
8.	25.0 - 26.5	110	100
9.	30.0 - 31.5	131	67
10.	35.0 - 36.5	116	77
11.	40.5 - 42.0	163	34

NOTE: Water level at 13 feet on 7/14/65

DN-203, ELEV. 1163.1

6/24/65

D.E.M.

0.0 1.5 TOPSOIL  
 1.5 41.5 SAND, silty with gravel, about 20% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 10% gravel, 7% cobbles, 3% boulders, angular, hard, maximum size 16", brown, damp, low to medium permeability, loose to very dense.  
 41.5 Bottom of Hole.

## Standard Penetration Test

No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	3	88
2.	1.5 - 3.0	2	67
3.	3.0 - 4.5	6	67
4.	4.5 - 6.0	8	88
5.	15.0 - 16.5	16	73
6.	20.0 - 21.5	36	77
7.	25.0 - 26.5	42	50
8.	30.0 - 31.5	34	72
9.	35.0 - 36.5	101	44
10.	40.0 - 41.5	137	77

NOTE: Water level at 15 feet on 7/14/65.





DN-613	Elev. 1181.7	8/6 to 8/10/70	DM
0.0	1.0	TOPSOIL.	
1.0	28.0	SAND, silty with gravel, about 45% fines, 10% fine sand, 10% medium sand, 30% coarse sand, 5% gravel, subangular, 1-inch maximum size, olive-brown, damp, low permeability, dense to very dense, GLACIAL TILL.	SM
28.0		Bottom of Hole.	
Drive Samples			
No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.0'	2	100
2.	1.5 - 3.0'	6	100
3.	3.0 - 4.5'	11	90
4.	4.5 - 6.0'	22	90
5.	10.0 - 11.5'	30	80
6.	15.0 - 15.8'	165/9" ref.	67
7.	20.0 - 20.9'	175/8" ref.	70
8.	25.0 - 25.5'	100/6" ref.	60

DN-615	Elev. 1183.28	8/3 to 8/17/70	PAB
0.0	1.0	TOPSOIL.	
1.0	3.0	TOPSOIL.	
3.0	15.0	SAND, silty with gravel, about 25% fines, 15% fine sand, 10% medium sand, 40% coarse sand, 10% gravel, subangular, some particles decomposed, olive-brown, moist, low permeability, very dense, Weathered Till.	SM
15.0	18.0	SAND, silty with gravel, about 25% fines, 15% fine sand, 10% medium sand, 30% coarse sand, 20% gravel, decomposed rock particles, olive-gray, moist, low permeability, very dense, GLACIAL TILL.	SM
18.0	29.0	HEMLOCK, gray, biotite hornblende gneiss, foliations dipping about 70°. From 18 to 21 feet, highly fractured. Fractures spaced about 1/2-inch to 2-inches apart. 21 to 29 feet -- moderately fractured. Fractures spaced about 8 to 14 inches.	
29.0		Bottom of Hole.	

<u>Drive Samples</u>			
No.	Depth	Blows/ft.	<u>% Recovery</u>
1.	1.0 - 2.4'	98/5" ref.	66
2.	4.0 - 5.5'	101	66
3.	10.0 - 11.5'	71	66
4.	15.0 - 16.5'	131/6" ref.	66

Rock Core Runs		
No.	Depth	Recovery
1.	18.0 -19.0'	50
2.	19.0 -20.0'	90
3.	20.0 -24.0'	100
4.	24.0 -29.0'	90

<u>Permeability Test</u>				
<u>No.</u>	<u>Depth</u>	<u>Hole Size</u>	<u>Head</u>	<u>Loss</u>
1.	10.5'	2" x 18"	Ground	Slight.

o head - pipe above ground

DN-616	Elev. 1196.01	8/5 to 8/6/70	PAB
0.0	2.0	No drilling - Removed boulders by hand.	
2.0	4.0	TOPSOIL.	
4.0	8.0	SAND, silty with gravel, about 25% fines, 25% fine sand, 20% medium sand, 15% coarse sand, 15% gravel, subangular, some decomposed rock particles, 1/2-inch maximum size, olive-brown, moist, low permeability, dense, Weathered Till.	SM
8.0	15.0	SILT, sandy with about 55% fines, 22% fine sand, 15% medium sand, 5% coarse sand, 5% gravel, 1/2-inch maximum size, olive brown, moist, low permeability, medium dense, GLACIAL TILL.	SM
15.0	28.0	HEMLOCK, gray biotite hornblende gneiss, foliations dipping about 70°. Fractures are about 12 to 18-inches apart -- mostly horizontal; all tight.	
28.0		Bottom of Hole.	

<u>Drive Samples</u>			
<u>No.</u>	<u>Depth</u>	<u>Blows/ft.</u>	<u>% Recovery</u>
1.	2.0 - 3.5'	39	81
2.	3.5' - 5.0'	50	66
3.	10.0' - 11.5'	29	44

Rock Core Runs		% Recovery
No.	Depth	
1.	15.0 - 15.9'	88
2.	15.9 - 20.0'	95
3.	20.0 - 25.0'	100
4.	25.0 - 28.0'	100

DN-617	Elev. 1191.98	8/6 to 8/7/70	PAB
0.0	3.0	TOPSOIL.	
3.0	16.0	SAND, silty with gravel, about 20% fines, 25% fine sand, 25% medium sand, 15% coarse sand, 15% gravel, decomposed rock, 1-inch maximum size, olive-brown, wet, medium permeability, very dense, GLACIAL TILL.	SM
	8.5 to 10.0	BOULDER.	
	14.9 to 16.0	BOULDER.	
16.0	28.0	HEMLOCK, gray, biotite hornblende gneiss. Foliations dipping about 70°. Moderately fractured -- spaced about 12 to 18 inches apart -- mostly horizontal; all tight.	
28.0		Bottom of Hole.	

Drive Samples			
No.	Depth	Blows/ft.	% Recovery
1.	0.5 - 2.0'	23	78
2.	2.0 - 3.0'	96/2" ref.	33
3.	4.5 - 6.0'	72	78
4.	10.0 - 11.5'	71	66

Rock Core Runs		
No.	Depth	% Recovery
1.	14.9 - 18.0'	91
2.	18.0 - 23.0'	100
3.	23.0 - 28.0'	100

NOTE: Water level at 5.5 feet on 8/6/70.

DN-618	Elev. 1185.72	8/10 to 8/11/70	PAB
0.0	3.5	TOPSOIL.	
3.5	10.0	SAND, silty with gravel, about 15% fines, 20% fine sand, 25% medium sand, 25% coarse sand, 15% gravel, subangular, with some decomposed rock bits, 3/4-inch maximum size, light olive-brown, moist, low permeability, very dense, GLACIAL TILL.	SM
6.0	8.0	Cobbles and Boulders.	
10.0	26.0	HEMLOCK -- gray biotite hornblende gneiss, foliations dipping about 70°. Moderately fractured. Fractures spaced about 6 to 14 inches apart, mostly horizontal.	
26.0		Bottom of Hole.	

Drive Samples		Blows/ft.	% Recovery
No.	Depth		
1.	0.0 - 1.5'	18	66
2.	1.5 - 2.9'	101/11" ref.	78
3.	5.0 - 6.5'	129	66

Rock Core Runs		Recovery
No.	Depth	
1.	10.0 - 13.5'	76
2.	13.5 - 18.5'	95
3.	18.5 - 23.5'	100
4.	23.5 - 26.0'	100

NOTE: Water level at 6.92 feet on 8/11/70.

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

LOGS OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Investigated by Geotechnical S. HILL & P. BRIDGES R/72	Date 8/7/70
Typed by J. LORING	Approved by
Traced	Checked
Checked by R. HILL	MA - 357 P

SCS-312B (APRIL 1963)

B-17

DM-619	Elev. 1172.67	8/11 to 8/12/70	PAB
0.0	3.0	TOPSOIL AND ROOTMAT.	
3.0	11.5	SILTY SAND, gravelly, about 15% fines, 10% fine sand, 25% medium sand, 30% coarse sand, 20% gravel, subangular, 3/4-inch maximum size, olive-brown, moist, medium-low permeability, very dense, GLACIAL TILL.	SM
	6 to 10'	BOULDER.	
	10.5 to 11.5'	BOULDER.	
11.5	25.0	BECKROCK, grey, biotite hornblende gneiss, foliations dipping about 70°. Highly fractured. Fractures spaced about 1 to 8 inches apart. Fractures are not all tight.	
25.0		Bottom of Hole.	
<u>Drive Samples</u>			
No.	Depth	Blows/ft.	% Recovery
1.	0.5 - 2.0'	25	65
2.	4.0 - 5.5'	99	66
<u>Rock Core Runs</u>			
No.	Depth	% Recovery	
1.	6.0 - 10.0'	58	
2.	11.5 - 16.5'	97	
3.	16.5 - 21.5'	100	
4.	21.5 - 25.0'	100	

DM-620	Elev. 1158.73	8/12 to 8/12/70	PAB
0.0	1.5	TOPSOIL, ROOTS.	
1.5	5.0	BOULDER.	
5.0	9.5	SAND, silty, with gravel, about 20% fines, 15% fine sand, 25% medium sand, 30% coarse sand, 10% gravel, subangular, 1-inch maximum size, olive-brown, moist, medium-low permeability, dense, GLACIAL TILL.	SM
9.5	17.5	BECKROCK, gray, biotite, hornblende, gneiss. Foliations dipping about 70°. Highly fractured with sand seams. Fractures spaced 1/2-inch to 6 inches apart.	
17.5		Bottom of Hole.	
<u>Drive Samples</u>			
	<u>No.</u>	<u>Depth</u>	<u>Blows/ft.</u> <u>% Recovery</u>
	1.	1.0 - 1.5'	18      100
	2.	5.0 - 5.8'	60/10" ref.      78
<u>Rock Core Runs</u>			
	<u>No.</u>	<u>Depth</u>	<u>% Recovery</u>
	1.	9.5 - 12.5'	93
	2.	12.5 - 17.5'	83
NOTE: Water level at 9.5 feet on 8/12/70.			

DM-621	Elev. 1171.82	8/13 to 8/13/70	DM
0.0	1.5	TOPSOIL.	
1.5	9.0	COBBLES and BOULDERS, with some silt and gravel matrix, UNGLACIAL DRIFT.	
9.0	21.0	BECKROCK, gray, biotite hornblende gneiss, moderately fractured, fractures spaced 12 to 18 inches apart, most fractures dipping about 70 degrees, some horizontal.	
21.0		Bottom of Hole.	
<u>Drive Samples</u>			
No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5	4	100
2.	1.5 - 2.2	41/7" ref.	40
<u>Rock Core Runs</u>			
No.	Depth	% Recovery	
1.	9.0 - 11.0'	75	
2.	11.0 - 16.0'	100	
3.	16.0 - 21.0'	93	
NOTE: Water level at 9 feet on 8/13/70.			

DM-622	Elev. 1179.3	8/13 to 8/14/70	DM												
0.0	11.0	COBBLES and BOULDERS, with some silt and gravel matrix, unable to obtain drive samples. UNGLACIAL DRIFT.													
11.0	21.0	BECKROCK, gray, biotite hornblende gneiss, moderately fractured. Fractures spaced 12 to 18 inches apart. Most fractures dipping about 70°. Some horizontal.													
21.0		Bottom of Hole.													
<table> <tr> <th>Rock Core Run</th><th>No.</th><th>Depth</th><th>% Recovery</th></tr> <tr> <td>1.</td><td>11.0 - 16.0'</td><td>80</td><td></td></tr> <tr> <td>2.</td><td>16.0 - 21.0'</td><td>100</td><td></td></tr> </table>				Rock Core Run	No.	Depth	% Recovery	1.	11.0 - 16.0'	80		2.	16.0 - 21.0'	100	
Rock Core Run	No.	Depth	% Recovery												
1.	11.0 - 16.0'	80													
2.	16.0 - 21.0'	100													

DM-351	Elev. 1101.8	8/12 to 8/12/70	DM
0.0	1.5	TOPSOIL and ROOTMAT.	
1.5	6.5	SAND, with gravel, about 15% fines, 10% fine sand, 10% medium sand, 50% coarse sand, 20% gravel, <span style="float:right">TP-651</span> subangular, 2-inch maximum size, <span style="float:right">0.0</span> red-brown, damp, medium permeability, dense, FLOODPLAIN. <span style="float:right">1.0</span>	
6.5	16.5	BECKROCK, gray, biotite hornblende gneiss, moderately fractured, fractures dipping about 60 degrees. Some horizontal. All fractures tight. BECKROCK.	
16.5		Bottom of Hole.	10.0
<u>Drive Samples</u>			
	<u>No.</u>	<u>Depth</u>	<u>Blows/ft.</u> <u>% Recovery</u>
	1.	0.0 - 1.5'	15 100
	2.	1.5 - 3.0'	82 70
	3.	3.0 - 4.5'	24 80
	4.	5.0 - 5.3'	100/4" ref. 100
			<span style="float:right">TP-652</span> <span style="float:right">0.0</span> <span style="float:right">1.0</span> <span style="float:right">0.5</span>
<u>Rock Core Runs</u>			
	<u>No.</u>	<u>Depth</u>	<u>% Recovery</u>
	1.	16.5 - 10.5'	95
	2.	10.5 - 16.5'	70
NOTE: Water level at 2.75 on 8/12/70.			

DM-352	Elev. 1098.4	8/13 to 8/13/70	PAB
0.0	2.0	TOPSOIL.	10.0
2.0	3.5	SAND, silty with gravel, about 25% fines, 20% fine sand, 25% medium sand, 20% coarse sand, 10% gravel, subangular, 3/4-inch maximum size, red-brown, damp, medium permeability, medium dense, Floodplain Deposits.	TP-653 0.0 1.0
3.5	14.5	BECKROCK, gray, biotite hornblende gneiss, foliations dipping about 80°. Highly fractured from 3'6" to 8'6". Fractures spaced about 3 to 5 inches apart. Very slightly fractured from 8'6" to 14'6".	
14.5		Bottom of Hole.	
<u>Drive Samples</u>			
No.	Depth	Blows/ft.	% Recovery
1.	0.0 - 1.5'	17	78
2.	1.5 - 3.0'	26	83
3.	3.0 - 3.5'	100/6" ref.	27
TP-654 0.0			
1.0			
<u>Rock Core Run</u>			
No.	Depth	% Recovery	
1.	3.5 - 8.5'	73	
2.	8.5 - 14.5'	100	
NOTE: Water level at 4.58 feet on 8/13/70.			

DM-353	Elev. 1095.2	8/13 to 8/14/70	PAB	
0.0	1.5	TOPSOIL and ROOT MAT.		10.0
1.5	7.0	SAND, with gravels, about 5% fines, 15% fine sand, 35% medium sand, 30% coarse sand, 15% gravel, subangular, 3/4-inch maximum size, red-brown, damp, high permeability, dense, Floodplain Deposits.	SP SM	TP-655 0.0 1.0
7.0	17.0	BECKROCK, gray, biotite hornblende gneiss, moderately fractured, foliations dipping about 60°. Most fractures are horizontal. All tight. BECKROCK.		
17.0		Bottom of Boring.		
		<u>Drive Samples</u>		12.0
		<u>No.</u> <u>Depth</u>	<u>Blows/ft.</u> <u>% Recovery</u>	
		1.      0.0 - 1.5'	7      88	TP-655
		2.      1.5 - 3.0'	28      83	
		3.      3.0 - 4.5'	98      83	0.0
		4.      5.0 - 5.5'	100/6" ref.      33	1.0
		<u>Rock Core Runs</u>		
		<u>No.</u> <u>Depth</u>	<u>% Recovery</u>	
		1.      7.0 - 12.0'	100	
		2.      12.0 - 17.0'	100	

DM-623	Elev. 1179.3	8/13 to 8/14/70	DM
0.0	11.0	COBBLES and BOULDERS, with some silt and gravel matrix, unable to obtain drive samples. UNGLACIAL DRIFT.	TP-657
			0.0
			3.0
11.0	21.0	BECKROCK, gray, biotite hornblende gneiss, moderately fractured. Fractures spaced 12 to 18 inches apart. Most fractures dipping about 70°. Some horizontal.	
21.0		Bottom of Hole.	10.0



8/12/70 DEM

TEST PITS  
CLAM LAKE, CLAM RIVER WATERSHED

ut 1/2 fines,  
um sand, SP  
ravel, SP  
um size,  
a permeability,  
  
hornblende  
cured, fractures  
as. Some  
urea tight. BEDROCK.

ft. % Recovery  
100  
70  
80  
1/2 ref. 100

SP

2.75 on 8/12/70.

3/70 PAB

1, about 25%  
25% medium sand, SM  
ravel, subangular,  
red-brown, damp,  
silty dense,

hornblende gneiss,  
at 80". Highly  
8'6". Fractures  
ches apart. Vary  
a 8'6" to 14'6".

ft. % Recovery  
75  
83  
3/6 ref. 27

covery

73

100

1.58 feet on

4/70 PAB

ut 5% fines,  
um sand, 30%  
1, subangular, SP  
red-brown, SM  
, dense,

hornblende  
cured,  
at 60". Most  
d. All tight.

ft. % Recovery  
88  
83  
83  
1/6 ref. 33

very

10

10

TP-651 6/8 to 6/8/71 DEM  
0.0 1.0 TOPSOIL AND ROOTMAT.  
1.0 10.0 SAND, silty with gravel, about  
25% fines, 15% fine sand, 20% medium  
sand, 30% coarse sand, 10% gravel,  
sub-angular, 18-inch maximum size,  
olive-brown, damp, low permeability,  
very dense, GLACIAL TILL est. 20% +  
6-inch size.  
Disturbed Sample: 3 to 9 feet.  
10.0 Bottom of Pit.

TP-652 6/8 to 6/8/71 DEM  
0.0 0.5 TOPSOIL and ROOTMAT.  
0.5 10.0 SAND and gravel, some silt, about 10%  
fines, 10% fine sand, 15% medium sand,  
35% coarse sand, 30% gravel, sub-  
rounded, 24-inch maximum size, tan-  
brown, damp, medium-high permeability,  
dense, Ice contact sand and gravel  
with cobbles and boulders to P 6'  
est. 40% cobbles and boulders then  
about 25% + 6-inch size. Some rock  
fragments highly weathered.  
Disturbed Sample: 3 to 10 feet.  
10.0 Bottom of Pit.

TP-653 6/8 to 6/8/71 DEM  
0.0 1.0 TOPSOIL and ROOTMAT.  
1.0 10.0 SAND and GRAVEL, some silt, about 10%  
fines, 10% fine sand, 15% medium sand,  
35% coarse sand, 30% gravel, sub-  
rounded, 18-inch maximum size, tan-  
brown, damp, medium-high, dense, Ice  
contact sand and gravel, est. 25% +  
6-inch size. Some rock fragments  
highly weathered.  
Disturbed Sample: 2 to 9 feet.  
Bottom of Pit.

TP-654 6/8 to 6/8/71 DEM  
0.0 1.0 TOPSOIL and ROOTMAT.  
1.0 10.0 SAND and GRAVEL, with some silt, about  
10% fines, 10% fine sand, 15% medium  
sand, 35% coarse sand, 30% gravel,  
sub-rounded, 20-inch maximum size, tan-  
brown, damp, medium-high permeability,  
dense, Ice contact sand and gravel,  
est. 25% + 6-inch size. Some rock frag-  
ments highly weathered.  
Disturbed Sample: 3 to 10 feet.  
Bottom of Pit.

TP-655 6/10/71 DEM  
0.0 1.0 TOPSOIL and ROOTMAT.  
1.0 12.0 SAND, silty with gravel and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 15-inch maximum  
size, olive-brown to 7 foot then blue-  
grey, damp to wet, low permeability,  
very dense, GLACIAL TILL weathered to  
7 foot with water. Seep at 7 foot.  
Disturbed Sample 7 to 11 feet.  
12.0 Bottom of Pit.

TP-656 6/10/71 DEM  
0.0 1.0 TOPSOIL and ROOTMAT.  
1.0 12.0 SAND, silty with gravel and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 9-inch maximum  
size, olive-brown, damp, low permea-  
bility, very dense, GLACIAL TILL.  
Disturbed Sample 2 to 12 feet.  
12.0 Bottom of Pit.

TP-657 6/10/71 DEM  
0.0 3.0 TOPSOIL and ROOTMAT and FILL.  
3.0 10.0 SAND, silty with gravel and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 14-inch maximum  
size, olive-brown, damp, low permea-  
bility, very dense, GLACIAL TILL.  
Disturbed Sample: 3 to 9 feet.  
10.0 Bottom of Pit.

Test Pits (Cont'd) Clam River Watershed -- Clam Lake Site

TP-658 6/10/71 DEM  
0.0 7.0 COBBLES and Boulders, with sand and  
gravel, matrix water entering pit  
at est. 5 gpm.  
7.0 Bedrock and bottom of pit.

TP-659 6/10/71 DEM  
0.0 1.0 TOPSOIL and ROOT MAT.  
1.0 3.0 SAND, silty with gravel and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 14-inch maximum  
size, red-brown, wet, medium permea-  
bility, loose, WEATHERED GLACIAL TILL.  
SH

TP-660 6/10/71 DEM  
0.0 1.0 TOPSOIL and ROOT MAT.  
1.0 5.0 SAND, silty with gravel and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 36-inch maximum  
size, red-brown, wet, medium permea-  
bility, loose, WEATHERED GLACIAL TILL.  
BEDROCK and BOTTOM OF PIT.

TP-661 6/10/71 DEM  
0.0 1.0 TOPSOIL and ROOT MAT.  
1.0 11.0 SAND, silty with gravel, and cobbles,  
about 25% fines, 15% fine sand, 20%  
medium sand, 30% coarse sand, 10%  
gravel, sub-angular, 22-inch maximum  
size, olive-brown, damp, low permea-  
bility, very dense, GLACIAL TILL.  
Bottom of Pit.

CLAM RIVER WATERSHED PROJECT  
CLAM LAKE MULTIPLE-PURPOSE DAM  
SANDSFIELD, MASSACHUSETTS

LOGS OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Investigator D. M. HILL & P. R. BRIDGEMAN R/70	Date 6/10/71	Approved by
Title N. LONCEAN		
Traced	Sheet No. 33	Drawing No. MA 357-P
Checked C. M. DOORE	of 36	

SCS-312B (APRIL 1963)

B-N

## LOG OF TEST HOLE

**TP-71, ELEV. 1182.3** 6/24/65 E.G.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 20% fines, 20% fine sand, 25% medium sand, 10% coarse sand, 15% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 10", damp, low permeability, very dense, glacial till. Bottom of Pit.

D.S. 157.1, 3.0-10.0 0% larger than 6" discarded.

NOTE: Water level at 7.3' on 7/14/65

**TP-231, ELEV. 1189.1** 6/24/65 E.G.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 15% fines, 25% fine sand, 15% medium sand, 5% coarse sand, 30% gravel, 10% cobbles, 5% boulders, angular, hard, maximum size 10", olive-brown, damp, low permeability, very dense, ground moraine. Bottom of Pit.

D.S. 231.1, 3.0-10.0 5% larger than 6" discarded.

NOTE: Water level at 8' on 7/14/65

**TP-232, ELEV. 1151.0** 6/25/65 E.G.L.  
 0.0 2.5 TOPSOIL  
 2.5 10.0 SAND, gravelly with silt, about 10% fines, 25% fine sand, 15% medium sand, 5% coarse sand, 30% gravel, 10% cobbles, 5% boulders, angular to sub-rounded, maximum size 24", brown, moist to wet, low to medium permeability, dense, ground moraine. Bottom of Pit.

D.S. 232.1 (2 bags) 2.5-10.0 8% larger than 6" discarded.

NOTE: Water level at 0.3' on 7/14/65.

**TP-233, ELEV. 1143.3** 6/25/65 E.G.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 25% fines, 35% fine sand, 15% medium sand, 5% coarse sand, 15% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 13", olive-brown, damp, impervious, very dense, glacial till. Bottom of Pit.

D.S. 233.1, 3.0-10.0 5% larger than 6" discarded.

NOTE: Water level dry on 7/14/65.

**TP-234, ELEV. 1199.3** 6/25/65 E.G.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 10% fines, 25% fine sand, 10% medium sand, 10% coarse sand, 35% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 14", brown, damp, low permeability, very dense, ground moraine. Bottom of Pit.

D.S. 234.1, 3.0-10.0 0% larger than 6" discarded.

NOTE: Water level dry on 7/14/65.

**TP-235, ELEV. 1196.6** 6/25/65 E.G.L.  
 0.0 3.0 BULKHEAD TOPSOIL  
 3.0 10.0 SAND, gravelly with cobbles, about 7% fines, 20% fine sand, 15% medium sand, 10% coarse sand, 35% gravel, 15% cobbles, 5% boulders, sub-angular, maximum size 12", brown, damp, high permeability, dense, base terrace. Bottom of Pit.

D.S. 235.1 (2 bags) 3.0-10.0, 0% larger than 6" discarded.

NOTE: Water dry on 7/14/65.

**TP-236, ELEV. 1175.6** 6/25/65 E.G.L.  
 0.0 3.0 TOPSOIL  
 3.0 10.0 SAND, silty with gravel, about 25% fines, 35% fine sand, 10% medium sand, 5% coarse sand, 25% gravel, 5% cobbles, 5% boulders, angular, hard, maximum size 10", olive-brown, damp, impervious, very dense, glacial till. Bottom of Pit.

D.S. 236.1, 3.0-10.0 5% larger than 6" discarded.




NOTE: Water level at 7.0' on 7/14/65.







**TP-72, ELEV.** 6/24/66 E.G.L.  
 0.0 1.0 TOPSOIL  
 1.0 5.0 SAND, silty, cobbles and boulders, dark, ALLUVIAL VALLEY FILL.  
 5.0 Bedrock at bottom of test pit.

**TP-92, ELEV.**  
 0.0 1.0 TOPSOIL  
 1.0 5.0 SAND, silty, gravel, cobbles and boulders, gray, ALLUVIAL VALLEY FILL.  
 5.0 Bottom of pit. Bedrock. Water appearing at 5.0.

**TP-93, ELEV.**  
 0.0 1.0 TOPSOIL  
 1.0 5.0 SAND, silty, gravel, cobbles and boulders, gray, ALLUVIAL VALLEY FILL.  
 5.0 Bottom of pit. Bedrock. Water entering at 5.0.

**TP-94, ELEV.**  
 0.0 1.5 TOPSOIL  
 1.5 4.0 SAND, silty, dark, ALLUVIAL VALLEY FILL.  
 4.0 Bedrock at bottom of pit.





CLAM RIVER WATERSHED PROJECT CLAM LAKE MULTIPLE-PURPOSE DAM SANDSFIELD, MASSACHUSETTS			
LOGS OF TEST HOLES			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Investigator R. H. H. H. H. H.	Date 1959	Approved by	
Type Soil		Title	
Transit		Sheet No. 34	
Checked R. H. H. H. H.	2-20	NA 357-P	




Photo 1

Overview of downstream  
channel looking south  
from top of dam.



Photo 2

Overview of reservoir  
area, upstream embankment  
and principal spillway  
structure looking north-  
westerly from embankment.



Photo 3

Overview of emergency spillway  
crest, weir wall and dam crest  
looking west from top of left  
slope of emergency spillway.

Photo 4

Overview of emergency spillway  
approach channel looking  
northerly from toe of spillway  
discharge channel.



Photo 5

Overview of downstream embankment  
looking westerly from training wall  
of emergency spillway.



Photo 6

Overview of emergency spillway  
training wall slope looking  
southerly from dam crest.  
Note: Erosion of slope.






Photo 7

Overview of downstream embankment, spillway discharge channel and left slope of emergency spillway. Note: The sloughing of left spillway slope.



Photo 8

60-inch outlet conduit and end wall. Note the crack above pipe and missing foundation drain pipe outlet to the left of the 60-inch conduit.



Photo 9

Pond drain inlet structure. Note damaged trash racks.

Photo 10

Pond drain inlet structure wing wall. Note cracks in concrete.





Photo 11

Gate well of principal spillway structure. Note the lower two stem guides are damaged.



Photo 12

Crack on right wall of riser transition.






Photo 13

Cracks and efflorescence  
on transition of principal  
spillway riser.



Photo 14

Crack in transition near  
the vertical downstream  
face of the principal  
spillway riser.



Photo 15

Closeup of silt from beneath  
rip rap on downstream side  
of embankment.



Photo 16

Closeup of left slope toe of  
emergency spillway at crest.  
Note groundwater seepage from  
slope.




Photo 17

Left slope of emergency spillway.  
Note slope failure and erosion.





Photo 18

Left slope of emergency spillway.  
Note erosion.



Photo 19

Transition of grass covered  
channel to riprap slope of  
emergency spillway. Note  
erosion and undercutting of  
rip rap by runoff.

DATE  
FILMED  
-8